

Photo E19 [3/5/98-1:23]

Range 19: Qualification Pistol Range, Site 234(7) or [75Q] [CERFA Parcel Map 11,23]

Range 19 is located on Southwest Main Post and has been in use from 1976 through the present. The photograph faces the NE. The site is an open area against a backstop hill. The Range is surrounded by pine forest. There is a drainage ditch between Iron Mountain Road and Range 19. It does not appear to drain behind the Range (i.e., hillside). A site walk was not performed due to restricted access (range was in use).



Photo E20 [3/5/98-1:24]

Range 19: Qualification Pistol Range, Site 234(7) or [75Q] [CERFA Parcel Map 11,23]

Range 19 is located on Southwest Main Post and has been in use from 1976 through the present. The photograph faces the NE. The site is an open area against a backstop hill. The Range is surrounded by pine forest. This photograph faces north and shows the drainage ditch mentioned in E19. The ditch is surrounded by small trees. A site walk was not performed due to restricted access (range was in use).



Photo E21 [3/5/98-1:30]

Former Fog Oil Storage Area, Site 232(7) [CERFA Parcel Map 12,26]

This photograph faces south and shows an open clearing in the middle of a highly wooded area. Large stands of pine trees surround the site. The area in the middle contains tall grasses and there is a paved road through the middle of the area as noted in the middle of the photograph. No aquatic areas were noted during the site visit.




Photo E22 [3/5/98-1:37]

This photograph is of the wrong site; **DISREGARD PHOTO**




Photo E23 [3/5/98-1:39]

Printing Plant Bldg. 3138, Site 162(7) [CERFA Parcel Map 15,28]

This 0.77 acre site once stored and used solvents. The photo faces the NE and shows bldg. 3138 located adjacent to stand of pine trees. This site is an open developed parking lot with buildings. No aquatic habitat was observed.




Photo E24 [3/5/98-1:45]

Former Personnel Decontamination Station (PDS) at Bldg. 3185, Site 179(7) [CERFA Parcel Map 19,32] This site is an open developed parking lot with associated building. Directly behind the building is a densely forested area.




Photo F1 [3/5/98-1:55]

Site 146(7) Complex, Motor Pool at Area 3100 [CERFA Parcel Map 15,27]

The Motor Pool at Area 3100, is across from the Polygraph Institute. Site 146(7) Complex also encompasses sites 73(7), 25(7), 212(7), and 24(7). The site consists of vehicle maintenance area, wash rack, USTs, and a oil water separator. Site 73(7) bldg. 3144 is a wash rack; Site 25(7) bldg. 3138 Motor Pool is a UST (10,000 gal.); Site 24(7) bldg. 3138 Motor Pool is an oil UST (3,000 gal.); and Site 212(7) bldg. 3138 Motor Pool is one 5,000 gal. UST for heating oil. The photo faces W and shows an open lot (asphalt and gravel) with parked military vehicles. The site is surrounded by tall pine stands.



Photo F2 [3/5/98-2:10]

Site 146(7) Complex, Motor Pool at Area 3100 [CERFA Parcel Map 15,27]

The Motor Pool at Area 3100, is across from the Polygraph Institute. Site 146(7) Complex also encompasses sites 73(7), 25(7), 212(7), and 24(7). The site consists of vehicle maintenance area, wash rack, USTs, and a oil water separator. The photo faces South and shows a stream running from the NW corner of the fenced parking area. Small stands of pine are scattered around the area.



Photo F3 [3/5/98-2:15]

Site 146(7) Complex, Motor Pool at Area 3100 [CERFA Parcel Map 15,27]

The Motor Pool at Area 3100, is across from the Polygraph Institute. Site 146(7) Complex also encompasses sites 73(7), 25(7), 212(7), and 24(7). The site consists of vehicle maintenance area, wash rack, USTs, and a oil water separator. This photo is the same as F2, and shows a stream running from the NW corner of the fenced parking area. Small stands of pine are scattered around the area.




Photo F4 [3/5/98-2:20]

Site 146(7) Complex, Motor Pool at Area 3100 [CERFA Parcel Map 15,27]

The Motor Pool at Area 3100, is across from the Polygraph Institute. Site 146(7) Complex also encompasses sites 73(7), 25(7), 212(7), and 24(7). The site consists of vehicle maintenance area, wash rack, USTs, and a oil water separator. This photo is of the same stream as in F2 and F3 but from the North. The stream is draining the parking area to the far right of the photo. A wash rack is present at the far right of the photo with a military vehicle on top of it and soldiers are seen washing the vehicle. Drainage from the concrete wash area is draining into the creek. A tall stand of pines is seen to the North.



Photo F5 [3/5/98-2:30]

Site 153(7) (ESE) Groundscar [CERFA Parcel Map 17,28]

This groundscar is south of Bldg. 3134 and is contained within a heavily wooded area. The photo face North and show the densely wooded area. The actual groundscar was not located. No aquatic habitats were observed on this site.




Photo F6 [3/5/98-2:39]

Tanks on hillside at abandoned Range 16. This is not a photo of a site. DISREGARD.




Photo F7 [3/5/98-2:43]

Site 177(2) AST located at Range 16 next to Bldg. PR6357-16 [CERFA Parcel Map 18,25]

This site is located in a heavily wooded area. The photograph faces to the north and show the AST and bldg. PR6357-16. Tall stands of pine trees can be seen directly behind the building. Small pines and grassy areas surround the building and AST. Directly South of the site is Range 16 (see photo F6). No aquatic systems were observed in the general area.




Photo F8 [3/5/98-2:53]

Site 241(7) FMR Motor Pool Area 2100 [CERFA Parcel Map 17,30]

This photograph faces south and shows the site as an open grass field bounded by roads to the north and west, buildings to the south, and South Branch Cane Creek to the east. There is a ditch along the road to the north running parallel to the site, which drains into South Branch Cane Creek under Bridge 4314.




Photo F9 [3/5/98-2:59]

Wild Turkeys in wooded area by MP school and south of the confidence course. This photograph faces west and is directly across the street from Site 158(7). The area is densely forested with coniferous and deciduous trees. The turkeys are in the background.



Photo F10 [3/5/98-3:15]

Groundscar Site 158(7) [CERFA Parcel Map 23,28]

The groundscar is located in a wooded area at the south end of the confidence course. This photograph faces north and shows an old foundation in a wooded area. The entire area is covered with small pines (0-6 inches in diameter). No water or drainage ditches were present at the site. Wild Turkeys were spotted foraging in a wooded area directly across the road (west) from this site (see photo F9).



Photo F11 [3/5/98-3:19]

Washrack/Grease rack, Bldg. 7140, Soldier's Chapel, Site 127(7) [CERFA Parcel Map 22,28]

The site is located behind (north and east of bldg. 7140) the Soldier's Chapel. This site was used as a vehicle maintenance facility during the 1950s/1960s. Terra cotta tile drains reportedly discharged downhill (north) of the washracks/grease pits. The sumps of all six washracks are now filled with concrete. The land around the Soldier's Chapel is maintained lawn. There are currently several concrete pads on the north side of bldg. 7140. The land drops of approximately 20 ft. to a sparsely wooded area. The photograph faces north and shows a wash/grease rack in a heavily vegetated area (i.e., briars, vine, bushes, etc.). There are potential drainage ditches near the wash/grease rack.



Photo F12 [3/5/98-3:19]

Washrack/Grease rack, Bldg. 7140, Soldier's Chapel, Site 127(7) [CERFA Parcel Map 22,28]

This photo is exactly the same as Photo F11. The site is located behind (north and east of bldg. 7140) the Soldier's Chapel. This site was used as a vehicle maintenance facility during the 1950s/1960s. Terra cotta tile drains reportedly discharged downhill (north) of the washracks/grease pits. The sumps of all six washracks are now filled with concrete. The land around the Soldier's Chapel is maintained lawn. There are currently several concrete pads on the north side of bldg. 7140. The land drops of approximately 20 ft. to a sparsely wooded area. The photograph faces north and shows a wash/grease rack in a heavily vegetated area (i.e., briars, vine, bushes, etc.). There are potential drainage ditches near the wash/grease rack.




Photo F13 [3/5/98-3:32]

Boiler Plant No. 4, Bldg. 1876, Site 101(7) (ESE) [CERFA Parcel Map 21,29]

Two 50,000 gal. USTs for No. 4 heating oil, one 500-gal. Gasoline UST for a back-up generator are all associated with Boiler Plant No. 4. The photograph faces west and shows the main building of Boiler Plant No. 4. The site is a very open, developed area with sparse woods to the west of the building.



Photo F14 [3/5/98-3:40]

DRMO, Bldg. T-341-346, Site 85(4) Currently Recycling Metal Operations [CERFA Parcel Map 23,36] This site was a former RCRA Interim Status Storage Facility. The building currently stores old appliances, furniture, clothes, brass ammunition, old tires, scrap metal, surplus vehicles. The former RCRA site stored pesticides, solvents, batteries and POL. The photograph faces south and show the building complex and paved lot. There is a forested area directly behind the facility.




Photo F15 [3/5/98-3:44]

Consolidated Maintenance Facility, Bldg. 351, Wash Rack [Site 170(7)] , Former Fire Training Pit, located where Bldg. 350 is now [77(7)], and Bldg. 350 Site 7(7) [CERFA Parcel Map 22,35-36] This photograph faces north and shows building 351 (Consolidated Maintenance Facility). Site 77(7) and 7(7) are behind building 351. The site is a heavily developed industrial area. The site is drained by three storm water outfalls emptying under the road and into the woods behind (south west) the current Wildlife Management Office (Site 149(7)). This wooded area is the beginning of a tributary to Cave Creek.



Photo F16 [3/5/98-4:00]

[CERFA Parcel Map 21,36] This photograph faces south and shows a sewer pipe in the foreground emptying into a stream across the street from bldg. 349, Site 170(7) complex. This stream is the beginning of a tributary to Cave Creek. Three outlets draining parcels 170, 77, and 7 converge at this point. The area is heavily wooded with dense undergrowth. This area is behind (south west) the current Wildlife Management Office (Site 149(7)).



Photo F17 [3/5/98-4:05]

[CERFA Parcel Map 21,36] Confluence of streams in wooded area behind the current Wildlife Management Office (Site 149(7)). This photograph faces north and portrays the same tributary to Cave Creek mentioned in the previous photo description (F16) only further north downstream. The area is heavily wooded with dense undergrowth.



Photo F18 [3/5/98-4:10]

[CERFA Parcel Map 21,36] Same shot as F17, just in the southern direction (upstream).




Photo F19 [3/5/98-4:30]

Cain Creek at the golf course from foot bridge 4343 [CERFA Parcel Map 12,37]

This photograph faces northwest and shows Cain Creek as it runs through the golf course. The topography is typical of golf courses.



Photo F20 [3/5/98-4:30]

Cain Creek at golf course from foot bridge 4343 in the opposite direction (SE) [CERFA Parcel Map 12,37]. This photograph face to the southeast and shows the opposite view of F19 Cane Creek. The creek is highly channelized on this side of the foot bridge. The creek bank in concrete lined. A wooded area is to the left of the photo which contains stands of coniferous and deciduous trees. The right side of the photo shows the continuation of the golf course. A drainage ditch from the golf course area can be seen in the bottom right corner of the photo.



Photo F21 [3/6/98-10:23]

Former Post Garbage Dump (N. of Reilly Air Field), Site 126(7) [CERFA Parcel Map 24,50]

The site is just south of Lake Reilly swamp and wetland area. Noted open pits atop hill overlooking swamp/wetland. The photograph faces west and shows open pit area to the left and the right of photo. This area is area is sparsely wooded with thick undergrowth. Farther east of the open pit area there was a drainage ditch leading north to the wetland area (ditch was dry).



Photo F22 [3/6/98-11:39]

Pelham Range (Range K, Former Agent Training Area), Site 203(7) [CERFA Parcel Map 12,39]  
The site is located in the northwest corner of Pelham Range. The area is moderately forested (tall pines) with thick understory; dirt road access only. Area is delineated by small signs posted to trees. The photo faces southwest. This site was not explored due to caution signs posted on trees warning against going into the area.



Photo F23 [3/6/98-12:02]

Reported HD Spill/Burial Site, Site 210(7) West Pelham Range [CERFA Parcel Map 4,35]

Thickly wooded area with sparse/clear understory. Drainage ditches exist adjacent to either side of the dirt access road. The photo faces to the south and shows the access road into the area.




Photo F24 [3/6/98-12:16]

This photograph faces south and depicts Cane Creek, and the end of a dirt access road which delineates the west boundary of Pelham Range. It is a heavily wooded area with a mix of coniferous and deciduous trees with thick understory.