

APPENDIX G.3

Team Logbooks

This page intentionally left blank.

Date	Team	UXO Supervisor	Comment
2/25/2002	BRUSH 1	K. Wright	0600 F/W safety brief. 0630 Loaded equipment, Cassiopeia 16066, vehicle 10 , shonstedt 12, passed through test grid, radio map lead,. 0645 Standby for brush crews to finish initial site safety, training. 0900 QC preparatory inspection 0930 Departed for M101 area. 0945 Arrived M101. 1000 Teams briefed on brush operation. 1015 Started downloading equipment. 1025 Started brush operation. 1215 Lunch. 1245 Resumed brush operations. 1355 Safety and SUXO, on site, decide to move all three teams. 1400 Moved to south side of Summerall road. 1600 Stopped operation for today, departed for compound. 1610 Stored equipment. 1630 End of day.

Team Members:
N/A

Date	Team	UXO Supervisor	Comment
2/25/2002	BRUSH2	D. Leshko	0600 Morning safety brief. 0630 Loaded equipment. Cassiopeia 16033 Truck #15 Magna-trac #1 Tested on test grid. Radio # Demo 2A 0630 Standby for brush crews brief and training. 0900 QC Predatory Inspection. 0930 Truck #15 battery died, jump started. 0945 Depart for M101 area. 1005 Arrive at M101 area. 1010 Teams briefed on Ops to be done. 1015 Download heavy equipment and prep for ops. 1025 Start brush ops. 1215 Lunch. 1245 Resume brush ops. 1355 Safety and SUXO on site, decision to relocate teams' 1400 Continued brush ops in C area of M101. 1600 End ops and return to compound. 1630 End of day.

Team Members:

N/A

2/25/2002	SURVEY 2	S. Harsh	0600 Safety Brief, Skipper Engineering on site. 0630 Skipper Engineering attended site safety and base safety brief. 0900 In the field in M101 1300 Lunch 1330 Lunch over 1640 Finished for the day 1700 Departed site
-----------	----------	----------	--

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
2/25/2002	SAFETY	J. Karkoszka	0600 Safety briefing 0630 Equipment checked 0645 Standby for brush crews finishing initial site safety briefing and training . 0900 QC preparatory inspection 0930 Truck 15, battery dead. jumped started ok. 0945 Depart compound for m 101 area. 1005 Arrived in m-101 area. 1010 Team's briefed on operations to be done. 1015 Start download hvy equipment and prep for ops. 1025 Starting brush removal operations . 1215 Lunch 1245 Resuming brush clearing operations 1355 Site/safety and SUXO on site. made decision to relocate team's . 1405 Team moved to new area by alpha grids . 1600 Ceased operations for heavy equipment maintenance . 1710 Depart work site 1730 Secured for the day.

Team Members:

N/A

2/25/2002	SURVEY 1	R. Alberti	0600 Morning safety brief 0630 Foster Wheeler site specific safety brief 0900 Started work 1635 Stopped work 1640 Left site
-----------	----------	------------	---

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
2/26/2002	SAFETY	J. Karkoszka	0600 Morning's safety briefing 0630 Equipment checked depart for work site 0645 Tailgate safety brief, start brush removal operations . 0815 Bush hog broken ,attempting on site repairs. 0855 Bush hog repaired , resumed operations . 1030 Chainsaw crews getting fuel, ran out, going to gasoline station . 1100 cCrews back on site resuming operations . 1215 Lunch. 1245 Rresumed operations 1330 Adjusted areas being worked , using newly laid boundary lines . 1420 Brush three team refueling hvy equipment . ran hydro axe machine dry.[brush one] while attempt8ng refueling they ran out of fuel. going downtown for diesel l 1530 Relieved Ken Wright 1600 All operations stopped for the day. doing maintenance on heavy equipment . 1700 Depart for compound. 1730 Secured for day.

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
2/26/2002	BRUSH 1	K. Wright	0600 F/W safety brief. 0630 Loaded equipment, vehicle 10, radio map lead, magna track 14, passed through test grid, Cassiopeia, 16066. 0645 Departed for M101. 0700 Arriv3d M101, safety brief, brush cutter, distance to stay away from, 300 feet. 0710 Started cutting, south side of Summerall gate road. 1200 Lunch. 1230 Back cutting brush. 1420 Brush cutter ran out of gas, brush crew coming over to refuel. 1430 Brush crew had to get wrenches and fuel, gas for their tank, left site.1530 Departed for DO6A, with Steve Neill. 1420 Departed for brush cutting crew. 1700 Departed for compound. 1710 Stored equipment. 1730 End of day.

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
2/26/2002	BRUSH2	D. Leshko	0600 Morning Safety brief, MSDS. 0615 Check out equipment, Cassiopeia 16033 Truck #15 Magnatrac #1 ,checked out on test grid. Radio , Demo 2A 0625 Escorted Brush removal team to M101. 0635 Arrive M101 0645 Begin brush removal ops. Brush removal ops in Alpha area of M101. 0815 Stopped work for maintenance on bush hog. 0850 Resumed brush removal ops, bush hog repaired. 1045 Stopped bush hog ops, wheel came off of bush hog deck. 1115 Resumed bush hog ops, wheels repaired. 1215 Lunch. 1245 Resumed brush ops after lunch. 1600 Ended brush ops for the day. Returning to compound. 1630 End of day.

Team Members:

N/A

2/26/2002	SURVEY 1	R. Alberti	0600 Morning safety brief 0630 Fueled vehicle #5 0640 Arrived on site 0645 Tailgate safety brief 0650 Start work 1200 Lunch 1230 Start work 1600 Stop work 1615 Survey team off site 1630 Off site
-----------	----------	------------	---

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
2/26/2002	SURVEY 2	S. Harsh	0600 Safety brief, Skipper Engineering on site 0700 At work site , tailgate safety brief, slips trips and falls 1000 West from Skipper Engineering on site received safety brief from site safety 1030 West in the field with survey 2 1040 Down 15 minute to check the exclusion zone 1330 Lunch 1400 Back to work 1615 Survey finished for the day 1630 Off site

Team Members:

N/A

2/27/2002	DO15 SAFETY	J. Karkoszka	0600 Morning safety briefing 0630 equipment checked 0640 Arrived at work site. 0645 Tailgate safety briefing 0650 Hvy equipment prepared 0700 Started brush operation 0830 Warm up break . 0840 Resumed operation 0945 Ken Wright left site , to escort regulators in southern by-pass areas . 1100 Ken Wright back On work site. 1110 Survey team one. Bill Gallitz, slipped and fell on his back, hitting his head. feels ok, no injury or pain. doesn't want to see a doctor , appears to feel fine. team leader Steve Harsh will observe him to ensure he is ok. 1200 Lunch . 1230 Lunch finished ,started refueling operation .battery needed to be replaced, and regular lubrication requirements for the Hydro-axe machine . 1410 Refueling operation and maintenance requirements completed, resumed brush operation . 1600 Ceased operation for day. 1630 Secured for day.
-----------	-------------	--------------	--

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
2/27/2002	BRUSH2	D. Leshko	0600 Morning Safety brief. 0620 Checked out equipment Cassiopeia 16033 Magnatrac #1,checked out on test grid. Truck #15 Radio , Demo 2A 0630 Departed for M101area. 0640 Arrived M101. 0700 Started brush removal ops in the Alpha area of M101. 1200 Lunch. 1230 Refueling. 1410 Resumed brush ops. 1600 Ceased bush hog operations for the day. 1630 End of day.

Team Members:
N/A

2/27/2002	SURVEY 2	S. Harsh	0600 Safety brief, Skipper Engineering on site 0640 On work site started survey in M101 1110 William Gallitz from Skipper Engineering fell and landed on his back and the back of his head, I notified DO 10 safety Joe Karkoska. He made an entry in his log. 1300 Lunch 1330 Back to work 1625 Survey finished for the day, surveyors off site 1630 Off site
-----------	----------	----------	--

Team Members:
N/A

Date	Team	UXO Supervisor	Comment
2/27/2002	BRUSH 1	K. Wright	0600 F/W safety brief. 0630 Loaded equipment, vehicle 10, radio map lead, magna trac 14, passed through test grid, Cassiopeia 16066. 0640 Departed compound for M101 area. 0655 Arrived M101. 0715 Started brush cutting. 0930 Found 3 metal carrying case for the M 12 Antitank, Heavy, Practice mine along the fence line, south of Summerall gate road, notified Steve Neill, SUXO. 0945 Departed M101 area to meet Steve Neaill at D063A area. 1000 Standing by for Steve Neill. 1040 Steve Neill arrives with ACOE. briefed them on the area boundaries and how it was swept, 30 foot spacing. 1125 Departed area for M101 1135 Back with brush cutter. 1145 Found a practice land mine, approx. 1000 feet from the west UXO gate, near new paper building, item was marked with 2 red flags and orange tape. Approx. grid F86. 1200 Lunch. 1230 Lunch over, Refueling brush cutter. 1410 All fueled up and starting to cut brush. 1600 Stopped brush operations, departed M101 area. 1610 Stored equipment. 1630 End of day.

Team Members:

S. Houston

2/27/2002	SURVEY 1	R. Alberti	0600 Morning safety brief 0630 Arrive on site 0635 Tailgate safety brief 0640 Start work 1230 Lunch 1300 Start work 1610 Stop work 1620 Survey team left site 1630 Off site
-----------	----------	------------	---

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
2/28/2002	SURVEY 2	S. Harsh	0600 Safety brief Skipper Engineering on site 0630 Start survey 1100 took survey crew to Bravo work area to look for survey monuments 1130 Lunch 1200 Back to work 1600 notified of a fire in M101 team evacuated 1630 Off site

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
2/28/2002	DO15 SAFETY	J. Karkoszka	0600 Morning safety briefing 0630 Equipment checked 0645 Arrived at work site. all brush operation on hold by direction of site manager/site safety. until further notice . team's standing by. 0735 Notification from site manager to cease brush operation and prepare for demob of crews. 0800 Notification from site manager to disregard demo instructions and stand by for further updates. 0930 Received permission to resume operations. all crews briefed on procedures to be followed . 0935 Tailgate safety briefing . 0940 Brush crews resuming operation . 1200 Lunch 1230 Lunch finished. awaiting Brother's brush crew to return l 1320 Notified site manager that brush crews haven't returned yet. was informed to standby and await Brothers crews to return. 1335 Brother's crew back on site, starting refueling operation . 1400 Resumed brush clearing operation . 1535 Brush crew one called that they had a fire start while cutting notified site safety. team fighting fire , all non essential personnel evacuated . 1600 Fire extinguished , proceeded to spray areas with water to ensure that fire is extinguished . 1645 Depart area for compound. 1700 End of day.

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
2/28/2002	BRUSH2	D. Leshko	0600 Morning Safety Briefing. 0615 Checked out equipment, Cassiopeia #16033 Magnatrac #1, checked on test grid. Truck #15 Radio Demo 2A 0630 Departed for M101. 0640 Arrived M101. 0645 Site Manager/Site Safety on site, notified to standby until further notice. 0735 Notified by Site Manger that all brush operations are terminated, prepare brush crew for demo. 0800 Notified by Site Manger to disregard demob instructions and instructed to standby. 0930 Given the ok by Site Manager to proceed with brush operations. Instructed bush hog operator to make sure that his equipment not dig up the ground. 0940 Resume bush hog operations in Alpha area of M101. 1200 Lunch. 1230 Lunch finished, awaiting return of Brothers brush removal team from lunch. 1335 Brothers brush crew back on site. Started refueling ops. 1400 Refueling operations completed, resumed bush ops. 1535 Notified by safety of a fire and brush crew to hard road. 1550 Evacuated area. 1600 Returned to compound. 1630 End of day.

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
2/28/2002	BRUSH 1	K. Wright	0600 F/W safety brief. 0630 Loaded equipment, vehicle, 10, radio map lead, Cassiopeia 16066, magna trac 14, passed through test grid, Departed for M101. 0640 Standing by for brush crew to get started. 0645 Notified by site safety/ site manager, all brush cutting operations on hold until further notice. 0735 Notified by site manager, all brush operations are terminated, prepare brush teams for demobilization. 0800 Notified by site manager, disregard demob, stand by for further information. 0940 Cleared by site manager to go back to clearing. 1200 Lunch. 1230 Returned from lunch, awaiting for Brothers Construction crew to return. 1335 Brother Construction returned. starting refuel. on brush cutter. 1400 Started back cutting brush. 1535 Notified Joe Karkosaka, Safety of a fire, started by the brush cutter, hitting a rock. Fires put out, evacuated the area, Site safety notified. 1600 Departed M101. 1620 Returned to compound. 1630 End of day.

Team Members:

R. Cope

Date	Team	UXO Supervisor	Comment
2/28/2002	SURVEY 1	R. Alberti	0600 Morning safety brief 0630 Equipment loadout 0640 Arrive on site 0645 Tailgate safety brief 0650 Start work 1200 Lunch 1230 Start work 1540 Stop work 1545 Survey team off site 1546 Notified of safety hazard downrange 1605 Off site 1630 End of day

Team Members:
N/A

3/1/2002	SURVEY 1	R. Alberti	0600 Morning safety brief 0620 Equipment loadout 0640 Fuel vehicle 0655 Arrive on site 0700 Tailgate safety brief 0705 Start work 1130 Lunch 1200 Start work 1600 Survey team off site 1615 Equipment off loaded 1630 Off site
----------	----------	------------	--

Team Members:
N/A

Date	Team	UXO Supervisor	Comment
3/1/2002	BRUSH 1	L. Lister	0600 Morning safety meeting, vehicle checkout and load. 0645 Depart compound for M101 parcel and brush cutting operations. 0700 Arrive M101, tailgate safety brief. Fueling and maintenance being performed on cutting equipment. 0745 Crew returning to the compound to pick up third piece of equipment. 0845 Crew returned with third piece of equipment. Performing maintenance on same. 0900 Brush hog moving out to begin cutting. Both hydroaxes still idle. 1000 The larger of the two hydroaxes beginning to cut, the smaller hydroax is still having maintenance performed on it and has not begun cutting today. 1050 The smaller of the hydroaxes has finally started to cut. 1150 Stopped work for lunch. 1245 Crew returned from lunch, fueling and minor maintenance. 1300 Resumed cutting. 1545 Stopped work with small hydroax, driver needs to leave at 1600. Approximately 1 to 1 1/2 acres cut by small hydroax for today. Area walked by Lister and Cope, nothing found. 1610 Returning to compound. 1620 Arrived compound, offload gear, complete paperwork. 1630 Ops complete, all secure.

Team Members:

R. Cope

Notes:

Date	Team	UXO Supervisor	Comment
3/1/2002	BRUSH2	D. Leshko	0600 Safety Brief. 0615 Checked out equipment. Cassiopeia 16033 Magnatrac #1, checked on test grid. Truck #15 Radio Demo2A 0630 Depart compound for M101. 0640 Arrive M101 area. Brush crew working on preventive maintenance. 0715 Return to compound, to transport second hydro ax to the M101 area. 0815 Arrived at M101 with second hydro ax and then preventive maintenance. 0930 Started brush operation. 1200 Lunch 1230 Finished lunch. 1245 Brothers brush team return, maintenance on equipment. 1255 Resumed brush removal. 1325 Stopped ops due to intruders, contacted Safety. 1330 Safety on site, escorted intruders out of area. 1335 Resumed brush operation. 1730 Ended brush operations and return to compound. 1800 End of day.

Team Members:
N/A

Date	Team	UXO Supervisor	Comment
3/1/2002	DO15 SAFETY	J. Karkoszka	0515 Arrived on site, opening compounds , prepared morning's safety and health briefing. 0600 Morning safety briefing and tasks assignments. 0630 Team's departing for field work. tailgate safety briefing. 0730 David Becker from IT called ,wanted to know if exclusion zones were set up. told him we did have any set for today's operation . 0800 Mike Moore , TF Safety will meet at uxo gate at 0830. wants to look at areas the had small fires in them on Thursday. 0830 Mike Moore and Scott Bolten on site, escort to burn sites 0930 Moore and Bolten off site. 1030 Observing brush operation 1100 J. Clements sustained a minor cut on his left hand . he had a thorn pierce his gloves cutting his left thumb, wound is minor, cleaned and put bandage on it. no further action required. individual states no pain and will continue to work with no difficulty . no medical treatment required at this time. 1200 Lunch 1230 Lunch finished 1245 Brother's crews back ,minor maintenance . 1255 Resumed brush operations 1325 Stopped operation ,unauthorized vehicles in areas . security notified. 1330 Security escorted vehicles off work site. uxo gate was found to be open. 1335 Brush operation resumed . 1615 Brush teams 1 and 3 done , team 2 continuing operation . 1730 Brush crew 3 finished for the day. all personnel clear of M1.01 and by pass. 1800 Secured for the day.

Team Members:
N/A

Date	Team	UXO Supervisor	Comment
3/1/2002	BRUSH 3	J. Clements	0600 Safety brief 0630 Equip Prep 0700 Brush team equip PMCS 0830 Start brush clearance. A small tree was jammed in the wheel of the bush hog. I called D. Leshko and asked for a saw to cut it out. As I was walking through some brush, a thorn pierced through the thumb of my left glove and I sustained a minor cut. 1130 Back to brush clearing 1200 lunch break 1230 Back to brush clearing 1245 Brush cutters return from lunch. Performing maintenance on equipment. 1255 Back to brush clearing 1550 Return to rally point 1615 Return to compound
		Team Members:	
		N/A	
3/2/2002	BRUSH2	D. Leshko	0600 Safety Brief. 0615 Checked out equipment. Cassiopeia 16033 Truck #15 Radio Demo2A 0630 Depart compound for M101. 0640 Arrived at M101 area. Brothers brush removal crew started preventive maintenance, service equipment and escorted additional heavy equipment into the area. 0845 Returned to compound. 0900 End of day.
		Team Members:	
		N/A	

Date	Team	UXO Supervisor	Comment
3/2/2002	DO15 SAFETY	J. Karkoszka	0515 On site 0600 Morning safety briefing 0615 Brother's crews will do maintenance on all there equipment in the field . they are also bringing additional hvy equipment to be located in the field . 0635 TF Base notified that we will be in the M1.01 area 0900 Brother's crews completed all maintenance and servicing of equipment . departing rk site. 0930 TF Base notified that all personnel clear of M1.01. Mercury /Vulcan training canceled due to weather . 1000 Secured for the day.

Team Members:

N/A

3/2/2002	BRUSH 3	K. Tibbits	0600 Daily ops and Safety brief 0620 Load out truck 0640 Depart for M1.01 area 0655 Arrive at M1.01 Equip staging area. Brush crews performing maintenance and fueling of equipment 0900 Secured from equip maintenance 0905 Departed for F.W. compound 0915 Arrived at FW 0930 Secured for the day.
----------	---------	------------	--

Team Members:

N/A

3/2/2002	BRUSH 1	M. Doak	0600 Safety brief/ Equipment check out. 0630 Depart for M-1.01 area in support of brush clearance operations. 0700 Brush crew performing equipment maintenance. 0905 All personnel departing M1.01 area. Gates locked with Task Force lock. 0917 Back at FWENC compound. 0930 End of the day.
----------	---------	---------	---

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/4/2002	BRUSH2	D. Leshko	0600 Morning Safety Brief. 0615 Checked out equipment. Magnatrac #1 checked on test grid. Cassiopeia #16033 4 Kenwood radios 2 Talkabouts Radio Demo 2A Truck #15 0645 Departed compound. 0700 Arrived M101. Brothers brush crew preparing equipment for brush operation. 0900 Begin brush ops. 1220 Lunch 1250 Lunch over, resume brush ops. 1315 Hydro ax broke down, blade and shaft came off 1330 Joined manual brush teams. 1600 Ended brush operation. 1610 Escorted Brothers to remove hydro ax to hard road. 1700 Hydro ax back to road, end ops. 1705 Return to compound. 1730 End of day.

Team Members:

N/A

3/4/2002	BRUSH 3	S. Harsh	0600 On site, daily safety brief 0700 In the field, brothers started maintenance on equipment 0945 Safety brought 2 brothers personnel to the field 1030 started cutting in M101 1200 lunch 1230 started cutting in M101 again 1545 Left grid for maintenance area 1615 Returned to base with brush team 1630 End of day
----------	---------	----------	--

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/4/2002	BRUSH 1	L. Lister	0600 Morning safety meeting, truck checkout and load. 0700 Depart compound for DO15 area. 0715 Arrive DO15, tailgate safety brief. Maintenance being performed on hydroax. 0725 I walked an area for the hydroax to cut and marked its boundary with white flagging tape. Identified a large area with orange flagging tape that contained empty M12 mine boxes. 0845 Maintenance still being performed on equipment. 0945 Returning to the compound to re-do time sheet. 1010 Returned to DO15, first hydroax ready to begin. Harsh will observe smaller machine. 1030 Small hydroax beginning to cut, Harsh observing. 1045 Large hydroax ready to begin, walked driver through area to be cut and showed him marked areas. 1100 Start cutting. 1220 Stopped cutting, returning to truck for lunch. 1230 Walked area that was cut and next area to be cut, marked one area containing buried culvert. 1310 Resume cutting. 1430 Called by driver when he noticed some blue tape on the ground. Had him stop hydroax while I investigated. Found bundle of barbed wire on the ground and added some orange flagging for better visibility. 1445 Resume cutting. 1530 Shut down cutter to cool it off and get some water. 1600 Decision made to call it quits for today. 1620 Depart DO15. 1630 Arrive compound, offload gear, complete paperwork. 1640 Ops complete, all secure

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/4/2002	DO15 SAFETY	J. Karkoszka	0600 Morning safety brief. 0630 Equipment checked 0700 Arrived on work site, crews doing checkout on hvy equipment . tailgate safety briefing given to all brother's employees. 0815 Manual brush crew starting operation .both weedeater are inoperative do not have correct parts on hand to repair . 1220 Lunch 1250 Resumed manual brush clearing 1400 Chipper machine down attempting onsite repair . continuing manual brush clearing operation . 1530 Chipper repaired continued brush clearing operation . 1600 Stopped operation for day. starting maintenance and removed broken hydro axe machine from grid area. 1700 Back in compound.

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/5/2002	BRUSH2	D. Leshko	0600 Morning Safety Brief. 0615 Checked out equipment, Magnatrac #1, tested on test grid. 2 Kenwood radios Cassiopeia #16033 Radio Demo 2A Truck #15 0640 Departed for M1.01 area. 0650 Arrived M1.01 area and let Brothers brush team in area. 0705 Started manual brush removal. 0715 Switched brush team with Ken, went with hydro ax for preventive maintenance and servicing. 0830 Started brush operation. 1025 Brother's hydro ax operator, called a break. 1045 Returned to work. 1155 Stopped operation for lunch. 1230 Lunch over, notified by Brother's t at they would work till 1700, I let them know that the ok was given to work later, but they said would probably work later tomorrow. Notified Ken of situation. 1235 Resumed brush operation. 1240 Checked again with Brothers, that they knew they could work till 1800. Said they needed to see how long servicing their equipment would take, so they would have a better idea for tomorrow. Let Ken know that I rechecked with them. 1330 Located a practice land mine, marked it and notified Ken. 1630 Hydro ax operator stopped operation, said he was calling it quits for the day. 1635 Escorted to UXO gate for servicing. 1705 Departed for compound. 1730 End of day.

Team Members:

N/A

*Final Site Specific Final Report
M1.01 Parcel and M3 Miscellaneous Property
Fort McClellan, Alabama*

Date	Team	UXO Supervisor	Comment
3/5/2002	BRUSH 3	S. Harsh	0600 On site, safety brief 0700 Brush crew on site, started maintenance on brush equipment 0820 Went to escort brush chipping operation 0920 Left chipping operation and went to escort hydro axe 1000 Maintenance complete started cutting in M101 1200 Lunch 1220 I backed in to a telephone pole and cracked the drivers side tail light cover 1230 Back to cutting 1700 Stopped cutting and started maintenance 1730 Out of the field

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/5/2002	SAFETY	J. Karkoszka	<p>0600 F/W safety brief</p> <p>0630 Loaded equipment, vehicle 10, radio spare 3, Cassiopeia, DO15 safety.</p> <p>0640 Started housing sweep.</p> <p>0700 Housing sweep completed.</p> <p>0705 Tailgate safety brief, hazard areas for brush cutting equipment . PPE safety glasses, gloves, hard hat.</p> <p>0715, Started brush cutting, mechanic arrived to work on large brush cutters, outside UXO gate.</p> <p>0915 Steve Harsh, watching chipper crew.</p> <p>0920 Steve Harsh departs for escort of the other brush cutter, finished with maintenance.</p> <p>1135 Notified by Steve Neaill, FW SUXO, that the brush crew can work until 1800 nightly, I passed that information on to Brothers Construction.</p> <p>1230 Notified by Dave Leeks, that Johnny Brothers had told him they were only working until 1700 - 1715 today. He was told that he could work until 1800, he wanted to shut down at 1700, see how long it takes to do maintenance before it gets dark. All this information passed on to Steve Neill, FW SUXO. Also at 0600 tomorrow, we will be at the Summerall gate to let them in, safety brief at the gate daily.</p> <p>1335 Dave Leeks notified me that he had found a practice mine, blue in color, and a blue can with the words ACTIVATOR on it. I told him to mark the mine with a red pin flag and orange tape, the can is marked with orange tape. Items in M101 parcel near M3 fencing, approx. grid F90.</p> <p>1625 Crew with the chipper left for the day.</p> <p>1700 All crews out of the area, returning to compound</p> <p>1730 All equipment stored, end of day.</p>

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/6/2002	DO15 SAFETY	J. Karkoszka	0600 Morning safety briefing 0615 Tailgate safety briefing 0630 Equipment checked 0640 Starting manual brush operation . 0830 Angel Athey on site, assigned to brush 2 team. 1130 Lunch 1200Lunch finished ,awaiting fuel and return of chipper machine . 1215 Fuel on site resumed cutting operation . 1240 Chipper back on site, resumed chipper operation 1245 Angel Athey on site with chipper operation . 1530 The chipper crew is taking a water and rest break. One of the Brother's employees is doing nothing but sitting on the tractor and moving it when needed. There is enough time for him to get down and help the others. With a little motivation from some of them, like the guy on the tractor, this would go a bit faster. As it is, the others are having to work harder to make up for it. 1545 Chipping starts up again. 1600 At this point, the two Mexican employees are doing a VAST majority of the work. Safety is being observed by all. Everyone is wearing their proper ppe. 1620 If I could make a suggestion, it would be safer if some of the chippers and dragger's were switched out sometimes as both of these jobs are tiring in different ways and it would keep energy levels and safety up. Safety is our main concern. 1700 Manual brush work has ended. We are preparing to return to the shop. 1725 Departing work zones for compound

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/6/2002	BRUSH 2	D. Leshko	0530 Load equipment . Magnatrac #1 ,tested on test grid. Cassiopeia #16033 Radio Demo 2A Kenwood radios Truck #15 0540 Departed for M1.01 area. 0550 Arrived M1.01 area, awaiting morning safety brief. 0610 Morning Safety Brief. 0630 Started brush removal operation. 0825 Angel Athey joined team. Reviewed procedures for brush operations, equipment safety, procedures for marking OE and other items. 0840 Equipment operator stopped operation to make a phone call. 0855 Resumed brush operation . 1145 Stopped for lunch. 1215 Lunch Over, waiting for Brother's to resume operation 1235 Refueling hydro ax. Ang4el left team to join Joe's team. 1255 Resumed Operations. 1650 Operation Hydro ax broke fan belt. 1700 Equipment operator went to get replacement belts. 1710 Returned with belts, started repair . 1800 Repair completed, let brush crew out. 1805 Departed for compound 1830 End of day.
			<p>Team Members: A. Athey</p>
3/6/2002	BRUSH 3	S. Harsh	0600 Went to Summerall Gate rd for morning safety brief 0630 Morning Safety brief was given to brush crew and there escorts by Nat Martin 0645 Started brush removal in M101 1200 Lunch 1230 Back to brush removal 1730 Cutting done for the day 1800 Off site
			<p>Team Members: N/A</p>

Date	Team	UXO Supervisor	Comment
3/6/2002	BRUSH 1	K. Wright	0530 Loaded equipment, vehicle 10, radio map lead, Cassiopeia 16066. 0545 Departed for M101 area. 0555 Arrived at Summerall gate road, awaiting safety brief. 0615 Safety brief completed. 0620 Started work. 1130 Lunch. 1200 Back cutting brush. 1700 Stopped brush cutting operations for the day. Comment: Antonio's brush crew completed cutting brush in an area of approximately 1000 feet long by 450 feet wide, without injury or a safety violation. The quality of work is excellent 1720 Departed for compound. 1730 Stored equipment. 1800 End of day.

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/7/2002	DO15 SAFETY	J. Karkoszka	0530 On site, checked equipment . 0600 Arrived in M1.01 area hvy equipment checked . 0620 Morning safety brief. 0625 Tailgate safety brief. 0710 Teams assigned starting operation for chipper and manual brush clearing 0830 Brush team one will assist putting up security fence line. after road brush is removed . 1025 Laborers from brush team one joined up forming one large clearing team. second tractor with chipper undergoing maintenance . 1045 Second chipper fixed and running . 1120 Ty Wrage on site taking over as escort for manual brush clearing team. 1200 Lunch 1230 Lunch over , resumed manual brush clearing 1530 J. Karkoszka back on sites with brush crews 1700 All operation stopped for maintenance . chipper 2,has blown tire, will repair in field if possible . 1735 Tire repaired 1755 Clear of M1.01 1810 Secured

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/7/2002	BRUSH 1	K. Wright	0530 Loaded equipment, vehicle 10, Cassiopeia 16066, radio map lead. 0545 Departed for M101 area. 0555 Arrived M101 area. 0620 Safety brief. 0630 Waiting on brush crew, maintenance of equipment. 0700 Army fire truck on site to fill up barricades on north side of Summerall UXO gate. 0750 Crew ready to start cutting, cutting fence line between M102 and M 101. 1010 Fence line cutting completed, moving brush crew to housing area. 1040 Escorting Bo Reeves, putting in boundary fence between M2 and M101. 1245 Bo Reeves left to get more fencing, going over to brush cutters. 1345 One of the brush cutters is down, mechanic called. 1410 Back with Bo Reeves, finishing up the fence. 1510 Fence line between M101 and M2 is completed, going back to brush crew. 1700 Stopped brush cutting operations, crew doing maintenance. 1725 Departed for the compound. 1735 Stored equipment. 1800 End of day.

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/7/2002	BRUSH 3	J. Karkoszka	<p>0530 Arrived at FW main shop to begin the day and check out equipment.</p> <p>0600 Arrived at Summerall gate road for safety briefing.</p> <p>0620 Nate Martin arrived on site for the safety briefing.</p> <p>0630 I am going to be with the chipping crew I was with yesterday. Ken's team is going to start in M3 and then move over to M1.01 and help my team. We are going back over to M1.01 and pick up where we left off yesterday.</p> <p>0650 Myself and two of the chipping guys are in place and ready to start but the supervisor and chipper are not here yet.</p> <p>0655 The cutting crew arrives.</p> <p>0710 The supervisor and chipper are here now, they start chipping.</p> <p>0750 I gave Ken the two walkabout radios that I had signed for on my sign-out sheet this morning.</p> <p>0855 Crew takes a break.</p> <p>0910 Crew goes back to work.</p> <p>0945 Cecil drove by, talked to Joe, and left at 0955.</p> <p>1015 Crew takes a break.</p> <p>1025 Ken brings the other chipping crew to our location, and the other chipper and tractor show up.</p> <p>1045 Both chippers are working and they are going back to work now.</p> <p>1115 Ty came out to relieve Joe.</p> <p>1200 Break for lunch.</p> <p>1230 Lunch break over, back to work.</p> <p>1315 Chipper A (first chipper) had to go over By Summerall gate to get fuel. Chipper B is still running.</p> <p>1330 Everyone takes a brake.</p> <p>1345 Back to work.</p> <p>1400 Chipper A is back.</p> <p>1405 Chipper B is going to fuel up. Chipper A is running.</p> <p>1450 Chipper B is back.</p> <p>1500 Break.</p> <p>1515 Break over.</p> <p>1600 Joe arrived back onsite.</p> <p>1700 Done on the site for the day, going back to the main shop to turn in equipment, sign time sheet, and fuel up the vehicle.</p>

Team Members:
A. Athey

Bravo

Date	Team	UXO Supervisor	Comment
3/7/2002	BRUSH2	D. Leshko	<p>0530 Load equipment, Magnatrac #1, checked on test grid. Cassiopeia #16033 2 Kenwood radios Radio Demo 2A Truck #15</p> <p>0540 Departed compound for M1.01 area.</p> <p>0550 Arrived M1.01 area, awaiting morning safety brief.</p> <p>0620 Morning Safety Brief.</p> <p>NOTE: Notified Site safety that while loading water jug onto truck, I [Dave Leshko] pulled my left lower back. Safety said to make note of this.</p> <p>0630 Waiting for Hydro ax operator to service his equipment.</p> <p>0700 Jake Clements joined team, briefed on Safety issues with brush ops.</p> <p>0845 Started brush operations.</p> <p>[1045 Jake's team completed area and moved to Bravo to start brush ops.]</p> <p>[1100 Jake's team started brush operations in the Bravo section.]</p> <p>1120 Stopped for lunch.</p> <p>1150 Lunch over.</p> <p>1155 Resumed brush operations.</p> <p>1700 End brush operations, moved equipment to gate.</p> <p>1710 Notified that chipper has flat, escorting back to remove tire.</p> <p>1735 Escorted brush crew out of area, departed for compound.</p> <p>1800 End of day.</p>

Team Members:

J. Clements

Date	Team	UXO Supervisor	Comment
3/8/2002	BRUSH 1	K. Wright	0530 Loaded equipment, vehicle 10 radio map lead, magna track 1, passed through test grid. 0540 Departed for M101. 0555 Arrived M 101. 0625 Safety brief completed, PP, safety glasses, gloves, hard hat. fixing tire on chipper, waiting on hydro axes. 0650 Brush crew started dropping trees in M3 parcel, awaiting chippers. Started on east side going west. 0700 Chipper on site. 0720 Brush cutters ready, started cutting middle section. 1200 Lunch. 1230 Back cutting, 3 brush cutters in operation. 1310 Brush cutter broke a blade, taking it outside of the uxo gate. 1410 One chipper down, possible overheating. visited by Cecil Taylor. 1420 Cecil Taylor left the area, chipper back in operation. 1425 Have 3 operational brush cutters. 1530 2 brush cutters down loose blades, radiator problem. also doing maintenance on both. Visited by Steve Neaill and Greg Williams. 1555 Steve and Greg departed the areas. 1600 Todd Biggs left the site. 1700 All brush cutting crews and equipment are outside Summerall UXO gate. 1710 Departed M101. 1720 Stored equipment. 1740 End of day.

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/9/2002	DO15 SAFETY	J. Karkoszka	<p>0515 On site 0530 Equipment checked 0600 Morning safety brief. 0615 Tailgate safety brief. 0700 Starting chipper and manual brush clearing . Eric Kramer will escort chipper crew. Karkoszka escort for chainsaw crews . 1020 Brush team 2 called unauthorized person in area video taping operation . individual stated he was from Micro Systems, and had approval from Foster Wheeler to tape operation . Individual was escorted from area, wanted information as to what type and amount of equipment and personnel were being used for present operation . no information was given. informed individual to keep outside of area. SUXS0 and SAFETY notified. Security also notified . 1030 Area secured ,operation resumed. 1215 Brothers released manual brush crews for the day , 1220 Karkoszka starting lunch 1240 Released Eric Kramer for the day. he is returning to office to put equipment away and sign out. Karkoszka finished lunch. awaiting brother's hvy equipment to start back on operation l 1245 Escort brother's maintenance personnel to repair broken tractor in woods. 1330 Tractor out of woods, parked by ux0 gate. tractor drivers off site. 1335 Marking and sweeping small parcel for brush crews to cut and chip on Monday. have some blue stakes that need to be verified as well. 1440 Assisting hydro-axe team's . 1600 Shutting down all hvy equipment for the day, 1615 Hvy equipment in safe area, collecting radios. 1630 Preventive maintenance on hvy equipment 1640 Maintenance complete 1700 Secured for day. * late entry- John Zimmer found tick in groin area of body, upon removal of tick, the ticks head broke of inside of skin. Area was thoroughly washed with soap and water.</p>

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/9/2002	BRUSH 1	J. Zimmer	0530 Loaded equipment, vehicle 10, radio map lead, Cassiopeia 16066. 2 - 2way radio 0545 Departed for M101 area. 0555 Arrived at Summerall gate road, awaiting safety brief. 0620 Safety brief completed. 0710 Started work with hydro ax vehicle. 1030 Work stopped due to equipment breakage, popped an air hose and wedged two large tree limbs under Hydro Ax. 1100 Hydro Ax vehicle repaired and work started again. Light rain in area. 1200 Lunch break. 1230 Lunch over. Waiting for Brothers personnel to return to job site to work. 1330 Brothers crew back to work. 1600 All heavy machinery stopped for the day. 1615 Assembled in safe area. 1630 Depart to FW compound 1645 Arrived at compound. 1700 End of duty day.

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/9/2002	BRUSH 3	D. Blackwell	0530 Loaded equipment and picked up necessary paperwork. 0600 Departed for DO-15 0630 Arrived at Summerall gate in DO-15. 0645 Safety Brief by site safety. 0700 Waiting on brush team Hydro Ax driver Mike (BROTHER'S) 0730 Started working with Joe Karkoszka and the (brother's) chipper's, while waiting for Hydro Ax to be fixed. 0800 Hydro Ax fixed and is starting cutting around the D41 area. 0820 I stopped the hydro ax, due to a couple of Headstones in the area of grids E40 and E41. 0825 Called site safety (Nate) and notified him of the headstones. 0826 Nate told me to stop operations till he gets to my location. 0845 Nate arrived at my location and I showed him the location of the headstones. I told Nate that I have checked the rest of the area that the hydro ax is working and I haven't found any other headstones. 0850 Nate tells me to mark of the area around the headstone and go back to work. 0915 Hydro Ax goes back to work. 1230 Lunch 1300 Back to work 1630 Hydro Ax stopped working for the day. 1615 Escorted hydro ax back to morning meeting area. 1630 Depart DO-15 area for Foster Wheeler compound. 1650 Arrived at Foster Wheeler compound. 1700 Download equipment and turned in all necessary paperwork. 1705 END OF DAY

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/9/2002	BRUSH2	D. Leshko	0530 Loaded equipment, Cassiopeia #16033 Magnatrac #1 checked on test grid. 4 Kenwood radios Radio Demo 2A Truck #15 0540 Departed for M1.01 area. 0550 Arrived M1.01 area, waiting for Brothers brush crew and morning safety brief. 0620 Morning Safety Brief. 0630 Waiting for Brothers brush crew to service their equipment. Briefed John Zimmer and Dave Blackwell on operation. 0840 Started brush operations. 1010 Observed intruder on foot in area. Stopped operations and notified DO 10 Safety, Joe. Escorted intruder to road and safety escorted out of area. 1020 Resumed operations. 1215 Lunch. 1245 Lunch over, waiting for Brother's brush crew to return. 1300 Resumed brush operation. 1600 Ended brush operations. 1610 Transported heavy equipment to UXO gate. 1630 Departed for compound. 1700 End of day.

Team Members:
N/A

Date	Team	UXO Supervisor	Comment
3/11/2002	Brush III	J. Karkoszka	0530 Start the day. Check out new equipment. 0600 Safety briefing at main shop. 0630 Equipment loadout 0700 Fueled vehicle 0720 Arrived on site 0750 Tailgate safety brief 0820 Start work 1230 Lunch 1300 Lunch over waiting on brush crew 1330 Start work 1445 Equipment failure (broken rear axle) 1500 Brush crew attempting to make repairs 1700 Return to gate 1725 Left site 1730 End of day

Team Members:

N/A

3/11/2002	BRUSH 1	K. Wright	0600 F/W safety brief. 0630 Loaded equipment, vehicle 8, radio brush 1, Kenwood's HO1012, 1010. 0700 Departed to refuel vehicle. 0720 Arrived M101, waiting on brush cutter, maintenance. 0852 Ready to start cutting brush. 1230 Lunch. 1300 Lunch over, back cutting brush. 1345 Brush cutter broke a blade, out of service, no replacement blades. 1445 Second brush cutter down, broken hub on rear axle. out of service. trying to fix in the field. 1500 Checking completed grids. 1700 All brush crews at the uxo gate. 1725 Departed for compound. 1735 Stored equipment. 1800 End of day.
-----------	---------	-----------	---

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/11/2002	DO15 SAFETY	J. Karkoszka	0530 On sites 0600 Morning sites safety briefing 0615 Team tasking 0625 Equipment checked ,fueled vehicles 0640 Tailgate safety briefing 0650 Awaiting manual brush teams to finish equipment check out and warm up 0717 Starting chipper operation and manual clearing operation .second chipper not ready for use, operator is doing maintenance on hydro axe 0900 Hydro axe number three still doing maintenance , second chipper still unavailable for use. manual brush teams continuing operation . 1030 PM requested to mark areas on map of areas complete for turn in. 1035 Took 3 man brush crew to touch up areas in alpha section . 1200 Lunch 1230 Lunch complete ,resumed clearing operation 1630 Alpha areas cleared and are ready for turnover up to the fourth house, grid a-50 approximately for location . 1730 All operation stopped for day 1800 Secured

Team Members:

A. Athey

Date	Team	UXO Supervisor	Comment
3/11/2002	BRUSH2	D. Leshko	0530 Loaded equipment. Cassiopeia #16033 Magnatrac #1, checked on test grid. 2 Kenwood radios Radio EECA Brush 2 Truck #15 0540 Departed compound for M1.01 area. 0550 Arrived M1.01 area, Brothers brush crew on site. Awaiting morning safety briefing. 0625 Morning Safety brief, waiting for Brothers brush crew to finish servicing heavy equipment. 0645 Tailgate Safety briefing. NOTE: Hydro ax blade loose, waiting for repairs. 1100 Lunch. 1130 Lunch over. 1715 Brush operation for the day, escorted hydro ax back to UXO gate. 1735 Return to compound. 1800 End of day.

Team Members:

N/A

3/12/2002	BRUSH2	D. Leshko	0530 Loaded equipment. Cassiopeia #16033 Magnatrac #1, checked on test grid. 2 Kenwood radios Radio EECA Brush 2 Truck #15 0610 Chris from Brothers showed, said they will get back with me in a few minutes, as to whether they were working or not. 0540 Departed compound for M1.01 area. 0550 Arrived M1.01 area, waiting for Brothers brush crew and morning safety briefing. 0620 Johnny called, said they were calling today a rain day, notified Joe and office. 0625 Departed for compound. 0640 Back at compound, unloaded equipment. 0700 End of day.
-----------	--------	-----------	--

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/13/2002	DO15 SAFETY	J. Karkoszka	0530 On site 0600 Morning safety briefing 0625 Tailgate safety briefing 0630 Awaiting maintenance and refueling operation to be completed 0700 Chipper and manual brush cutting operations starting . one hydro axe is down for maintenance , the other two are operational and working . 1200 Lunch 1230 Lunch finished , awaiting refueling operation and maintenance on one chipper . minor fluid leaking from line. no spilling . manual brush team's resuming op. chipper one resumed operations, second chipper still being repaired . 1245 Second chipper repaired ,resumed operation . 1415 One chipper broken ,attempting on site repair . 1445 Chipper repaired ,resumed operation . 1545 All operations going smoothly, good progress has been made. several piles of brush on steep hill will be done later due to slippery conditions there. 1700 All operations stopped for the day, doing loadout and maintenance . 1725 All gates secured and all personnel outside of m1.01 areas . return to main compounds . 1800 Secured for day.

Team Members:

A. Athey

Date	Team	UXO Supervisor	Comment
3/13/2002	BRUSH2	D. Leshko	0530 Loaded equipment. Cassiopeia #16033 Magnatrac #1 2 Kenwood radios Radio Brush 2 Truck #15 0540 Departed compound for M1.01 area. 0550 Arrived M1.01 area, waiting for Brothers brush crew and morning safety briefing. 0620 Morning safety briefing. 0630 Brothers servicing heavy equipment. 0715 Started brush operation. 1230 Lunch. 1300 Lunch over, resumed brush operation. 1710 Ended brush operation for the day, transported heavy equipment back to gate. 1720 Departed for compound. 1800 End of day.

Team Members:

N/A

3/14/2002	Brush 3	R. Alberti	0600 Morning safety brief 0630 Equipment loadout 0650 Arrive on site 0650 Equipment maintenance (Hydro axe) 0900 Tailgate safety brief 0905 Start work 1230 Lunch 1300 Start work 1720 End work 1730 Return to main compound 1740 Offload 1800 End of day
-----------	---------	------------	--

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/14/2002	BRUSH 1	T. Wrage	0600 F/W safety brief. 0630 Loaded equipment , vehicle 12, Motorola talkabouts 2wayC and 2wayF 0640 arrived at M101. 0650 Waiting for Joe to arrive and assign my daily task. 0715 Joe arrives and assigns me to escort the Mechanics who are fixing the broken axle of the hydroax 0730 Mechanics take me out to where they are working and begin removing broken part. 0910 Mechanics need a sheet of plywood to roll their lift on, leave to go to Marvin's. I wait for them at the gate. 0930 Return to work 1200 Lunch. 1230 Back to area 1410 Need lock-tight stopped to run get some. 1430 Return to work 1715 Tire replaced 1730 Back to compound 1800 End of day.

Team Members:

N/A

3/14/2002	DO15 SAFETY	J. Karkoszka	0530 Arrived on site 0600 Morning safety briefing 0615 Equipment checked 0630 Tailgate safety briefing 0645 Team assigned to priority in northern area of alpha grids 0700 Starting chipper operation and manual brush clearing operation 1200 Lunch 1230 Lunch finished , resumed all operations 1235 Two hydro-axes still down for parts. 1445 David leeks departing area. brush op still in full swing. 1700 Team's working still brush cutting operation . 1730 All operation done for the day. 1745 Areas secured all personnel clear. 1830 Secured
-----------	-------------	--------------	---

Team Members:

N. Metzler

Date	Team	UXO Supervisor	Comment
3/14/2002	BRUSH2	D. Leshko	0530 Loaded equipment, Cassiopeia #16033 Magnatrac #1 [checked on test grid.] 2 Kenwood radios Radio Brush 2 Truck #15 0545 Departed for M1.01 area. 0555 Arrived M1.01 area, awaiting Brothers brush crew and morning safety briefing. 0625 Morning safety briefing. Brothers servicing heavy equipment. 0915 Started brush operation. 1030 Hydro ax broke down, blades came off! 1035 Attempting repairs. 1215 Lunch. 1245 Lunch over. Assisting manual brush operations. 1430 Departed for compound. 1500 End of day.

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/15/2002	DO15 SAFETY	J. Karkoszka	0530 Arrived on sites 0600 Morning safety briefing 0615 Equipment checked , 0630 Tailgate safety briefing given to all personnel on TO-15 0635 Starting manual brush operation and chipper operation . 0800 Replaced porta-potty 0915 All operations running smoothly , two hydro axes up and running . the third should be repaired shortly. 1030 ALDOT personnel in areas going to by-pass areas 1045 Escort Herb Surveying team to grave site found along perimeter fence . 1115 Second hydro - axe broken . operators going to Atlanta to pick up replacement parts. machine will be out for the rest of the day. only one hydro - axe in operation at this time. 1200 Lunch,one chipper needs to be refueled 1215 ALDOT and Herb Surveying team departed working sites . 1230 Lunch complete ,resumed chipper operation and manual brush clearing . 1330 One hydro axe almost ready to be placed in service .currently one is operational out of three. 1720 Ceased operation . 1745 All personnel clear of m1.01 1800 Main gate locked ,security coming to open gate 1830 All secured

Team Members:
N. Metzler

Date	Team	UXO Supervisor	Comment
3/15/2002	BRUSH 3	R. Alberti	0600 Morning safety brief 0630 Equipment loadout 0650 On site 0655 Equipment maintenance (Hydro axe) 0820 Tailgate safety brief 0825 Enroute to downed Hydro axe 0830 While backing up I hit a tree limb and cracked the passenger side rear taillight. 0835 Equipment repair (Hydro axe) 1230 Lunch 1300 Equipment repair (Hydro axe) 1445 Hydro axe is repaired and is Enroute to gate for refueling 1500 Hydro axe breaks down 1501 Much profanity 1505 Equipment repair (Hydro axe) 1730 Stop repairs 1735 Start back to main 1745 Equipment download 1800 End of day

5

Team Members:
N/A

Date	Team	UXO Supervisor	Comment
3/15/2002	BRUSH2	D. Leshko	0530 Loaded equipment. Cassiopeia #16033 Magnatrac #1,checked on test grid. 2 Kenwood radios Radio Brush 2 Truck #15 0545 Departed for M1.01 area. 0555 Arrived M1.01 area. 0625 Morning safety briefing. 0640 Brothers servicing heavy equipment. Replacing blades. 0900 Started brush operation with hydro ax. 1115 Hydro ax operation stopped, attempting repair. 1200 Hydro ax out of service due to needing bearings for blade assembly. Transported back to UXO gate. 1215 Lunch. 1245 Lunch over. Joined manual brush operation. 1720 Ended brush operation. 1745 All personnel clear of M1.01 area. Main gate at Summeral locked waiting for security to unlock. 1830 Returned to compound.

Team Members:

N/A

3/16/2002	BRUSH2	D. Leshko	0530 Loaded equipment. Cassiopeia #16033 2 Kenwood radios Radio Brush 2 Truck #15 0545 Departed for M1.01 area. 0555 Arrived M1.01 area. 0625 Morning safety briefing. 0655 Started brush operation. 0750 Stopped operation due to lightning in area. On weather hold. 0830 Called it a day due to weather, departed for compound. 0900 End of day.
-----------	--------	-----------	--

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/16/2002	BRUSH 1	P. Bechtel	0600 F/W safety brief. 0620 Loaded equipment, vehicle 12, radio brush 1. 0630 Arrived at site. 0710 Started cutting brush. 0800 Stopped brush cutting for today due to rainfall. 0815 End of day.
	Team Members: N/A		
3/16/2002	BRUSH 3	D. Houseknecht	0600 Morning meeting and safety brief. 0630 Transit to M101 to escort brush crew. 0800 Heavy rain and lightning caused end of work due to unsafe conditions. 0830 Secure
	Team Members: N/A		
3/16/2002	DO15 SAFETY	J. Karkoszka	0530 Arrived on site 0600 Morning safety briefing 0630 Tailgate safety briefing 0640 Starting chipper operation 0750 Weather hold 0845 Terminated all activities in m1.01 areas for the day. 0900 Arrived compound stow gear/equipment , do log entries. 0930 Secured for the day.
	Team Members: N/A		

Date	Team	UXO Supervisor	Comment
3/18/2002	BRUSH 3	J. Karkoszka	0600 Safety brief at FW main shop. 0630 Meet at Summerall gate. 0715 Subcontractor started working. 0730 Second chipper arrived. 0815 Break 0830 Back to work 1000 Taking a break and then moving over to the middle section of M1.01 and start working along the fenceline. 1115 Break 1130 Back to work. 1200 Lunch 1230 Back to work 1515 Break 1530 Back to work. 1630 Crew stops work. They say that the company that they work for "forgot" to pay them for their overtime, so they are only working 10 hours today. 1715 Arrived back at FW compound. 1730 End of the day.

Team Members:

A. Athey

3/18/2002	SURVEY 1	F. Bynum	0600 Safety briefing. 0630 Load out. 0700 Depart compound. 0710 Tailgate safety briefing. 07:40 Start surveying grids in M101 area. 1135 Stop for lunch. 1205 End lunch. 1550 Began packing up for the day. Grid stakes staked for the day are: A77, A84, A86, B05, B06, B07, B08, B11, B12, B13, B14, B15, B18, B19, B20, B21, B22, B25, B26, B27, B28, B31, B32, B36, & B43. End of day.
-----------	----------	----------	--

Team Members:

N/A

134

Date	Team	UXO Supervisor	Comment
3/18/2002	BRUSH 1	R. Alberti	0600 Morning safety brief 0630 Equipment loadout 0650 Arrive on site 0655 Equipment repair (Hydro axe) 1230 Lunch 1300 Equipment repair (Hydro axe) 1700 Shutdown, loading equipment 1710 Enroute to main 1720 Offload equipment 1730 End of day

Team Members:

N/A

3/18/2002	BRUSH2	D. Leshko	0530 Loaded equipment. Cassiopeia #16033 Magnatrac #1 Radio Brush 2 Truck #15 0545 Departed compound for M1.01 area. 0555 Arrived M1.01 area. 0620 Morning safety briefing. 0640 Started brush operation. 1200 Lunch. 1230 Lunch over, resumed brush operation. 1715 Ended brush operation, moving heavy equipment back to gate. 1735 Departed for compound. 1800 End of day.
-----------	--------	-----------	---

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/18/2002	DO15 SAFETY	J. Karkoszka	0530 Arrived on site 0600 Morning safety briefing 0630 Tailgate safety briefing for brush operation 0700 Starting brush operation 0800 Co-ordinate with surveying crew 0920 Arranged escort for algasco/power comp. 0945 Escort for algasco /power comp. finished . 1030 Brush crews moved to center section , starting cutting operation . 1200 Lunch 1230 Lunch finished , resumed brush op. one hydro - axe repaired , one still being worked on. 1545 Second hydro axe still being worked on. brush operation continuing smoothly 1700 Brush operation stopped for the day. team's loadout gear, exit wooded areas for gate area.. 1730 Hvy equipment operation stopped for the day. 1800 Back in compounds . 1830 Secured

Team Members:

N. Metzler

Date	Team	UXO Supervisor	Comment
3/19/2002	BRUSH 3	J. Karkoszka	0600 Morning safety brief at main compound. 0632 Alberti and I arrive at the Summerall gate. Nate Martin is in the middle of his safety brief here. 0645 I am given my instructions, and I am going to the M3 parcel. 0730 Found one old illumination rifle grenade. I got some red flags from Dave and flagged it. 0910 Chipping crew takes a break. 0925 Break over. 1130 I am moved to escorting the large hydroaxe operator. 1230 Starts raining. 1415 Dana, the hydroaxe operator, has stopped for the day. I'm going back to the main FW compound. 1430 End of the day.

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/19/2002	DO15 SAFETY	J. Karkoszka	<p>0530 Arrived on site 0600 Morning safety briefing 0615 Equipment checked 0630 On working sites , 0635 Ttailgate safety briefing 0650 Co-ordinate tasking for brush removal operation hvy equipment being serviced and prepared . 0700 While discussing operation plan, it came to my attention that the general foreman [Bill Burns], had an extremely strong odor of alcohol on his breath . individual appearance seemed normal , will maintain close observation of him in the field. will contact site safety and pass information . individual made comments to his home office that uxo escorts are never here ready to support him before 0700. 0715 Starting operation whenever equipment is prepared and serviced . 0730 Starting manual brush operation in m-3 0930 Discussed situation about individual with alcohol on his breath and remarks made by about uxo escorts with site safety rep.. 1000 All FW personnel briefed on responsibilities of escorting and safety . have no authority to dictate on how and where to do brush operations. will perform only escort/safety duties . 1200 Lunch 1230 Finished lunch . 1235 Resumed brush operation and chipper work. 1445 Had small fire break out in m-3 parcel ..all nonessential personnel evacuated from woods, fighting fire, site safety notified . 1450 Fire out, soaked area with water , checked surrounding area for additional smoldering embers. 1500 Site safety on scene, assisted in determining cause of fire 1510 Determined that fire started as result of hydro axe blade striking rock under leaves sending a hot spark into the surrounding brush area, 1520 All clear given by site safety , resumed brush operation . 1645 Manual brush team's starting to break down for the day. 1655 Brush 2 called , hydro axe apparently had debris go on the roadway striking a vehicle,</p>

Date	Team	UXO Supervisor	Comment
			Anniston policeman responded . site safety and site manager notified . Brothers supervisor notified. 1720 All concerned parties met and police report filed. 1750 Areas secured 1815 Back in compound , working on incident report.

Team Members:

N. Metzler

Date	Team	UXO Supervisor	Comment
3/19/2002	DO 15 BRUSH2	D. Leshko	0530 Loaded equipment. Cassiopeia #16033 Radio Brush 2 Truck #15 0545 Departed compound for M1.01 area. 0555 Arrived M1.01 area. 0625 Morning safety briefing. 0715 Started brush operation. 1025 Window popped out of heavy equipment, waiting for repair. 1100 Restarted brush operation with heavy equipment. 1230 Lunch. 1300 Lunch over, took heavy equipment operator to help start tractor with chipper. 1325 Resumed brush operation with heavy equipment. 1445 Heavy equipment operator notified me of a small fire, notified TO 15 Safety. Was a small fire and put out. 1450 Fire out. on hold for Site safety ok to resume 1520 Cleared to resume operation. Refueling heavy equipment. 1545 Resumed brush operation. 1600 Stopped operation, equipment operator had to assist with getting tractor with chipper started. 1630 Resumed operation. 1650 Notified by heavy equipment operator that a truck on the highway had stopped. Went to investigate and notified TO 15 Safety. 1720 Returning to gate. 1800 End of day.

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/19/2002	BRUSH 3	J. Karkoszka	<p>0600 Morning safety brief at main FW compound.</p> <p>0615 Alberti and I arrive at Summerall gate.</p> <p>0620 Nate Martin arrived to give the morning safety brief.</p> <p>0620 The following is noted per instructions given to me by my team leader. While standing next to Joe Karkoszka and Bill from the subcontracted compay(Pevahouse), the smell of alcohol was coming from Bill's direction. When Bill directly breathed on me it was apparent that the smell of alcohol was his breath.</p> <p>0730 Antonio's crew is given instructions and they start work. We are working in the top right-hand corner of the middle parcel of M1.01 along the fenceline.</p> <p>0800 Joe comes to the site and two of the 8 people I have with me go with Joe to help on the M3 parcel.</p> <p>0830 Dave comes to get a pole saw. He says that I should have all personnel on the chipper chipping wood. I relayed the message to Antonio and he says that he doesn't want that many people working with one chipper.</p> <p>0915 Break.</p> <p>0930 Break over.</p> <p>0945 Antonio asks to speak to Joe. I call him on the radio and he says he will be here in a few minutes.</p> <p>1000 Joe arrives and speaks to Antonio about where he wants them to work next. Joe tells me that he is having a problem with the subcontractor and that FW employees are not to tell them how to do their job. He states that we are here only as uxo escorts.</p> <p>1030 I walked back to my truck to move it up the road toward where the grave sites are and someone moved it. It must have been one of the employees of Pevahouse because we are the only ones out here.</p> <p>1130 I notice that Dave is in site distance so I asked him if while he was there if he can help me keep an eye on the guys with chain saws so they don't get too close to the large machine.</p> <p>1200 Lunch. Joe comes by to get the water cooler from the Pevahouse truck. Joe tells me that I need to tell Phil from Pevahouse that if he can't get his tractor back where the piles of brush are then they need to drag them to the chipper. I am told now that I have to tell</p>

Date	Team	UXO Supervisor	Comment
			Pevahouse employees what to do.
			1230 Lunch over, back to work.
			1245 The tractor won't start.
			1300 Phil asks me to call Dave so that he can ask Chris from Pevahouse to come out here to help Phil with the tractor.
			1315 Chris arrives and fixes the tractor. Chris told Phil to get the piles of brush along the road and that he would bring the large hydroaxe out here and get the piles in the middle.
			1330 Phil asks me to ask Antonio if he can send one more person to help him chip. I asked Antonio and he said he didn't have anyone to spare. I told Phil that I had relayed his message and that no one was coming to help.
			1340 Joe arrived to check things out.
			1430 Break.
			1445 Break over. There is a fire in the woods. We are evacuating to Summerall gate. We are waiting for further instructions.
			1530 All clear. Everybody back to work.
			1545 Tractor won't start again. Called Dave to get Chris to come and help Phil with the tractor.
			1600 Chris arrives, Joe asks Dave to ask Chris when does everyone work till, he says plan on 1730.
			1630 Chris got the tractor started. Joe tells me that the Mexicans were told that they work until 5pm today.
			1700 The ground crew stopped working so we are heading up to the gate

Team Members:

A. Athey

Date	Team	UXO Supervisor	Comment
3/19/2002	SURVEY 1	F. Bynum	<p>6:00 Safety briefing. 6:20 Load out. 6:35 Depart compound. 6:45 Tailgate safety briefing. 6:50 Begin staking grid stakes. 11:50 Start lunch. 12.20 End lunch. 2:45 A fire in the woods was reported and we evacuated to the rally point. 3:20 Fire was put out and all clear was given. Resumed survey activities. 3:45 Departed for compound. Grid stakes staked for the day are: B33, B44, and B45. The following points are staked but not labeled with our numbers yet. 2698, 2699, 2700, 2701, 2702, 2703, 2704, 2705, 2706, 2707, 2708, 2709, 2710, 2711, 2712, 2713, 2714, 2715, 2716, 2726, 2727, 2725, 2724, 2723, 2722, 2728, 2737, 2738, 2739. End of day.</p> <p>Team Members: N/A</p>
3/19/2002	BRUSH 1	K. Wright	<p>0600 Morning safety brief 0630 Equipment loadout 0650 Arrive on site 0655 Equipment maintenance (Hydro axe) 0800 Tailgate safety brief 0805 Start work 1230 Lunch 1300 Start work 1445 Fire down range all personnel to rally point 1520 All clear 1525 Equipment maintenance (Hydro axe) 1540 Start work 1700 Stop work 1705 Equipment maintenance (Hydro axe) 1735 Enroute to main 1745 Offload equipment 1800 End of day</p> <p>Team Members: N/A</p>

Date	Team	UXO Supervisor	Comment
3/20/2002	SURVEY 1	F. Bynum	6:00 Morning safety briefing. 6:20 Load out. 6:35 Depart compound. 6:45 Tailgate safety briefing. 6:55 Begin staking grids. 12:15 Start lunch. 12:45 End lunch. 12:46 Delayed by rain. 1:10 Return to work. 1:30 Delayed by rain. 1:45 Return to work. 3:50 Departed for compound. Grids staked are as follows: A57, A58, A59, A60, A61, A62, A65, A66, A67, A68, A69, A70, A73, A74, A75, A76, A78, A81, A82, A83, A85, B03, B04, A62.53, A62.48, A70.41, A70.37, A78.29, A78.26, A86.17, A86.16, A56.62, A64.64, A64.67, A72.69, A72.73, A80.74, A80.78, B02.79, B02.83, B10.84, B10.88, B17.89, B17.93, B24.94, B24.98, and B30.99. End of day.

Team Members:
N/A

3/20/2002	.DO15 SAFETY	J. Karkoszka	0530 Arrived on site 0600 Morning safety briefing 0630 Tailgate safety briefing to brother's brush crews and manual laborers . 0645 Crews moving into m-3 parcels to begin manual brush cutting and chipper operation . will use three chippers today. 0700 Brush operation resumed 1100 Ground brush crews leaving m-3 parcel going into center parcel. 1115 Lunch 1145 Lunch finished ,resumed brush operation . 1330 Ground crews released for the day, due to slick terrain . hvy equipment will still operate. 1430 All brush operation done for the day. 1445 Areas secured 1500 Fueled vehicles 1530 Secured for the day.
-----------	--------------	--------------	---

Team Members:
N/A

Date	Team	UXO Supervisor	Comment
3/20/2002	BRUSH2	D. Leshko	0530 Loaded equipment. Cassiopeia #16033 2 Kenwood radios Radio TO 15 Brush 2 Truck #15 0545 Departed for M1.01 area. 0555 Arrived M1.01 area, awaiting Brothers brush crew and morning safety briefing. 0625 Morning safety briefing. 0635 Brothers assembling equipment. 0805 Started brush operation. 0815 Chipper broken, attempting repair. 1030 Reshowed Brothers what doesn't need to be picked up. 1115 Lunch. 1245 Lunch over. 1250 Resumed brush operation. 1330 Manual brush operation, stopped due to rain. 1400 End of day.

Team Members:

N/A

3/20/2002	BRUSH 3	J. Karkoszka	0600 Morning safety brief at main FW compound. 0645 I arrived at the Summerall gate. 0700 I am escorting three personnel around in the M3 parcel. 0800 We moved over to the middle part of the M1.01 parcel in the upper right hand corner to chip the wood piles there. 0815 One more person arrives, I am now escorting four personnel. 1150 They break for lunch. 1230 They start working again. 1730 End of the day.
-----------	---------	--------------	--

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/20/2002	BRUSH 1	K. Wright	0600 Morning safety brief 0620 Equipment loadout 0635 Arrive on site 0640 Equipment maintenance 0755 Tailgate safety brief 0800 Start work 0805 Stop work (Chipper down) 0805 Equipment repair (Chipper) 0835 New assignment (Monitor brush crew) 1130 Lunch 1200 Start work 1330 Stop work (Bad weather) 1340 Enroute to main 1350 Offload equipment 1400 End of day
		Team Members: N/A	
3/21/2002	BRUSH2	D. Leshko	0530 Loaded equipment. Cassiopeia #16033 2 Kenwood radios Radio TO 15 Brush 2 Truck #15 0545 Departed for M1.01 area. 0555 Arrived M1.01 area, waiting for Brothers brush crew and morning safety briefing. 0625 Morning safety briefing. 0635 Brothers getting equipment ready. 0705 Started brush operation. 1215 Lunch. 1245 Lunch over. 1250 Resumed brush operation. 1700 Ended brush operation for the day. Moving equipment back to gate. 1730 Departed for compound. 1800 End of day.
		Team Members: N/A	

Date	Team	UXO Supervisor	Comment
3/21/2002	DO15 SAFETY	J. Karkoszka	0530 Arrived on site 0600 Morning safety briefing 0615 Training 0630 Equipment checked 0645 Arrived working sites 0650 Starting brush operation 0800 Return to office to work on incident reports. 1100 Lunch 1130 Lunch finished 1145 Return to field ,checked brush team's progress , no further op using hydro- axes allowed. 1400 Brush team's making good progress clearing areas 1700 Brush operation done for the day getting gear / hvy equipment out of areas . 1730 All personnel clear of m1.01 parcel 1800 Secured for the day

Team Members:

N/A

3/21/2002	BRUSH 1	R. Alberti	0600 Morning safety brief 0630 Equipment loadout 0650 Enroute to site 0700 Tailgate safety brief 0705 Equipment maintenance (Brush crew) 0725 Start work 1200 Lunch 1230 Equipment maintenance (Brush crew) 1300 Start work 1700 Stop work 1705 Equipment maintenance (Brush crew) 1710 Left site 1720 Equipment offload 1730 End of day
-----------	---------	------------	---

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/21/2002	SURVEY 1	F. Bynum	<p>6:00 Safety briefing. 6:25 Load out. 6:45 Depart compound with one survey person. 7:00 Tailgate safety briefing. 7:10 Start staking grids. 12:30 Start lunch. 1:00 End lunch. 3:40 Depart for compound. Points that we put in on Tuesday and labeled today: B08.06, B08.05, B15.94, B22.93, B22.58, B28.58, B33.58, B36.58, B39.97, B40.97, B40.95, B42.95, B43.54, B44.60, B45.54, B45.36, B49.70, B48.64, B47.77, B42.24, B42.23, B40.19, B40.18, B38.14, B38.13, B35.09, B35.08, B31.04, and B31.03. Total labeled is 29. Stakes put in today: A49, A50, A51, A52, A53, A41, A42, A31, A12, A19, A20, A21, A28, A29, A30, A38, A39, A40, A47, A48, A53.58, A53.65, A42.69, A42.77, A31.80, A31.89, A56.36, A55.69, A12.30, A20.88, A21.46, A21.90. Total staked today is 32. End of day.</p> <p style="text-align: center;">Team Members: N/A</p>
3/22/2002	BRUSH2	D. D. Leshko	<p>0530 Loaded equipment. Cassiopeia #16033 2 Kenwood radios Radio TO 15 Brush 2 Truck #15 0545 Departed for M1.01 area. 0555 Arrived M1.01 area, waiting for Brothers brush crew and morning safety briefing. 0620 Morning safety briefing. 0630 Brothers assembling equipment. 0645 Started manual brush operation. 1135 Departed for compound. 1200 End of day.</p> <p style="text-align: center;">Team Members: N/A</p>

*Final Site Specific Final Report
M1.01 Parcel and M3 Miscellaneous Property
Fort McClellan, Alabama*

Date	Team	UXO Supervisor	Comment
3/22/2002	DO15 SAFETY	J. Karkoszka	0530 Arrived on site 0600 Morning safety briefing 0610 Equipment checked 0620 Tailgate safety briefing 0630 Brush crews starting operation . 0800 Making good progress , so far, no chipper operation required yet. vegetation not very thick , mostly light cutting , heavier areas previously cut using hydro - axe brush mower. 0955 QC-3 team requested we open gate at soccer field , dispatched brush -2 member. 1005 QC-2 team requested gate at soccer field be opened , dispatched brush -2 team member. 1130 Brush -2 escort released for the day 1200 Lunch 1230 Lunch finished , resumed brush operation 1400 SUXSO on site , informed team's of new locks installed on uxo gates, he will bring new keys out shortly. 1600 Brush operation done for the day 1620 All personnel clear of m1.01 and all gates secured 1700 Secured for day

Team Members:

E. Kramer

Date	Team	UXO Supervisor	Comment
3/22/2002	SURVEY 1	M. Leak	0600 Morning safety brief 0630 Head out to M1.01 0700 Have to go back to shop and get replacement batteries for Magna-Track 0715 Back on M1.01 0730 Sat up on 312.3 and shot back sight 0800 Put in A12.72 0810 Magna-Track died 0835 Went to get a Schonstadt from Joe Karkoska 0842 Back in M1.01 area 0845 Reset A11.73 0847 Put in A06.36 0851 Put in A06.15 0906 Put in A27 0912 Laid down A37, not exact because of trees. Have to return to it 0920 Put in A46 0923 Put in A46.05 0929 Put in A46.02 0935 Put in A45.35 0940 Put in A44.68 0946 Laid down A33.02, not exact because of trees. Have to return to it 0950 Laid down A23, not exact because of trees. Have to return to it 0957 Put in A14 1003 Laid down A-07, not exact because of trees. Have to return to it 1017 Put in A08 1025 Put in A15 1030 Put in A24 1037 Put in A34 1042 Put in A35 1048 Put in A36 1102 Put in A26 1112 Put in A25 1117 Put in A16 1121 Put in A17 1130 Put in A18 1134 Broke for lunch 1234 Return from lunch 1246 Put in A11 1252 Put in A10 1256 Put in A09 1308 Shoot in a traverse point 1327 Put in A07 1331 Put in A07.10 1333 Put in A07.04 1337 Put in A13.61 1344 Put in A22.26

Date	Team	UXO Supervisor	Comment
			1349 Put in A23 1356 Put in A33.2 1404 Put in A33 1433 Put in A03.32 1444 Put in A04 1452 Put in A05 1500 Set in a new traverse point 1515 Put in A01.67 1522 Put in A02 1529 Put in A05.58 1531 Survey crew secures gear for the day 1535 Leaving M1.01 area 1600 Last entry
	Team Members: N/A		
3/22/2002	SURVEY 2	D. Blackwell	0600 Morning meeting 0610 Equipment loadout 0630 Departed for M101area. 0645 Arrived at M101 area 0650 Tailgate Safety Brief 0700 Team started placing stakes for grid G-02 1150 Team completed grids g60,g48,g34,g19,g02, g03,g20,g35,g04,g05, and f 59,f 60,f 40,f 41,f 61 f 62 1215 Lunch 1245 Back to work 1600 Team completed grids f 42,f 43,f 44, f 45, f 63,f 64,f 65,f 66 and g6, g7,g8,g9,g10,g21,g22,g23, g24,g25,g26,g27,g36,g37,g38g39,g40,g41,g49,g 50,g51 1615 Team ends day 1620 Departed m101 area 1630 Arrived Foster Wheeler compound 1635 Downloaded equipment and turned in paperwork 1645 End of day
	Team Members: N/A		

Date	Team	UXO Supervisor	Comment
3/23/2002	DO15 SAFETY	J. Karkoszka	0730 Arrived on site 0740 Equipment checked 0800 Arrived on working site laborers will not start work until paid. awaiting Brother's foreman to arrive with payroll 0900 Foreman on site, laborers paid. morning safety briefing given 0910 Tailgate safety briefing 0915 Brush operation starting 1000 Hvy equipment trailers picking up one hydro axe, and two chippers. will pick up more on Sunday . 1430 Brush crews finished working for the day, no lunch taken. 1445 Brush crews loading gear and equipment . 1450 All personnel clear of m1.01 1455 Gates secured ,TF base notified. 1515 Back in compound ,put equipment and vehicles away 1530 Secured, site safety still in office. will be notified in the morning as to what time escort will be needed for the rest of the hvy equipment pickup.

Team Members:

D. Houseknecht

3/24/2002	DO15 SAFETY	J. Karkoszka	0900 Arrived on site checked out vehicles 0915 Awaiting brother's brush crews 0930 Brush crews on site to pick up one hydro axe, chipper ,and tractor . 1045 Loadout of hvy equipment done. all personnel clear of m1.01. 1100 Secured for the day.
-----------	-------------	--------------	---

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
3/25/2002	TO15 Safety	J. Karkoszka	0530 Arrived on site 0600 Morning safety briefing 0615 Equipment checked 0640 Arrived at working site, tailgate safety briefing .starting surveying escort . 0710 Site suxso , PM, and Art Holcomb inspection of brush areas revealed that several areas needed further work. John Brothers on site, and shown areas to be worked. 1130 Lunch 1200 Lunch finished , resumed surveying escort . 1430 Karkoszka retaped boundary lines that needed to be brushed , some areas were off by 15 feet, have scattered piles of brush in two of thee parcels . brush crews scheduled to return in a day or so. so far missed brush piles having no effect on surveying team's as of yet. 1540 John Brother's called about starting brush operation on Tuesday , refereed him to contact SUXSO and/or PM at the office. notified suxso of phone call. 1615 Surveying done for the day. area secured 1630 Back in compounds .

Team Members:

A. Athey

3/26/2002	DO15 SAFETY	J. Karkoszka	0530 Arrived on site 0600 Tailgate safety briefing given to brother's brush crews 0620 Morning safety and health briefing given to brother's brush crews 0650 Weather hold , lightning in areas , all personnel taking shelter in vehicles until further notice . 0735 All operation terminated for the day due to severe weather 0800 Secured for the day.
-----------	-------------	--------------	--

Team Members:

A. Athey

Date	Team	UXO Supervisor	Comment
3/27/2002	DO15 SAFETY	J. Karkoszka	0530 Arrived on site 0540 Equipment checked 0555 Arrived at m1.01 0600 Talked to John Peavahouse/bill burns on chipper operation and teams 0605 Brother's checking equipment , laborers not on site yet. on hold until they arrive to be briefed. 0630 Morning safety and health briefing , team tasking 0635 Tailgate safety briefing , survey team starting operation with escort 0640 Starting brush operation and chipper operation . 1120 Site suxso on site , showed areas that needed to be cleared further , and quality of work expected . 1200 Breaking for lunch 1230Lunch finished, resumed chipper operation in m-3 parcels , starting second chipper operation in center areas. 1300 Supervisor of boys camp requested if we could put chippings over fenceline into his planting area. pass on to site manager for approval. ok was given for just that small area . 1600 One chipper broken , team still working collecting brush and stacking for chipper operation when repaired . 1730 All operation done for the day 1800 Secured

Team Members:

D. Leshko

Date	Team	UXO Supervisor	Comment
3/28/2002	DO15 SAFETY	J. Karkoszka	0530 Arrived on site 0535 Checked equipment out. 0545 Depart for work site 0600 Open gate, brother's doing vehicles warm up and maintenance . morning safety and health briefing . 0615 Ttailgate safety briefing 0630 Starting chipper operation and brush clearing 0700 Notification by suxso that algasco need to be escorted at 0720. will meet them at gate. 0720 Escorted Jeff Gibson from algasco 0725 Algasco personnel clear of m1.01 area. area secure of all nonessential personnel 0810 Suxso notified me of demolition shot scheduled return to compound to prepare. 0855 One notice to tf base of demo shot 0900 Drawing demo explosive 0940 Depart for Charlie area demo site 0955 Demo briefing 1015 Demo preparation 1038 Final prime on demo shot 1055 Five minutes warning given to tf base and all radios prior to demo shot 1059 One minutes warning prior to detonation 1100 Demo shot fired 1101 Suxso and demo t/l checking demo shot 1110 Demo shot - all clear, demo operation complete for the day, 1125 Demo team back at firing point, 1130 Depart area returning to brush teams in m1.01 area. 1200 Lunch 1230 Lunch finished..brush team resumed clearing operation . one chipper still being repaired on site. Greg Williams [PM], and Steve Neill [site manager] on site. 1400 One chipper still broken ,one still in service , progress is fairly good with one machine in operation, 1445 Second chipper repaired ,starting chipper operation with second machine . 1555 Surveying team departed area. brush operation continuing . 1720 While looking at brush that needed to be cleared tomorrow , seven 2.36 rockets were discovered , site suxso notified and area marked . 1730 All personnel clear of m1.01 area and all

Date	Team	UXO Supervisor	Comment
			gates secured 1800 Secured for the day.
			Team Members:
			D. Leshko
3/29/2002	DO15 SAFETY	J. Karkoszka	0530 Arrived on site 0600 Morning safety briefing 0620 Equipment checked 0630 Tailgate safety briefing 0640 Site suxso /qc/site safety on scene with corps rep. Randy Harris looking at the seven rockets found late Thursday afternoon. It was decided that items will be disposed today during demo operations. 0750 Brother's brush crew decided to not continue operation today and will return on Monday . 0820 All brush crew clear of m1.01 areas .

Team Members:

D. Leshko

4/1/2002 DO15 SAFETY J. Karkoszka

Team Members:

D. Leshko

Date	Team	UXO Supervisor	Comment
4/2/2002	DO15 SAFETY	J. Karkoszka	<p>0530 Arrived on site</p> <p>0535 Equipment checked , refueled vehicle</p> <p>0600 Morning safety breifing</p> <p>0615 Uxo training</p> <p>0630 Tailgate safety breifing for brush crews.</p> <p>0645 Brush operations starting</p> <p>0815 Bobcat tractor on site, performed initial inspection , all appears in working order.</p> <p>0830 Starting bobcat operation .</p> <p>1000 Safety fenceline installed around well opening .site safety notified of completion . well has filled with water since last rainfall .</p> <p>1230 Lunch</p> <p>1300 Lunch finished , resumed brush clearing operations.</p> <p>1320 Site suxso on working site, john peavahouse discussed using a small dozer to move dead trees. operators breifed that on no circumstances will the blade penetrate the earth, and only surface debris will be pushed</p> <p>1330 Bulldozer on site, performed initial safety inspection , all appears in order and is in servicable condition.</p> <p>1350 Using bulldozer to move dead trees and brush piles.</p> <p>1405 Site safety notified of dozer operation .</p> <p>1415 Dozer operation stopped by direction of site suxso until further clarification on use of dozer to push trees and brush piles in m1.01 areas . resumed operation using bobcat with claw attachment</p> <p>1420 Bobcat operator stopped working ,on telephone</p> <p>1435 Site suxso called informed that john peavahouse assumed all hvy equipment operation on hold. informed operators that bobcat operation is ok to continue, dozer operation is on hold until site suxso arrives later . operator understand's will continue using bobcat until further notice to proceed other wise</p> <p>1525 Site qc on working site, observing bobcat operation .</p> <p>1545 Site qc departed working areas ..</p> <p>1610 Surveying team departing working areas , found uxo gate wide open, gate secured</p> <p>1625 Site suxso on site to observe dozer test..</p> <p>1645 Dozer testing complete ,dozer is not suitable for use in areas , no dozer operation is authorized for use. will continue to use bobcat .</p> <p>1705 All operations stopped for day. moving</p>

Date	Team	UXO Supervisor	Comment
			equipment to roadway . 1715 All personnel clear of m1.01 areas . 1720 Gates locked and secured. departed for main office 1730 Arrived main office ,turn in gear/equipment . 1745 Secured

Team Members:

D. Leshko

4/3/2002	DO15 SAFETY	J. Karkoszka	0530 Arrived on site 0535 Equipment checked 0600 Morning safety briefing 0615 Uxo training/snskes 0625 Departed for working site 0630 Tailgate safety briefing for brush crews 0640 Starting brush clearing operations in m1.01 areas 0900 Operation is moving along at a good pace. 1100 John peavahouse requested that site suxso come out after lunch and inspect areas done. possible that all work could be completed today. information passed on to site suxso 1200 Lunch 1230 Lunch finished, resuming brush clearing. 1400 Stopped bobcat operation , ground too soft. area will be finished manually. all other brush operations still in progress . 1500 Assisted site safety install class 2 safety fenceline around well opening . 1545 Installation of fenceline complete 1555 Surveying team clear of m1.01 areas . brush operations still continuing. 1630 Ste suxso on site, met with john peavahouse discussed that job should be complete by thursday noontime , depends on 9nspectio of areas . 1700 Work stopped for the day. 1725 Areas secured, all personnel clear of m1.01. 1745 Secured for the day.
----------	-------------	--------------	--

Team Members:

D. Leshko

Date	Team	UXO Supervisor	Comment
4/4/2002	DO15 SAFETY	J. Karkoszka	0540 Arrived on site 0600 Morning safety briefing 0615 Uxo training 0630 Tailgate safety briefing 0645 Brush operation resumed 0900 Site Suxso / pm on site 1220 Brush clearing operation complete , brother's loading equipment and vehicles . site suxso notified . 1320 Brush crews clear of m1.01 areas 1330 Secured for day

Team Members:

D. Leshko

4/8/2002	DO15 SAFETY/QC	P. Saveall	0600 Morning meeting. 0630 Site specific breifing and preparatory phase inspection for M1.01 0930 Toured work areas with site manager. 1215 USA Environmental SUXO reports radiator damage to team #2 vehicle and subsequent coolant spill. 1300 Investigate incident and begin report. 1330 Observed clearance operation in M1.01 grid A22. 1400 Depart M1.01. Return to office to continue work on IR02-18. 1600 Pass IR02-18 to chop. 1630 Secure.
----------	----------------	------------	--

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
4/8/2002	USAINTR1	R. Patenaude	0600 Safety Meeting 0620 Site training class 1000 Checked and load equipment 1030 Load budlite 1045 Depart compound for A sector, changed locks on north gates, checked housing area and road blocks 1100 Arrived at A01, tailgate safety 1115 Prepared and start A01 1140 A01 complete 1145 Turn trucks around 1200 Lunch 1230 Start A03 1400 Break 1415 Return to A03 1530 Start truck to hard top 1545 Load equipment 1600 Depart A03 for compound, changed locks on north gate 1615 Arrived at compound complete paper work 1630 Depart compound end of shift

Team Members:

J. Paksi
E. Huguenin
S. Collier
K. Jones
L. Stephens
R. Webb

Date	Team	UXO Supervisor	Comment
4/9/2002	USAINTR2	D. Renner	0600 Safety meeting 0620 Load and test equipment 0640 Depart CP, check South gate 0705 Arrive A22, conduct safety brief 0712 Begin intrusive on A22 0900 Break 0915 Resume intrusive 1130 Lunch 1200 Resume intrusive 1400 Break 1415 Resume intrusive 1550 Load truck 1600 Depart for CP 1630 Cease operations

Team Members:

L. Martin
P. Kendall
A. Smith
G. Edwards
M. Anderson

Date	Team	UXO Supervisor	Comment
4/9/2002	USAINTR1	R. Patenaude	0600 Sign in, briefing, safety and training 0630 Team leaders briefing, check and load equipment 0650 Depart compound for sector C, changed locks on north gates, checked housing area and road blocks on Littlebrant Dr. 0710 Arrived at sector C, tailgate safety and team briefing 0720 Start C02 all stakes for C01 and C05 are marked as C02 stakes 0800 Completed C01 start C05 0830 Complete C05 start C02 1200 Completed C02, lunch 1230 Start C03 1400 Complete C03, break 1415 Start C04 1450 Scrap picked up 1520 C04 complete 1530 Load equipment 1545 Depart area, changed locks on north 1630 Day Complete

Team Members:

J. Paksi
E. Huguenin
S. Collier
K. Jones
L. Stephens
R. Webb

4/9/2002	DO15 SAFETY/QC	P. Saveall	0600 Morning meeting. 1015 Observe intrusive activities in M1.01 C2. 1115 Fueled vehicle. 1400 Observed team #1 in M1.01 grid C4. 1445 Observed team #1. 1530 Admin. 1640 Secure.
----------	----------------	------------	---

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
4/10/2002	USAINTR2	D. Renner	0600 Safety meeting 0620 Load/test equipment 0645 Depart CP, check South gate 0710 A43, tailgate safety 0718 Digging on A43 0720 JR Martin told of embedded tick 0830 Off A43, to A33 0900 Break 0910 Resume work 1200 Lunch 1230 Start work 1350 Off A33, to A23 1400 Break 1415 Resume work 1550 Load truck 1600 Depart 1610 Arrive CP 1630 Days end

Team Members:

L. Martin
 P. Kendall
 A. Smith
 G. Edwards
 M. Anderson

4/10/2002	DO15 SAFETY/QC	P. Saveall	0600 Morning meeting. 0650 Teams #1 and #2 in the field. 0730 In the field. Check EZ and visit teams in the field. Team #1 working grid C9; team #2 in grid A43. 0830 Observed team #2 laying out grid A33. 1230 Observed USA ENV QC in grid A3. Grid failed QC check. 1630 Secure.
-----------	----------------	------------	---

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
4/10/2002	USAINTR1	R. Patenaude	0600 FW morning safety meeting 0620 USA team Ldr brief, check and test equip 0645 Departed for M1.01 0700 Tailgate safety brief 0715 Setup and started C09 0900 Break 0915 Return to grid 1020 Started C10 1130 Lunch 1200 Return to grid 1220 Complete C09, Start C11 1240 Complete C11 1300 Complete C10, begin C15 1400 Break 1415 Return to work 1545 Stopped work, loaded truck 1600 Departed for base 1615 Arrived base, download trucks 1630 End of day

Team Members:

J. Paksi
E. Huguenin
S. Collier
K. Jones
L. Stephens
R. Webb

Date	Team	UXO Supervisor	Comment
4/11/2002	USAINTR1	R. Webb	0645 Departed for M101 0600 FW morning safety meeting 0620 Test and loadout equipment, team leaders brief 0705 Barrier check complete, tailgate safety brief, 0720 Returned to grid C15 0900 Break 0915 Return to the grid 1130 Lunch 1200 Return to C15, start resweep 90 degrees 1340 Started 90 degree resweep of C10 &11 1400 Break 1415 Return to work 1500 Started resweep C09 1530 Stopped work, reload truck, 1A departed on scrap run 1550 Departed for base 1610 Arrived, clean and download equipment, team leaders debrief 1630 Days end

Team Members:

J. Paksi
E. Huguenin
S. Collier
K. Jones
L. Stephens

Date	Team	UXO Supervisor	Comment
4/11/2002	USAINTR2	D. Renner	0600 Safety meeting 0640 Depart cp,check south uxo gate 0620 Load/test equipment 0710 Digging on A23 0700 On A23,tail gate safety 0900-0915 Break 1100 Off A23 to A3 1145-1215 Lunch 1300 Off A3,to A14 1400-1415 Break 1550 Load truck 1600 Off grid 1610 At cp 1630 Days end

Team Members:

L. Martin
P. Kendall
A. Smith
G. Edwards
M. Anderson

4/11/2002	DO15 SAFETY/QC	P. Saveall	0600 Morning meeting 0830 Observed operations at M1.01 areas 1000 Set up detector and gather tools for QC 1250 At M1.01 A33 and 43 with USA ENV QC specialist 1415 Finished USA QC of grids A33 and A34 1430 QC C3 with USA ENV QC specialist 1545 Depart M1.01 1630 Secure
-----------	----------------	------------	---

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
4/15/2002	USAINTR1	R. Webb	0600 FW morning safety brief 0620 USA team leaders brief, test and loaded out equipment 0645 Departed to check gates and barriers 0705 Arrived M101, set work area, tailgate safety brief 0720 Started work on C06 0820 Jathan Futral arrived on site to work on team 0900 Break 0915 Return to grid 1130 Lunch 1200-1230 Lunch 1200 Return to grids 1115 Started C12 1320 C12 complete, started C07 1330 Break 1350 Return to grid 1515 C06 complete with 90 degree recheck 1530 Stop work, scrap team departed 1550 Departed for base 1605 Arrived, download equipment and stow, team leaders debrief 1630 End of day

Team Members:

J. Paksi
E. Huguenin
S. Collier
K. Jones
L. Stephens

4/16/2002	DO15 SAFETY/QC	P. Saveall	0600 Morning meeting 0800 Help USA ENV QC grids A2,3 and 7 1030 SUXO on site 1045 SUXO departs 1100 Depart M1.01 1330 Observed Team #1 in M1.01. 1530 Replace SW corner stake for A32 1630 Secure
-----------	----------------	------------	--

Team Members:

D. Welch

Date	Team	UXO Supervisor	Comment
4/16/2002	USAINTR2	D. Renner	0600 Safety meeting 0615 Load/test equipment 0635 Depart cp 0645 On A4,tail gate safety 0745 Off A4 to A44 0700 Digging on A4 0900-0915 Break 1200-1230 Lunch 1230 Off A44 to A34 1415-1430 Break 1550 Load truck 1630 At cp 1600 Off grid

Team Members:

L. Martin
P. Kendall
A. Smith
G. Edwards
M. Anderson

4/16/2002	USAINTR1	R. Webb	0600 FW safety brief 0615 USA team leaders brief, test and loadout equipment 0635 Departed base to check gates and barriers on route to work site 0650 Tailgate safety brief 0710 Returned to work on C07 0900 Break 0915 Return to grid 1130 Lunch 1200 Returned to grids, started C13 1400 Break 1415 Return to grids 1510 Complete C07 & C13, started C08 1540 Stop work 1600 Departed for base 1615 Arrived, download and stow equipment, team leaders debrief 1630 End of day
-----------	----------	---------	---

Team Members:

J. Paksi
E. Huguenin
S. Collier
K. Jones
L. Stephens

Date	Team	UXO Supervisor	Comment
4/17/2002	USAINTR2	D. Renner	0600 Safety meeting 0615 Load/test equipment 0635 Depart cp 0645 On A34,tail gate safety 0655 Digging on A34 0900-0915 Break 1020 Off A34 to A32 1138 Off A32 to A24 1415-1430 Break 1550 Load truck 1600 Depart grid 1630 Days end

Team Members:

L. Martin
P. Kendall
A. Smith
G. Edwards
M. Anderson

4/17/2002	USAINTR1	R. Webb	0600 FW morning safety meeting 0615 USA team leaders brief, test and loadout equipment 0630 Departed for gate and barrier check in route to M101 0650 Checks complete, tailgate safety, permission to dig 0705 Returned to work on C08 0915 Return to work 0900 Break 1130 Started lunch 1200 Returned to work on C18 1345 Break 1545 Stopped work 1400 Return to work 1600 Departed for base 1615 Arrived, download equipment and stow, team leaders debrief 1630 End of day
-----------	----------	---------	---

Team Members:

J. Paksi
E. Huguenin
S. Collier
K. Jones
L. Stephens

Date	Team	UXO Supervisor	Comment
4/17/2002	DO15 SAFETY/QC	P. Saveall	0600 Morning meeting 0730 Verify EZs for M1.01 0745 Oserve Team #2 in grid A34 0825 Observe QC grids C1 and 5 0930 Observe QC grid A4 1345 Observe QC grid C3,4, and 6 1630 Secure

Team Members:

N/A

4/18/2002	USAINTR2	D. Renner	0600 Safety meeting 0635 Depart cp 0615 Load/test equipment 0655 Digging on C47 0645 On C47,tail gate safety 0820 Off C47/58 to A24 0900-0915 Break 1000 Started A15, two lanes lefted on A24 1120 Done on A24,working A15 1235 On C13 1200-1230 Lunch 1400-1415 Break 1430 Off C13, to A15 1550 Off A15,load truck 1608 At cp 1630 Days end
-----------	----------	-----------	---

Team Members:

L. Martin
P. Kendall
A. Smith
G. Edwards
M. Anderson

4/18/2002	DO15 SAFETY/QC	P. Saveall	0600 Morning meeting 0730 Verfied EZs for M1.01 0745 Observe QC of grid A23 0900 Observe QC of grids C-7,8,12 and 13. C13 to be done again. 1230 Admin 1630 Secure
-----------	----------------	------------	--

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
4/18/2002	USAINTR1	R. Webb	0600 FW safety brief 0615 Team leader brief, test and load equipment 0640 Depart FW area, check gate and change lock 0700 Tailgate safety brief and download equipment 0715 Permission to go intrusive, started on C-14/C18 25ft roadway 0840 Started 25ft roadway in C23 0900 Break 0915 Relocated break area, returned to work 0930 Started C29 and pick up where Tm2 left off in C37 1130 Lunch 1200 Return to work, started C30 1340 Break 1400 Return to work 1530 Stopped work 1545 Departed for fuel farm 1610 Arrived base, download and stow equipment, team leaders debrief. 1630 End of day.

Team Members:

J. Paksi
E. Huguenin
S. Collier
K. Jones
L. Stephens
J. Futral

Date	Team	UXO Supervisor	Comment
4/22/2002	USAINTR2	D. Renner	0600 Safety meeting 0612 Load/test equipment 0635 Depart cp 0648 On A15 ,tail gate safety 0653 Digging on A14 0755 Lighting strike called by FW Safety, team in trucks 0900 All clear on lighting,back on grid 1200-1230 Lunch 1555 Off grid,load truck 1607 At cp 1630 Days end

Team Members:

L. Martin
P. Kendall
A. Smith
G. Edwards
M. Anderson

Date	Team	UXO Supervisor	Comment
4/22/2002	USAINTR1	R. Webb	0600 FW morning safety meeting 0615 USA team leaders brief, test and load out equipment 0630 Departed to check gates and barrier 0650 Reported all secure, received permission to dig 0700 Tailgate safety brief 0715 Start C14 0745 FW Safety recalled all team's to their trucks due to lighting 0830 Lighting all clear, return to work 0910 Break 0925 Return to grid 1100 Lunch 1130 Relocated to C46 for 25ft roadway sweep 1215 Started C56 1250 Started C68 25ft roadway sweep 1330 Roadway sweeps complete, break 1345 Relocated back to C14, return to work 1545 Complete C14, stopped work 1600 Departed for base 1615 Arrived, download and stow equipment, team leaders debrief 1630 End of day

Team Members:

J. Paksi
E. Huguenin
S. Collier
K. Jones
L. Stephens
J. Futral

Date	Team	UXO Supervisor	Comment
4/22/2002	DO15 SAFETY/QC	P. Saveall	0600 Morning meeting. 0630 Vehicle checked. 0715 Checked EZ for M1.01. Begin FW QC of grids. 0750 Lightning within 3-5 mile area. All personnel retreat to vehicles until all clear is given. 0805 Lightning still in the area. Awaiting the all clear from base. 0835 Resume work. 1000 Fueled vehicle. 1200 Observed team #1 working along the fenceline clearing the roadway. 1245 SUXO on site 1330 Observe team #2 in grid A15. 1335 SUXO at team #2 location. 1400 QC Mgr on site. 1410 Observe team #1 in grid C14. 1715 Secure

Team Members:

N/A

4/23/2002	DO15 SAFETY/QC	P. Saveall	0600 Morning meeting. 0715 Checked EZ for M1.01. 0730 Perform surveillance on A44. 0900 Perform surveillance on A22. 1000 Initial phase inspection on team #3 in grid F59. 1035 Initial phase inspection on team #5 in grid G57. 1115 Initial phase inspection on team #4 in D32. 1200 Check EZ. 1230 Perform surveillance on grid C13. 1300 Admin 1630 Secure
-----------	----------------	------------	--

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
4/23/2002	USAINTR4	A. Smith	0600 Safety brief 0930 Tm 4 arrived grid D 31/32 1115 D31 complete 18 digs. 1200 Lunch 1324 D33 complete 45 digs total. 1445 Grid D52 complete 1630 Cease operations

Team Members:

M. Anderson
P. Kendall
W. Bennet
K. Groff
D. Millar

4/23/2002	USAINTR1	R. Webb	0600 FW morning safety meeting 0615 USA team leaders brief, new team orientation, and loadout 0905 Departed to check gates 0915 Tailgate safety brief 0930 Started on 25ft roadway D01 1130 Started 25ft roadway D16 1250 Complete work on roadway, lunch 1320 Relocated back to C18 1400 Break 1415 Return to grid 1545 Stopped work 1600 Departed for base 1615 Arrived, download equipment and stow, team leaders debrief 1630 End of day
-----------	----------	---------	---

Team Members:

M. Koerner
N. McNally
R. Russel
D. Potts
L. Stephens

Date	Team	UXO Supervisor	Comment
4/23/2002	USAINTR2	D. Renner	0600 Safety meeting 0620 Load/test equipment 0635 Depart cp 0650 On A8,tail gate safety 0656 Digging On A8 0900-0915 Break 1215-1245 Lunch 1400-1415 Break 1550 Off grid 1605 At cp 1630 Days end

Team Members:

L. Martin
S. Adams
D. Brown
G. Edwards

4/23/2002	USAINTR3	K. Jones	0600 Foster Wheeler safety brief 0620 USA Team leader brief, new team members attending site specific safety, and work plan brief 0635 Loading and checking equipment, team preparation 0930 Team depart compound for grid F59 1033 Start grid F59 1015 Tail gate safety brief 1130 Break for lunch 1200 Continue in grid F59 1400 Break 1415 Continue in C59 1520 QC picked scrap 1545 Secure from intrusive ops grid F59 1600 Depart grid for office 1630 End of day
-----------	----------	----------	---

Team Members:

E. Huguenin
R. Brooks
D. Burton
J. Royalty
D. Kneuppel

Date	Team	UXO Supervisor	Comment
4/23/2002	USAINTR5	J. Paksi	0600 FW safety brief 0620 Load and test equipment 0630 Depart FW site 0645 Tailgate safety brief 0655 Permission to go intrusive 0700 Start intrusive actions on G43 0900 Break 0915 Continue work on G43 1200 G43 complete 1201 Lunch 1230 Start intrusive action on G29 1400 Break 1415 Continue work on G29 1600 Load equipment and return to F W site 1630 Cease operations

Team Members:

S. Collier
J. Futral
V. Nelson
M. Hughes
R. Funk

4/24/2002	USAINTR5	J. Paksi	0600 FW safety brief 0620 Test equipment and load vehicles 0930 Depart site to M1.01 area G57 0945 Tailgate safety brief 1000 Permission to go intrusive. Start G57 1200 Lunch 1230 Continue work on G57 1400 Break 1415 Return to work on G57 1530 G57 complete 1531 Start work on G43 1545 Check out and Load equipment 1600 Depart grid and return to FW area 1630 Cease operations
-----------	----------	----------	---

Team Members:

S. Collier
J. Futral
V. Nelson
M. Hughes
R. Funk

Date	Team	UXO Supervisor	Comment
4/24/2002	USAINTR1	R. Webb	0600 FW morning safety meeting 0620 USA team leaders brief, test and loadout equipment. 0635 Departed to check barrier and gates 0715 Returned to C18 0700 Tailgate safety brief 0900 Break 0915 Return to work 1035 Complete C18, started C23 1130 Lunch 1200 Return to work 1345 Break 1400 Return to grid 1550 Stopped work 1610 Departed for base 1620 Arrived, download and stow equipment, team leaders debrief. 1630 End of day.

Team Members:

M. Koerner
N. McNally
R. Russel
D. Potts
L. Stephens

4/24/2002	USAINTR4	A. Smith	0600 Safety brief 0630 Team depart for site. 0700 Tailgate safety brief. 0710 Started intrusive on D33. 1000 Grid D33 complete 132 digs. 3lbs. Started D53. 1115 D31 complete 18 digs. 1200 Lunch 1324 D33 complete 45 digs total. 1410 D53 complete . 136 digs. 25 lbs noe. Started grid D54. 1445 Grid D52 complete 1530 D54 working. 97 digs 70lbs. 1600 Equip loaded. end of day.
-----------	----------	----------	---

Team Members:

M. Anderson
P. Kendall
W. Bennet
K. Groff
D. Millar

Date	Team	UXO Supervisor	Comment
4/24/2002	USAINTR2	D. Renner	0600 Safety meeting 0620 Load, test equipment , maintance, new person briefings 0950 On A15, tail gate safety 0958 Digging on A15 1200-1230 Lunch 1400-1415 Break 1555 Off grid 1607 At cp 1630 Days end

Team Members:

L. Martin
S. Adams
D. Brown
G. Edwards

4/24/2002	USAINTR3	K. Jones	0600 Foster Wheeler safety brief 0620 USA team leader brief 0635 Depart compound for grid F59 0645 Tailgate gate safety brief 0700 Premission to intrusive 0715 Continue in grid F59, found rifle grenade smoke at N41 E75 0900 Morning break 0915 Continue in grid F59 1130 Break for lunch 1200 Continue in grid F59 1430 Complete grid F59 1435 Mov9ng to Gulf sector 1445 Setup and start Grid G86 1545 Stop intrusive in G86 loading equipment 1600 Departing grid G86 for office 1630 End of day
-----------	----------	----------	--

Team Members:

E. Huguenin
R. Brooks
D. Burton
J. Royalty
D. Knuettel

Date	Team	UXO Supervisor	Comment
4/24/2002	DO15 SAFETY/QC	P. Saveall	0600 Morning meeting. 0945 QC check A34. 1315 Observe team #5 in G29. 1335 Observe team #3 in grid F59. 1400 Observe team #4 in grid D54. SUXO and I looked at the quality of the grubbing. It looks good to us but the team was saying they were having to move a lot of brush. 1500 Observe team #1 in grid C23. 1530 Check locator on targets at Iron Mt. south. 1630 Secure

Team Members:

N/A

4/25/2002	USAINTR2	D. Renner	0600 Safety meeting 0615 Load/test equipment 0635 Depart cp 0648 On A9,tail gate safety 0659 Digging on A9 0900-0915 Break 1200 1230 Lunch 1400-1415 Break 1550 Off grid/load truck 1606 At cp 1630 Days end
-----------	----------	-----------	--

Team Members:

L. Martin
S. Adams
D. Brown
G. Edwards

Date	Team	UXO Supervisor	Comment
4/25/2002	USAINTR4	A. Smith	0600 FW safety brief 0620 Test White's 0630 TM leaving for grid. 0700 Tailgate safety 0715 Started D34. 1200 Lunch 1440 Grid D34 complete. 263 digs. 37 lbs. 1445 Grid 54 complete .621 digs. 53 lbs nos. 1457 Grid D15 complete . 0 digs. 0 nos. 1520 Grid D16 complete . 0 digs. 0 nos. 1525 Complete grid ops. starting vehicle maintaince.

Team Members:

M. Anderson
P. Kendall
W. Bennet
K. Groff
D. Millar

Date	Team	UXO Supervisor	Comment
4/25/2002	USAINTR3	K. Jones	0600 Foster Wheeler safety brief 0615 USA Team leader brief and check instruments 0635 Depart compound and change assigned gate lock 0655 Tail gate safety brief 0657 Permission granted to go intrusive 0710 Continue intrusive ops in grid G86 0900 Break 0915 Continue in grid G86 0955 Complete G86 0958 Start grid G89 11:15 Complete G89 11:16 Start G88 11:30 Break for lunch 12:00 Continue in G88 1310 Complete grid G8 1317 Start grid G84 1405 Break 1420 Continue in Grid G84 1535 Stop intrusive activities 1545 Depart grid 84 to refuel vehicle 1630 End of day

Team Members:

E. Huguenin
R. Brooks
D. Burton
J. Royalty
D. Knueppel

Date	Team	UXO Supervisor	Comment
4/25/2002	USAINTR1	R. Webb	0600 FW morning safety meeting 0620 USA team leaders brief, test and loadout equipment 0635 Departed for barrier and gate check 0645 Tailgate safety brief 0700 Started on C30 0905 Break 0920 Return to grid 1050 Started C37 1140 Lunch 1210 Return to work 1350 Break 1405 Back to the grids 1535 Stopped work 1555 Departed for fuel farm 1620 Arrived base, download and stow equipment, team leaders debrief 1630 End of day

Team Members:

M. Koerner
N. McNally
R. Russel
D. Potts
L. Stephens

4/25/2002	DO15 SAFETY/QC	P. Saveall	0600 Morning meeting. 0745 Observe USA QC at F59 1000 Visit team #2 1030 QC A13 1300 Admin 1445 Oserve team #1 in C30 and C37. 1545 Admin 1630 Secure
-----------	----------------	------------	--

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
4/25/2002	USAINTR5	J. Paksi	0600 FW safety brief 0615 Test and load equipment , team leader brief 0630 Depart FW site 0645 Tailgate safety brief 0650 Permission to go intrusive 0700 Start intrusive actions on G29 0900 Break 0915 Continue intrusive on G29 1130 Lunch 1200 Continue intrusive on G29 1400 Break 1415 Continue intrusive on G29 1530 Grid G9 complete 1531 Check out equipment and load vehicle . 1540 Depart grid

Team Members:

S. Collier
J. Futral
V. Nelson
M. Hughes
R. Funk

Date	Team	UXO Supervisor	Comment
4/29/2002	USAINTR1	R. Webb	0600 FW morning safety meeting 0620 USA team leaders brief, test and loadout equipment 0640 Departed for gate check 0655 Tailgate safety brief, permission to dig. 0710 Started E44, stakes and map are hard to make sense of 0900 Break 0915 Return to grid 1130 Lunch 1200 Return to grid 1240 E44 complete, start E45 and E64 1345 Break 1405 Returned to the grids 1435 E64 complete. start E43 1535 E45 complete 1545 Stopped work 1600 Departed for base 1615 Arrived, download and stow equipment, team leaders debrief 1630 End of day

Team Members:

M. Koerner
N. McNally
R. Russel
D. Potts
L. Stephens

Date	Team	UXO Supervisor	Comment
4/29/2002	USAINTR3	K. Jones	0600 Foster Wheeler safety brief 0615 USA Team leader brief 0630 Equipment check, depart compound for grid C30 0640 Change locks on Sumerald road gate off of hwy 0650 Tailgate safety brief 0655 Permission to go intrusive 0705 Continue intrusive ops in grid C30 0812 Complete C30 0814 Lay out and start C37 0915 Break 0930 Continue in C37 1045 Complete C37 1046 Start C38 1130 Break for lunch 1200 Continue in Grid C38 1400 Break 1415 Continue in grid C38 1550 Stop intrusive activities grid C38 1600 Depart grid C38 to change lock and return to compound 1630 End of day

Team Members:

E. Huguenin
R. Brooks
D. Burton
J. Royalty
D. Kneuppel

Date	Team	UXO Supervisor	Comment
4/29/2002	USAINTR4	A. Smith	0600 Safety brief 0630 Left for site 0700 Tailgate safety . Equipment checked 0710 Started grid E1 1000 E1 complete . 119 digs. 18 lbs noes. Moving to E2 1200 Lunch 1400 Grid E2 complete .286 digs. 12 lbs noes. Started E23 1430 Grid E23 complete . 77 digs. 6 lbs noes. Started E3 1600 Close ops 1630 End of day

Team Members:

M. Anderson
P. Kendall
W. Bennet
K. Groff
D. Millar

4/29/2002	DO15 SAFETY/QC	P. Saveall	0600 Morning meeting 0630 Vehicle check 0645 Check out locators 0700 Make copies of survey maps 0730 Check EZ and visit teams in the grids. Survey stakes and blue boundary line continue to confuse team leaders 0800 QC grids C56 and D15 0900 QC grids G88 and G89 1230 QC grid G29 1445 QC grid G43 1630 Secure
-----------	----------------	------------	--

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
4/29/2002	USAINTR5	J. Paksi	0600 FW safety brief 0620 Test and load equipment , team leader brief. 0630 Depart FW site 0645 Tailgate safety brief 0655 Permission to go intrusive 0700 Begin intrusive action on A09. 0815 A09 complete 0816 Start intrusive action on A16 0900 Break 0915 Continue intrusive on A16 1130 Lunch 1200 Continue intrusive on A16 1300 A16 complete 1301 Start intrusive action on A25 1400 Break 1415 Continue intrusive on A25 1530 Scrap team departs 1600 Load vehicle and depart for FW site. 1630 Cease operations

Team Members:

S. Collier
 J. Futral
 V. Nelson
 M. Hughes
 R. Funk

4/29/2002	USAINTR2	D. Renner	0600 FW safety brief 0620 Load/test equipment 0635 Depart cp,pick up ropes off A9,moving to B49 0700 On B49,tail gate safety 0712 Digging on B49 0915-0930 Break 1200-1230 Lunch 1400-1415 Break 1555 Off grid,load trucks 1608 At cp 1630 Days end
-----------	----------	-----------	---

Team Members:

L. Martin
 S. Adams
 D. Brown
 G. Edwards

Date	Team	UXO Supervisor	Comment
4/30/2002	DO15 SAFETY/QC	P. Saveall	0600 Morning meeting 0700 Fueled vehicle 0730 Checked M1.01 EZ 0800 QC G57 0930 SUXO informs of demo shot at 1300 weather permitting 1200 Secure due to weather

Team Members:

N/A

4/30/2002	USAINTR3	K. Jones	0600 Foster Wheeler safety brief 0620 USA team leader brief 0630 Equipment check 0635 Depart compound for grid C38 0655 Tailgate safety brief 0658 Permission to go intrusive 0705 Continue intrusive ops grid C38 0900 Break 0915 break complete 0916 Directed to return to truck for lighting storm 0950 Return to work grid C38 1030 Return to truck for lighting 1200 End of day
-----------	----------	----------	---

Team Members:

E. Huguenin
R. Brooks
D. Burton
J. Royalty
D. Kneoppel

Date	Team	UXO Supervisor	Comment
4/30/2002	USAINTR2	D. Renner	0600 Safety meeting 0615 Load/test equipment 0645 Depart cp 0658 On B44,tail gate safety 0705 Digging on B44 0915 -0930 Break 0930 Ligthing in area,team in truck 0948 Out of truck back on grid 1030 Lighting called,in trucks 1129 Day called by usae suxos,due to weather. 1144 At cp 1200 End of day

Team Members:

L. Martin
S. Adams
D. Brown
G. Edwards

4/30/2002	USAINTR1	R. Webb	0600 FW morning safety brief 0620 USA team leaders brief, test and loadout equipment 0640 Departed for gate check 0655 Tailgate safety brief, permission to dig 0710 Return to work on E43 0900 Break 0915 Return to grid 0920 "All hands return to trucks due to thunder storm in the area" 0945 "All clear" returned to work 1030 "All hand to the trucks due to thunder storms" 1130 Day called due to weather, return to base 1140 Arrived, download, debrief 1200 End of day
-----------	----------	---------	---

Team Members:

M. Koerner
N. McNally
R. Russel
D. Potts
L. Stephens

Date	Team	UXO Supervisor	Comment
4/30/2002	USAINTR5	J. Paksi	0600 FW safety brief 0620 Test and load equipment , team leader brief 0650 Tailgate safety brief 0655 Permission to go intrusive 0745 A25 complete 0700 Begin intrusive action on A25 0746 Start intrusive on A35 0910 Lighting in the area, all personel in vehicle 0900 Break 0950 Continue intrusive on A35 1030 Lighting in the area all personel in vehicle 1120 Work cancelled due to weather 1200 Cease operations

Team Members:

S. Collier
J. Futral
V. Nelson
M. Hughes
R. Funk

4/30/2002	USAINTR4	A. Smith	0600 Morning safety . 0620 Equipment checked . 0630 Tailgate safety . Started E3. 0930 Lighting hold. 0955 Return to work. 1040 Lighting hold. 1131 End of day due to weather. 1200 Cease operations
-----------	----------	----------	---

Team Members:

M. Anderson
P. Kendall
W. Bennet
K. Groff
D. Millar

Date	Team	UXO Supervisor	Comment
5/1/2002	DO15 SAFETY/QC	P. Saveall	0600 Morning meeting 0715 Checked M1.01 EZ 0720 QC grids A5,6, and 9 0930 QC grid 8 1025 QC grid C18 1115 QC grids D31 and 51 1300 Roadguard for shot in E45 1400 Check shot hole 1410 Continued QC of D31 and 51 1430 Surveillance Team #1 grid F59 1630 Secure

Team Members:

N/A

5/1/2002	USAINTR4	A. Smith	0600 Morning safety 0615 Equipment checked 0630 Leaving for site 0645 Tailgate safety .Started E3 1300 Complete E3. 234 hits. 29 lbs. 1200 Lunch 1630 End of day
----------	----------	----------	--

Team Members:

M. Anderson
P. Kendall
W. Bennet
K. Groff
D. Millar

Date	Team	UXO Supervisor	Comment
5/1/2002	USAINTR1	R. Webb	0600 FW morning safety meeting 0620 USA team leaders brief, test and loadout equipment 0630 Download "Bud lite" 0645 Departed for gate check inroute to grid 0700 Tailgate safety brief 0715 Returned to work on E43 0815 Start on E63 0830 E43 complete 0930 Relocated to F59 0915 E63 complete, break 0950 Started work on F59(redo) 1200 Return to grid 1130 Lunch 1330 Break 1345 Return to grid 1545 Stopped work 1600 Departed for base 1615 Arrived, download equipment and stow, team leaders debrief. 1630 End of day

Team Members:

M. Koerner
N. McNally
R. Russel
D. Potts
L. Stephens

Date	Team	UXO Supervisor	Comment
5/1/2002	USAINTR2	D. Renner	0600 Safety meeting 0615 Load/test equipment 0635 Depart cp 0648 On B43,tail gate safety 0658 Digging on B43 0915-0930 Break 1215 Off B43,to G86 RE-DO grid 1230-1300 Lunch 1230 On G86 1415-1430 Break 1500 Renner found inbedded tick on left leg 1555 Load truck,off grid 1608 At cp 1630 Days end

Team Members:

L. Martin
S. Adams
D. Brown
G. Edwards

Date	Team	UXO Supervisor	Comment
5/1/2002	USAINTR5	J. Paksi	0600 FW safety brief 0620 Test and load equipment , team leader meeting 0630 Depart FW site 0645 Tailgate safety 0700 Permission to go intrusive 0701 Begin intrusive action on A35 0845 A35 complete 0846 Begin intrusive on A45 0900 break 0915 continue intrusive on A45 1030 A45 complete 1031 begin intrusive action on A54 1055 A54 complete 1056 Begin intrusive action on A46 1130 Lunch 1200 Continue intrusive on A46 1315 A46 complete 1316 Begin intrusive on A36 1400 Break 1415 Continue intrusive action on A36 1550 A36 complete 1600 Load vehicle and return to FW site 1630 Cease operations

Team Members:

S. Collier
J. Futral
V. Nelson
M. Hughes
R. Funk

Date	Team	UXO Supervisor	Comment
5/1/2002	USAINTR3	K. Jones	0600 Foster Wheeler safety brief 0615 USA teamleader brief 0625 Depart comound for M101 grid C38 0703 Permission to go intrusive 0705 Continue intrusive ops in C38 0859 Complete C38 0900 Break 0915 Return to work start grid C46 1130 Lunch break 1200 Continue in grid C46 1240 Complete Grid C46 1242 Start grid C47 1400 Break 1415 Continue in grid C47 1600 Depart grid C47 to change locks 1630 End of day

Team Members:

E. Huguenin
R. Brooks
D. Burton
J. Royalty
D. Kneuppel

Date	Team	UXO Supervisor	Comment
5/2/2002	USAINTR1	R. Webb	0600 Safety brief 0620 USA team leaders brief, test and loadout equipment 0635 Departed for barrier check inroute to grid 0650 Tailgate safety brief, permission to dig. 0705 Returned to F59 0745 Started F37 0900 Break 0915 Returned to grid. 1030 F37 complete 1130 Lunch 1200 Return to work 1330 Break 1345 Return to work 1530 Stopped work 1545 Departed for gas station 1610 Arrived base, download equipment, team leaders debrief, admin. 1630 End of day

Team Members:

M. Koerner
N. McNally
R. Russel
D. Potts
L. Stephens

Date	Team	UXO Supervisor	Comment
5/2/2002	USAINTR2	D. Renner	0600 Safety meeting 0615 Load/test equipment 0642 On G86,tail gate safety ,short one team member 0630 Depart cp 0657 Digging on G86 0715 Brown informed TL , that he found a inbedded tick on his left hip. 0915-0930 Break 1015 Edwards returns to team 1030 JR Martin bitten by something on right wrist, swelling,and hurting some 1200-1230 Lunch 1415-1430 Break 1555 Off grid 1608 At cp 1630 Days end

Team Members:

L. Martin
S. Adams
D. Brown
G. Edwards

Date	Team	UXO Supervisor	Comment
5/2/2002	USAINTR5	J. Paksi	0600 FW safety brief 0620 Test and load equipment , team leader brief 0630 Depart FW site 0645 Tailgate safety brief 0655 Permission to go intrusive 0656 Begin intrusive action on A26 0836 Begin intrusive action on A17 0835 A26 Complete 0900 Break 0915 Continue intrusive action on A17 1040 A17 Complete 1041 Begin intrusive action on A10 1130 Lunch 1200 Continue intrusive on A10 1400 Break 1415 Continue on A10 1430 A10 complete 1431 Begin intrusive action on A11 1515 Scrap run 1555 Vehicle fuel and equipment maintenance 1630 Cease operations

Team Members:

S. Collier
 J. Futral
 V. Nelson
 M. Hughes
 R. Funk

5/2/2002	USAINTR4	A. Smith	0600 Morning safety 0620 Equipment checked 0630 Leaving for site 0645 Tailgate safety . Started D16 1200 Lunch 1430 D16 complete . 555 digs. 43 lbs noes. Started D34 1545 Complete grid ops 1630 Cease operations
----------	----------	----------	--

Team Members:

M. Anderson
 P. Kendall
 W. Bennet
 K. Groff
 D. Millar

Date	Team	UXO Supervisor	Comment
5/2/2002	USAINTR3	K. Jones	0600 Foster Wheeler safety brief 0650 Change locks on housing area boundary gate 0710 Continue intrusive ops in C47 0912 Complete grid C47 0914 Break 0929 Start grid C56 1129 Start grid C57 1130 Lunch break 1200 Continue in grid C57 1400 Break 1230 Complete C57 1430 Start grid C68 1510 Complete grid C58 1515 Complete C68 1530 Depart grid to refuel vehicle 1630 Cease operations

Team Members:

E. Huguenin
R. Brooks
D. Burton
J. Royalty
D. Knueppel

5/2/2002	DO15 SAFETY/QC	P. Saveall	0600 Morning meeting 0700 Checked M1.01 EZ 0730 QC grids B43, 44, 45, 47, and 49. 1045 QC grids E43, 44, 45, 63 and 64. 1515 Observe team #3 in grid G58 1630 Secure
----------	----------------	------------	---

Team Members:

N/A

Date	Team	UXO Supervisor	Comment
5/6/2002	USAINTR6	M. Anderson	0600 Safety briefing Equipment check out and new personnel brief 0842 Depart compound for G58 0900 Arrive G58 0902 Tailgate safety brief 0915 Loaded White's and train new personnel 0925 Informed not to allow childers to work pending approval 1000 Begin intrusive on G58 1130 Completed G58 1135 Started intrusive on G44 1200 Lunch 1205 Notified Childers clear to work 1230 Completed lunch 1415 Break 1415 Visit from FW QC 1430 End of break 1550 Stopped ops on G44, dug 524 items 1600 Loaded truck for main compound 1605 Secured equipment 1630 End of day

Team Members:

R. Freve
V. Pajorin
D. Satko
G. Childers
D. Wilson

Date	Team	UXO Supervisor	Comment
5/6/2002	USAINTR2	D. Renner	0600 Safety meeting 0615 Load/test equipment 0635 Depart cp 0648 On G85,tail gate safety,team of 3,Renner,Martin,Brown 0654 Digging on G85 0900 Two new persons, on grid,safety brief 0900-0915 Break 0915 Garrett on grid,but not usacoe cleared yet. 1200-1230 Lunch 1213 Usacoe cleared Garrett to work 1248 Fifth team member on grid 1420-1435 Break 1550 Off grid 1605 At cp 1630 Days ends

Team Members:

L. Martin
 S. Adams
 D. Brown
 R. Booth
 R. Funk
 J. Garrett

5/6/2002	USAINTR4	A. Smith	0600 Morning safety 0630 Equipment checked 0700 Tailgate safety . Started D34 1130 D34 complete . 302 digs. 22 lbs 1200 Lunch 1545 Finished ops.D-54 489 digs. 7lbs 1630 End of day
----------	----------	----------	---

Team Members:

S. Elder
 P. Kendall
 W. Bennet
 K. Groff
 D. Millar

Date	Team	UXO Supervisor	Comment
5/6/2002	USAINTR5	J. Paksi	0600 FW safety brief 0620 Test and load equipment 0635 Depart FW area 0655 Permission to go intrusive 0650 Tailgate safety brief 0700 Begin intrusive action on A11 0830 A11 complete 0831 Begin intrusive action on A18 0900 Break 0915 Continue intrusive action on A18 1200 Continue intrusive action on A18 1130 Lunch 1225 A18 complete 1226 Begin intrusive action on A27 1415 Continue intrusive on A27 1400 Break 1515 A27 complete 1516 Begin intrusive action on A37 1555 Check and load equipment 1600 Depart grid for FW area 1630 Cease operations

Team Members:

S. Collier
J. Futral
V. Nelson
M. Hughes
C. Brown

Date	Team	UXO Supervisor	Comment
5/6/2002	USAINTR1	R. Webb	0600 FW morning safety meeting 0620 Test and loadout equipment 0640 Departed for gate check inroute to grid 0655 Permission to dig, tailgate safety brief. 0710 Return to F59 0905 Break 0920 Returned to grid 1130 Lunch 1200 Return to work 1400 Return to grid 1345 Break 1545 Stopped work 1615 Arrived, download equipment and stow, team leaders debrief. 1630 End of day.

Team Members:

M. Koerner
N. McNally
R. Russel
D. Potts
L. Stephens

5/6/2002	USAINTR3	K. Jones	0600 Foster Wheeler safety brief 0615 USA team leader brief 0630 Depart compound for grid C69 0650 Permission to go intrusive 0645 Changed locks on housing area gate 0705 Begin intrusive ops grid C70 0903 Break 0918 Continue in grid C70 1130 Break for lunch 1200 Return to C70 1400 Break 1505 Stop digging to make scrap run 1230 Stop digging completed all of C70 noted wire 1515 Picking up scrap 1630 End of day
----------	----------	----------	--

Team Members:

E. Huguenin
R. Brooks
D. Burton
J. Royalty
D. Knueppel

Date	Team	UXO Supervisor	Comment
5/6/2002	DO15 SAFETY/QC	P. Saveall	0600 Morning meeting 0700 Checked M1.01 EZ 0715 QC grids A14 and 15 0915 QC grids A45 and 46 1230 QC grid A54 1250 SUXO on the grid 1315 QC grid C14, 24 and 30 1530 Depart M1.01 1630 Secure

Team Members:

N/A

5/6/2002	USAINTR7	G. Edwards	0600 Safety brief 0630 New personal training 0640 Prepare equipment 0825 Greet new teammembers 0830 Depart compound 0840 Arrived work area 0851 Tailgate brief explain procedures 0905 Equipment training 0930 Lay out grid 59 0940 Start working 1230 Started using schostedt In some lanes. due to fragments and hot soil it was not very effective. we are continually using it to clear some small areas 1435 discovered pipe under tree marked w yellow flag and orange paint 1600 Stopped operations 1615 Arrived compound 1630 Complete
----------	----------	------------	--

Team Members:

S. Adams
J. Burton
S. Ennis
D. Foster
R. Harrer

Date	Team	UXO Supervisor	Comment
5/7/2002	USAINTR1	R. Webb	0600 FW morning safety meeting 0620 USA team leaders brief, test and loadout equipment 0640 Departed for gate check inroute to grid 0655 Permission to dig, tailgate safety brief, Note: R. Russell reported removing an embedded deer tick from inside his left knee 0710 Returned to F59 0900 Break 0915 Returned to grids 0810 Started F58 1020 F59 complete 1200 Return to work 1400 Return to work 1345 Break 1545 Stopped work 1600 Departed for base 1615 Arrived, download and stow equipment, team leaders debrief 1630 End of day

Team Members:

M. Koerner
N. McNally
R. Russel
D. Potts
L. Stephens

5/7/2002	USAINTR4	A. Smith	0600 Morning safety 0615 Equipment checked 0630 Leaving for site 0645 Tailgate safety . Started D54 1200 Lunch 1300 D54 complete . Started D55 1430 Require to leave D55 due to demo 1500 Relocated to E47 1530 Ceased ops due to demo 1630 End of day
----------	----------	----------	---

Team Members:

S. Elder
P. Kendall
W. Bennet
K. Groff
D. Millar

Date	Team	UXO Supervisor	Comment
5/7/2002	USAINTR6	M. Anderson	0600 Safety briefing 0630 Equipment checked and loaded 0645 Departed main compound for G44 0710 Conducted tail gate safety briefing both Daryl Satko and Rob Freve informed me that they had to remove an inbedded tick on 6/5/02. 0710 Arrived G44 0720 Started work on G44 0845 Completed operation on G44 75 items investigated, no OE items found. 0840 Started work on G45 0915 Team took 15min break 0930 Completed break 1200 Lunch break 1230 Completed lunch break 1245 Started G46 1355 Completed G46 1415 Took 15 min break 1420 Break Over 1550 Completed G45 1600 Departed G45 for main compound 1630 Completed operations

Team Members:

R. Freve
V. Pajorin
D. Satko
G. Childers
D. Wilson

Date	Team	UXO Supervisor	Comment
5/7/2002	USAINTR5	J. Paksi	0600 FW safety brief 0620 Test and load equipment , team leader meeting 0635 Depart FW area 0655 Tailgate safety brief 0656 Permission to go intrusive 0705 Begin intrusive action on A37 0905 A37 complete 0906 Break 0921 Begin intrusive action on A47 1105 A47 complete 1106 Begin intrusive on A55 1130 Lunch 1200 Continue intrusive action on A55 1310 A55 complete 1311 Begin intrusive action on A56 1400 Break 1415 Continue on A56 1545 Check and load equipment 1600 Depart for FW area 1630 Cease operations

Team Members:

S. Collier
J. Futral
V. Nelson
M. Hughes
C. Brown

Date	Team	UXO Supervisor	Comment
5/7/2002	USAINTR2	D. Renner	0600 Safety brief 0620 Load/test equipment 0640 Depart cp 0652 On G80 ,tail gate safety 0701 Digging on G80 0900-0915 Break 1000 Large 30 foot tree laying across grid 1010 Two oe items,one oe lookalike/see OE dara for G80 1200-1230 Lunch 1230 Moved of G80, due to demo on G80 /20% done 1235 On G83 1400-1415 Break 1555 Off grid,load truck 1608 At cp 1630 Days end

Team Members:

L. Martin
S. Adams
D. Brown
R. Booth
R. Funk
J. Garrett

Date	Team	UXO Supervisor	Comment
5/7/2002	USAINTR3	K. Jones	0600 Foster Wheeler 0615 USA Team Leader brief 0630 Check equipment/load and depart compound 0650 Check barackades and changed lock at housing area 0655 Tailgate safety brief 0658 permission granted for intusive ops 0705 Begin intusive ops C 71 0900 Break 0915 Continue in C71 1130 Break for lunch 1200 Continue intrusive ops in C71 1345 Located one 2.36 rocket and warhead full up at N35 E49 1400 Break 1347 Notified SUXOS 1415 Load equipment and move to grid B48 while Foster Wheeler conducts demo in C71 1435 Set up on B48 commence intrusive ops 1555 Complete grid B48 1600 Load equipment and return to compound 1630 End of day

Team Members:

E. Huguenin
R. Brooks
D. Burton
J. Royalty
D. Knueppel

Date	Team	UXO Supervisor	Comment
5/7/2002	USAINTR7	G. Edwards	0600 Morning safety brief 0635 Depart compound 0645 Arrived grid g59 0655 Tailgate safety brief 0700 Started grid work 0915 Break 0930 Off break 1000 Marked rubber coated wire with tree growing over it 76n-35e 1100 Marked steel pipe approximately 4in x 65 ft in grid g59. pipe continue into g60 1200 Lunch 1400 Break 1230 Lunch over 1415 Break over 1515 Turned over scrap 1600 Stopped operation and loaded truck 1610 Depart grid area 1610 Depart area 1620 Arrived compound 1630 End of day

Team Members:

S. Adams
J. Burton
S. Ennis
D. Foster
R. Harrer

Date	Team	UXO Supervisor	Comment
5/8/2002	USAINTR3	K. Jones	0600 Foster Wheeler safety brief 0615 USA team leader brief 0630 Check equipment and load vehicle 0645 Change locks on housing area gate 0635 Depart compound 0655 Permission granted to go intrusive 0646 Tail gate safety brief 0700 Stand9ng by to go intrusive in grid C71 0730 Continue intrusive ops in C71, delayed start while demo team removed debris from demo shot conducted 05/07/02 0900 Break 0915 Continue in grid C71 1020 Start intrusive ops in grid C69 1130 Break for lunch 1200 Continue in grid C69 1400 Break 1415 Continue in C69 1600 Stop digging in C69 3 lanes remain for completion 1630 End of day

Team Members:

E. Huguenin
R. Brooks
D. Burton
J. Royalty
D. Knueppel

Date	Team	UXO Supervisor	Comment
5/8/2002	USAINTR7	G. Edwards	0600 Safety brief 0635 Deapar compound 0645 Arrived grid 0655 Tailgate safety 0705 Started grid work 0845 Grid g59 complete 0915 Break 0930 Break over 1100 Hot hole 67n-8e marked w/paint and flags 1200 Lunch 1230 Lunch over 1320 Diggers found a blue in color at mine evac area and contacted suxos area 1355 Suxso arrived photo taken waiting on fw crews 1425 FW arrived 1425 Break 1520 Turned over scrap 1600 Stopped grid working 1610 Depart grid 1620 Arrived compound 1630 End work day

Team Members:

S. Adams
J. Burton
S. Ennis
D. Foster
R. Harrer

Date	Team	UXO Supervisor	Comment
5/8/2002	USAINTR6	M. Anderson	0600 Received daily safety briefing 0630 Equipment checked and loaded 0640 Departed main compound for G30 0655 Arrived G30 0700 Conducted tail gate safety briefing 0715 Started work on G30 0900 Team took a 15 min break 1200 Team took 30 min lunch 1230 Began ops G31 1305 Completed G30 1415 Team took 15 min break 1530 Departed G31 returned to main compound to load equipment for shipment. 1630 Completed operation for the day

Team Members:

R. Freve
V. Pajorin
D. Satko
G. Childers
D. Wilson

Date	Team	UXO Supervisor	Comment
5/8/2002	USAINTR5	J. Paksi	0600 FW safety brief 0620 Test and load equipment , team leader meeting 0635 Depart FW area 0650 Tailgate safety brief 0655 Permission to go intrusive 0700 Begin intrusive action on A56 0751 Begin intrusive action on A63 0750 A56 complete 0815 A63 complete 0816 Begin intrusive action on A48 0900 Break 0915 Continue on A48 1140 A48 complete 1141 Lunch 1211 Begin intrusive action on A38 1400 Break 1415 Continue on A38 1540 A38 complete 1541 Lay out lanes on A28 and sort scrap 1600 Check and load equipment and return to FW area 1630 Cease operations

Team Members:

S. Collier
J. Futral
V. Nelson
M. Hughes
C. Brown

5/8/2002	USAINTR4	A. Smith	0600 Safety brief 0615 Equipment checked 0630 Leaving for site 1145 E47 complete . Moving to D55 1200 Lunch 1600 Ceased operation . 399 digs 1630 End of day
----------	----------	----------	--

Team Members:

S. Elder
P. Kendall
W. Bennet
K. Groff
D. Millar

Date	Team	UXO Supervisor	Comment
5/8/2002	USAINTR2	D. Renner	0600 Safety meeting 0615 Load/test equipment 0630 Depart cp 0645 On G80,tail gate safety 0649 Booth,informed TL,he had two inbedded ticks on left hip 0655 Digging on G80 0915-0930 Break 1200-1230 Lunch,moving 500 feet during lunch to let demo look at ap mine. 1400-1415 Break 1415-1430 off whilebfw d4mo tem on near by grid looking at at AT mine 1555 Off grid ,load truck 1608 At cp 1630 Days end
	Team Members:		
	L. Martin		
	S. Adams		
	D. Brown		
	R. Booth		
	R. Funk		
	J. Garrett		
5/8/2002	USAINTR1	R. Webb	0600 FW morning safety meeting 0620 USA team leaders brief 0635 Departed for gate check 0650 Tailgate safety brief, permission to dig 0705 Returned to F58 0900 Break 0915 Return to worked 1130 Lunch 1200 Returned to grid 1330 Break 1400 Returned to the grid 1550 Stopped work 1605 Departed for base 1630 End of day
	Team Members:		
	M. Koerner		
	N. McNally		
	D. Potts		
	L. Stephens		
	R. Russel		

Date	Team	UXO Supervisor	Comment
5/9/2002	USAINTR1	R. Webb	0600 FW morning safety meeting 0620 USA team leaders brief, test and loadout equipment 0635 Transported POV's to new base site. 0710 Departed for gate check inroute to grid 0725 Tailgate safety brief, permission to dig 0740 Returned to F58 0800 Started F57 0900 Break 0915 Return to grids 0930 F57 complete 1130 Lunch 1200 Return to work 1250 A member of Skipper Engineering drove on site on a four wheeler unannounced to do some surveying. Notified SUXO of his presence. Shot his point and departed (:10). Back to work. 1345 Break 1400 Back to the grid 1530 Stopped work 1545 Departed for fuel 1615 Arrived, download equipment, team leaders debrief 1630 End of day

Team Members:

M. Koerner
N. McNally
R. Russel
D. Potts
L. Stephens

Date	Team	UXO Supervisor	Comment
5/9/2002	USAINTR7	G. Edwards	0600 Safety brief 0635 Departed compound 0645 Arrived grid 0657 Tailgate brief 0700 Informed by j. burton that she had removed an embedded tick. 0715 Started grid work 0915 Break 0930 Break over 1000 Discovered poss mine fuze 65n-52e, notified suxso 1200 Lunch 1230 Lunch over 1400 Break 1415 Break over 1530 Stopped grid working 1540 Departed grid 1550 Arrived compound 1620 Equipment clean and secured 1630 End Of day

Team Members:

S. Adams
J. Burton
S. Ennis
D. Foster
R. Harrer

Date	Team	UXO Supervisor	Comment
5/9/2002	USAINTR6	M. Anderson	0600 Safety meeting 0630 Equipment checked and loaded 0645 Preparation for site movement. loaded electronic for shipment to home office 0645 Went to gas station, fueled up vehicle. 0730 Arrived at G31 0732 Tail gate safety 0740 Started operation on G31 0900 15 min break 1200 Lunch break 1330 Started working on G32 1400 15 min break 1500 Completed G32 1600 Returned to main compound 1630 Completed operation for the day

Team Members:

R. Freve
V. Pajorin
D. Satko
G. Childers
D. Wilson

Date	Team	UXO Supervisor	Comment
5/9/2002	USAINTR5	J. Paksi	0600 FW safety brief 0620 Test and load vehicle , team leader meeting 0630 Move vehicles and equipment to new location 0720 Tailgate safety brief 0721 Permission to go intrusive 0725 Begin intrusive action on A28 0900 Break 0915 Continue intrusive on A28 0945 A28 complete 0946 Begin intrusive action on A19 1110 A19 complete 1111 Begin intrusive action on A12 1135 A12 complete 1136 Lunch 1206 Begin intrusive action on A20 1325 A-20 complete 1326 Begin intrusive on A29 1415 Continue intrusive action on A29 1400 Break 1525 A29 complete 1535 Check and load equipment and vehicle maintenance 1630 Cease operations

Team Members:

S. Collier
J. Futral
V. Nelson
M. Hughes
C. Brown

Date	Team	UXO Supervisor	Comment
5/9/2002	USAINTR4	A. Smith	0600 Morning safety 0615 Equipment checked 0630 Convoy to facilities 0645 Trouble with battery 0720 Arrived on D55. Tailgate safety 0730 Started D55 1200 Lunch 1230 Change team leader, UXOQC assume duties due to family emergency 1235 Resume intrusive on D55 1350 Steve Elder sent with truck to gate to meet mechanic 1350 Break 1405 Resume intrusive 1430 Steve returns 1445 Steve sent on scrap run 1450 Assist FW bldg sandbag barricade 1515 Cease operations, load truck 1545 Arrive compound, equipment maintenance 1630 Cease operations

Team Members:

S. Elder
P. Kendall
W. Bennet
K. Groff
D. Millar

Date	Team	UXO Supervisor	Comment
5/9/2002	USAINTR3	K. Jones	0600 Foster Wheeler Safety brief 0615 USA Team leader brief 0635 Check equipment and load equipment 0640 Move POV's to new offices 0650 Return to compound to pick-up team gear in old office 0700 Inspect housing area and switch locks on housing area gate 0700 Conduct tailgate safety brief 0720 Permission granted to go intrusive 0735 Continue intrusive activities in grid C69 0900 Break 0915 Continu in grid C69 0928 Complete C69 0930 Start grid D02 1130 Break for lunch 1200 Continue in grid D02 1400 Break 1415 Continue in D02 1520 Secure and depart D02 1525 Pick up man from team two and switch locks on housing area gate 1538 Refueling vehicle

Team Members:

E. Huguenin
R. Brooks
D. Burton
J. Royalty
D. Kneuppel

Date	Team	UXO Supervisor	Comment
5/9/2002	USAINTR2	D. Renner	0600 Safety meeting 0620 Load/test equipment 0645 Depart cp,move equipment ,pov's to new cp 0710 On G80 ,tail gate safety 0719 Digging on G80 0900-0915 Break 1200-1230 Lunch 1400-1415 Break 1555 Off grid,load trucks 1608 At cp 1630 Days end

Team Members:

L. Martin
S. Adams
D. Brown
R. Booth
R. Funk
J. Garrett

Date	Team	UXO Supervisor	Comment
5/13/2002	USAINTR1	R. Webb	0600 FW morning safety meeting 0625 USA team leaders brief, equipment loadout 0645 Departed to old base site to test grid and drinking water 0705 Departed for gate check inroute to grids 0720 Tailgate safety brief, Mac McNally reported finding and removing an embedded tick on his upper left thigh, permission to dig. 0730 Returned ot F58 0905 Break 0920 Returned to work 1030 Angel Athey is added to the team 1035 Started G01 1135 Lunch 1205 Returned to grids 1235 F58 complete 1350 Break 1405 Return to work 1550 Stopped work 1605 Departed for base 1620 Arrived, download equipment, team leaders debrief. 1630 End of day.

Team Members:

M. Koerner
N. McNally
R. Russel
D. Potts
L. Stephens
A. Athey

Date	Team	UXO Supervisor	Comment
5/13/2002	USAINTR5	J. Paksi	0600 FW safety brief 0630 Load equipment , team leader brief 0655 Move to old FW site and test equipment 0715 Tailgate safety brief 0725 Permission to go intrusive 0726 Begin intrusive action on A39 0900 Break 0915 Continue on A39 0950 A39 complete 0951 Begin intrusive on A49 1045 Received Jake Clement on the team. Gave him tailgate safety . 1130 Lunch 1200 Continue on A49 1230 A49 complete 1231 Begin on A57 1400 Break 1415 Continue on A57 1505 A57 complete 1506 Begin intrusive on A64 1610 Check equipment and load vehicle 1630 Cease operations

Team Members:

S. Collier
J. Futral
V. Nelson
M. Hughes
C. Brown

5/13/2002	USAINTR4	A. Smith	0600 Morning safety 0630 Equipment checked 0645 Leaving for site E4 0715 Tailgate safety 1140 E24 complete . 524 hits. 26 lbs 1145 Started E4 1200 Lunch 1545 Grid E4 515 hits . Ceased operation 1630 End of day
-----------	----------	----------	---

Team Members:

S. Elder
P. Kendall
W. Bennet
K. Groff
D. Millar
J. Clement

Date	Team	UXO Supervisor	Comment
5/13/2002	USAINTR3	R. Brooks	0600 Foster Wheeler Safety Brief 0615 Checked out equipment 0620 Departed Compound for test grid 0630 Tested equipment on test grid 0700 Changed lock on housing area gate and checked barrier 0715 ARRIVED safe area conducted tail gate safety brief 0730 USA SUXO mag and flag until team leader approval is received 0735 team start mag and flag 0900 Started break 0915 Returned to work 1000 USA SUXO provided ice for team 1020 Started digging Larry On site as Team Leader 1140 Break for lunch 1210 Started grid D03 1220 USA SUXO released Larry from Team Leader duty and placed team on hold until further notice 1230 UXO TECH I To QA 1330 UXO TECH I Return from QA 1400 UXO TECH I To QA 1430 Team depart for G80 to assist demo team 1500 Team depart G80 1515 Start scrap run 1600 Arrive scrap yard 1615 Depart scrap yard 1620 Arrive compound 1630 Days end

Team Members:

E. Huguenin
D. Knueppel
D. Burton
J. Royalty

Date	Team	UXO Supervisor	Comment
5/13/2002	USAINTR2	D. Renner	0600 Safety meeting 0645 Depart cp,go to test griid,get water,with four team members 0625 Load trucks,Brown informed team leader he has a burn on leg from wasp spray on 5/9/02. 0710 de part test grid 0724 On G80,tail gate safety 0730 Digging on G80 0735 Booth had inbedded tick on left leg 0800 M8 ap mine found N37/E78 G80 0828 N90/E77 hit under tree 0915-0930 Break 1145 N72/E81 Thermite grenade,unfuzed,N93/E81 3pcs smk mixture, 1200 Off G80, to G75 1205 -1235 Lunch 1230-1237 FW Demo team in area,waiting to work,when they leave 1345 Found 5foot timber rattle snake on grid,used long tree branches to get snake to move off grid. 1420 Off G75,due to demo 1430 On F2 1555 Off F2,not done,load truck 1605 At cp 1630 Days end

Team Members:

L. Martin
S. Adams
D. Brown
R. Booth
R. Funk
J. Garrett

Date	Team	UXO Supervisor	Comment
5/13/2002	USAINTR6	M. Anderson	0600 Safety meeting 0630 Equipment checked and loaded 0650 Went to old compound to check the white's on test grid and get drinking water. 0715 Departed old compound for G31 0730 Arrived at G31 0732 Conducted tail gate safety briefing 0750 Two personnel completing last three lanes on G31, remaining personnel started G14 0815 Completed G31 0915 15 minute break 0935 Received visit from FW QC (Pat) he was conducting an initial team assessment on team 1200 30 min lunch break 1415 15 min break 1515 Turned over scrap 1600 Stopped intrusion ops 1630 Completed daily operation

Team Members:

R. Freve
V. Pajorin
D. Satko
G. Childers
D. Wilson

Date	Team	UXO Supervisor	Comment
5/13/2002	USAINTR7	G. Edwards	0600 Safety brief 0645 Depart compound 0722 Arrived grid 0725 tailgate safety 0725 Started working 0910 Break 0925 Break over 1140 Lunch 1210 Lunch over 1220 Located rif smoke grenade g48 48n 83c 1350 G48 completed 1400 Break 1420 Moved to g07 1425 Arrived g07 1430 Set up grid and started working 1547 F07 completed 1615 Arrived compound 1600 Departed grid 1630 End of day

Team Members:

S. Adams
J. Burton
S. Ennis
D. Foster
R. Harrer

Date	Team	UXO Supervisor	Comment
5/14/2002	USAINTR1	R. Webb	0600 FW morning safety meeting 0620 USA team leaders brief, loadout equipment 0635 Departed for test grid 0640 Return to base, test grid locked 0700 Departed for backup test grid 0710 Departed test grid to work area 0720 Tailgate safety brief, permission to dig 0730 Set up, grub, and start work on F20 0900 Break 1045 Stopped digging due to demo 1100 All clear, returned to digging 1155 F20 complete, lunch 1225 Relocated to E71 and start. 1450 E71 complete, start E54 1550 Stopped work 1615 Departed for base 1625 Arrived, download equipment, debrief 1630 End of day.

Team Members:

M. Koerner
N. McNally
R. Russel
D. Potts
L. Stephens
A. Athey

Date	Team	UXO Supervisor	Comment
5/14/2002	USAINTR2	D. Renner	0600 Safety meeting 0620 Load equipment 0630 Waiting to use rest grid 0700 On test grid 0720 Off test grid 0735 On G75,tail gate safety 0740 Digging on G75 0915-0930 Break 1015 TL Renner injured left foot 1020 TM L Martin assessed injury, determined to be a puncture wound do to thorn. Performed first aid. Notified SUXO Richardson. 1030 SUXO Richardson arrived, stopped intrusive operation. TL taken to urgent care center. Team on hold. 1130 Lunch 1200 Lunch complete 1205 Team depart G75 meet and escorted Hertz to Summerall gate 1245 Team returns to G75 team still on hold 1445 AT practice Landmine found 1445 New TL Brooks arrived and completed safety brief 1455 Started intrusive operation 1530 Scrap 1600 Stopped operation 1615 Arrived compound 1630 End of day

Team Members:

L. Martin
S. Adams
D. Brown
R. Booth
R. Funk
J. Garrett

Date	Team	UXO Supervisor	Comment
5/14/2002	USAINTR3	R. Brooks	0600 Morning meeting 0630 Equipment loadout 0650 Await direction for new test grid location 0705 Arrive new test grid 0715 Depart test grid, all instruments check OK 0730 Arrive grid D03 0735 Tailgate safety brief 0740 Commence grid D03 0900 Break 0915 Continue grid D03 1130 Lunch 1200 Continue grid D03 1400 Break 1415 Continue grid D03 1600 Secure from intrusive 1605 Depart for compound 1620 Arrive compound 1630 Secure for the day

Team Members:

E. Huguenin
D. Knueppel
D. Burton
J. Royalty

5/14/2002	USAINTR4	A. Smith	0630 Equipment checked . 0700 Tailgate safety . 0715 Started operation E04. 1100 E04 complete 435 hits . Moving to F24. 1115 Work stopped due to vehicle trouble . 1200 Lunch . 1300 Vehicle fixed. 1310 Setting up F23. 1545 Ceased operation . 1630 End of day.
-----------	----------	----------	--

Team Members:

S. Elder
P. Kendall
W. Bennet
K. Groff
D. Millar
J. Clement

Date	Team	UXO Supervisor	Comment
5/14/2002	USAINTR5	J. Paksi	0600 Safety brief 0620 Check and load equipment 0700 Test equipment 0725 Tailgate safety brief 0740 Permission to go intrusive 0741 Begin intrusive action on A-64 0900 Break 0915 Continue on A64 1015 A64 complete. 2 ea 2.36 on grid for demo team 1016 Begin intrusive action on A71 1030 A71 complete 1031 Begin intrusive action on A72 1130 Move of of grid so demo team can prep on A64 1155 Lunch 1225 Begin intrusive action on A62 1400 Break 1415 Continue on A62 1600 A62 complete 1601 Check and load equipment 1630 Cease operations

Team Members:

S. Collier
J. Futral
V. Nelson
M. Hughes
C. Brown

Date	Team	UXO Supervisor	Comment
5/14/2002	USAINTR6	M. Anderson	0600 Morning safety meeting 0630 Loaded vehicle waited for direction to test grids 0706 Convoyed with other vehicle to test grids 0710 Arrived at test grids. checked white's 0718 Departed test grids enroute to G14 0725 Arrived at G14 0735 Received call from suxo, ok to intrusive 0740 Began instrusive operation on G14 0900 15 min break 1200 30 min lunch break 1345 Began instrusive operation on G13 1350 Found a illumination round at N35 E55 1415 15 min break 1425 Identified large nails pit. area marked for backhoe 1435 Found a illumination round at N75 E40 1600 Completed intrusion ops 1600 Stopped to help team4 with there vehicle (want start) 1630 Retuned to main compound completed ops for the day.

Team Members:

R. Freve
V. Pajorin
D. Satko
G. Childers
D. Wilson

Date	Team	UXO Supervisor	Comment
5/14/2002	USAINTR7	G. Edwards	0600 Safety brief 0620 Team leader brief 0700 Test grid check 0715 Depaart test grid 0730 Tailgate safety brief 0741 Started digging 0725 Arrived F08 0755 Located practice mine at 15n1e f08 0915 Break 0930 Break over 1130 Lunch 1202 Lunch over 1400 Break 1415 Break over 1520 Complete grid F08 1530 Arrived g49 1535 Set up grid g47 1600 Depart grid 1615 Arrived compound 1630 Working day over

Team Members:

S. Adams
J. Burton
S. Ennis
D. Foster
R. Harrer

Date	Team	UXO Supervisor	Comment
5/15/2002	USAINTR3	R. Brooks	0600 Foster Weeler safety briefing 0615 Equipment checked and loaded 0630 Depart compound 0645 Changed lock at housing area gate and checked barackades 0650 Arrived D03 0655 Tail gate safety brief 0700 Cleared to go intrusive 0900 Break 0915 Return to work 1130 Break for lunch 1200 Return to work 1400 Break 1405 Foster Wheeler Safety arrived 1415 Returned to work 1515 D03 complete 1515 Started D04 1600 Stopped intrusive work 1610 Changed locks on housing area gate 1620 Arrived compound 1630 Cease operations

Team Members:

E. Huguenin
D. Knueppel
D. Burton
J. Royalty

Date	Team	UXO Supervisor	Comment
5/15/2002	USAINTR7	G. Edwards	0600 Safety brief 0625 Team leader meeting 0650 Depart compound 0655 Arrived grid 0655 Tailgate brief 0706 Started grid work g49 0800 Found grenade fuse w/cap @ 93n2e grid g49 0915 Break 0930 Break over 1200 Lunch 1235 Lunch over 1415 Break 1430 Break over 1611 Depart grid 1620 Arrived compound 1630 End working day

Team Members:

S. Adams
J. Burton
S. Ennis
D. Foster
R. Harrer

5/15/2002	USAINTR4	A. Smith	0600 Morning safety . 0615 Equipment checked . 0645 Leaving for site. 0700 Picked up port-a-john from Delta sector moved it to Foxtrot. 0715 Tailgate safety . Started F23. 0815 F23 incomplete . 41 hits. Moving to F24. 1010 F24 420 hits. incomplete . Moving to F25. 1200 Lunch . 1455 F25 complete . 1084 hits. 58 lbs. Started F26. 1550 Ceased operation . 1630 End of day.
-----------	----------	----------	--

Team Members:

S. Elder
P. Kendall
W. Bennet
K. Groff
D. Millar
J. Clement

Date	Team	UXO Supervisor	Comment
5/15/2002	USAINTR2	D. Renner	0600 Safety meeting 0620 Load/test equipment 0635 Depart cp,get water at old cp 0650 Check uxo gates 0718 Digging on F2 0900 Done F2 except two unclear nail pits 0900-0915 Break 0915 On F3/F1,both small grids 1200-1230 Lunch 1400-1415 Break 1600 Off grid 1630 Days end

Team Members:

L. Martin
S. Adams
D. Brown
R. Booth
R. Funk
J. Garrett

Date	Team	UXO Supervisor	Comment
5/15/2002	USAINTR1	R. Webb	0600 FW morning safety meeting 0620 USA team leaders brief, test and loadout equipment 0640 Departed for gate check inroute to grid 0655 Tailgate safety brief, permission to dig. 0710 Returned to E54 0900 Break 0915 Returned to work. 1205 Stop work for demo on grid, relocate. 1210 Lunch 1245 All clear, returned to location. 1255 Returned to work on E54 1345 Started E33 1355 E54 complete 1400 Break 1415 Return to grid 1550 Stopped work 1605 Departed for base 1620 Arrived, download equipment, team leaders debrief. 1630 End of day

Team Members:

M. Koerner
N. McNally
R. Russel
D. Potts
L. Stephens
A. Athey

Date	Team	UXO Supervisor	Comment
5/15/2002	USAINTR6	M. Anderson	0600 Morning safety briefing 0630 Equipment checked and loaded 0645 Departed main compound for G13 0700 Arrived at G13 0707 Conducted tailgate safety 0716 Began intrusive operation on G13 0915 15 minute break 1030 Completed G13 1035 Started intrusive ops on G12 1200 30 minute lunch break 1400 15 minute break 1520 Turned over scrap 1600 Stopped intrusive operation for the day 1630 Complete daily operation

Team Members:

R. Freve
V. Pajorin
D. Satko
G. Childers
D. Wilson

5/15/2002	USAINTR5	J. Paksi	0600 FW safety brief 0620 Test and load equipment , team leader meeting 0650 Tailgate safety brief 0700 Permission to go intrusive 0701 Begin intrusive action on A72 0900 Break 0915 Continue on A72 0955 A72 complete 0956 Begin intrusive on A79 1015 A79 complete 1016 Begin intrusive on A65 1130 Lunch 1200 Continue on A65 1400 Break 1415 Continue on A65 1600 Check equipment and load vehicle 1630 Cease operations
-----------	----------	----------	---

Team Members:

S. Collier
J. Futral
V. Nelson
M. Hughes
C. Brown

Date	Team	UXO Supervisor	Comment
5/16/2002	USAINTR7	G. Edwards	0600 Safety brief 0630 Team leader meeting 0645 Depart compound 0655 Arrived grid g49 0705 Tailgate safety brief 0713 Start grid working 0915 Break 0930 Break over 1130 Lunch 1200 Lunch over 1230 Expended rif. smoke grenade located g49 80n92e, photo completed. 1415 Break 1430 Break over 1540 Ended gid work, recovered tools & equipment 1600 Arrived compound for weekly maintenance and pay 1630 End of day

Team Members:

S. Adams
J. Burton
S. Ennis
D. Foster
R. Harrer

Date	Team	UXO Supervisor	Comment
5/16/2002	USAINTR6	M. Anderson	0600 Morning safety meeting 0630 Checked and loaded equipment 0700 Departed main compound to G12 0715 Arrived at G12 0716 Tailgate safety 0722 Started intrusive ops on G12 0915 15 min break 0930 Completed intrusive operation on G12 0940 Started intrusive operation on G15 1200 Completed intrusive ops on G15 1200 Lunch break 30 minutes 1230 Started intrusive operation on G16 1415 15 minute break 1436 Started intrusive operation on G17 1445 Completed intrusive ops on G16 1546 Completed intrusive ops for the day 1550 Loaded vehicle returned main side 1630 Completed for the day

Team Members:

R. Freve
V. Pajorin
D. Satko
G. Childers
D. Wilson
J. Clement

Date	Team	UXO Supervisor	Comment
5/16/2002	USAINTR5	J. Paksi	0600 FW safety brief 0620 Test and load equipment 0700 Tailgate safety brief 0720 Permission to go intrusive 0721 Begin intrusive action on A65 0900 Break 0915 Continue on A65 0950 A65 done except for back hoe work 0951 Begin intrusive action on A58 1130 Lunch 1200 Continue on A58 1315 A58 complete 1316 Begin intrusive action on A50 1400 Break 1415 Continue on A50 1535 A50 complete 1536 Check and load equipment 1545 Equipment and vehicle maintenance 1630 Cease operations

Team Members:

S. Collier
J. Futral
V. Nelson
M. Hughes
C. Brown

Date	Team	UXO Supervisor	Comment
5/16/2002	USAINTR4	A. Smith	0600 Morning safety . 0630 Equipment checked . 0645 Leaving for site. 0700 Tailgate safety . Started F26. 0945 Commence working grid F47 1145 Completed grid F26 1200 Lunch break 1230 Return to work in grid F46 1400 Afternoon break 1415 Return to work in grid F46 1535 Secure from intrusive operations, packip equipment 1550 Arrive main compoid, download equipment 1630 Secure for the day

Team Members:

S. Elder
P. Kendall
W. Bennet
K. Groff
D. Millar

Date	Team	UXO Supervisor	Comment
5/16/2002	USAINTR3	R. Brooks	0600 Foster Wheeler safety brief 0615 Load equipment and checked 0630 Changed lock on housing area gate and checked barackades 0700 Cleared to start intrusive operation 0715 Started work D-04 0900 Started break 0915 Break over started work 1135 Lunch break 1205 Return to work 1300 OE found at 36N 75E 2.36 Rocket M-6 USA SUXO Notified 1345 USA SUXO Arrived and took picture. Directed to move to E-48.. 1350 Secured gear and moved 1400 Arrived E-48 1405 Started break 1420 Started work E-48 1540 Stopped work E-48 1545 Loaded gear 1550 Departed E-48 1600 Fueled vehicle 1605 Changed lock on housing are gate 1615 Arrived compound 1630 End of day

Team Members:

E. Huguenin
D. Kneppel
D. Burton
J. Royalty