Attachment B-6

Site Reconnaissance (27-31 July 1998) Field Activity Daily Log (FADL) Sheets

INTERNATIONAL TECHNOLOGY CORPORATION

FIELD ACTIVITY DAILY LOG

DAILY LOG				
DATE	7	27	98	
NO.	0	0	1	
SHEET	1	OF	3	

PROJECT NAME: Ft McClellan

PROJECT NO.:

FIELD ACTIVITY SUBJECT: Field/Ecological Reconnaissance #2

DESCRIPTION OF DAILY ACTIVITIES AND EVENTS:

Arrived on Installation at 12:20 pm C.S.T.

spoke with Lisa Kingsbury; checked in at Range control. Spoke with Mr. Tolbird on requirements for travel within Ranges. Scoped Cantonment area not covered during Reconn. #1.

1400 Site visit 150(7) Frmr Motor Pool Area 1000 (Pkg 3) Area is covered by streets/building, maintained grass, surrounded by stands of decid. trees. Area behind building appears to be Parcel 13(7) [UST gym Pool Bldg 1012]. Site 139(7) covered by parking lot.

1420 Site visit 172(7) Frmr Printing Plant Bldg 1060. Site previously visited; seep on east slope of bldg. Mound to be sampled. Sparse tree stands & open lawn.

1440 Golf course site; central-north area. Sediment depositional area within Cane Creek Noted minnows, songbirds, and a kingfisher?

1450 Golf course - maintenance shed revisit. ~~Ag SFT~~ Creek & 2 Depo. Soil samples not shown in EcoSmple map. Who has this WP site? Creek is mostly bedrock & shallow aquatic grass.

VISITORS ON SITE:
Michael Nazarias
Adrian Gonzalez

CHANGES FROM PLANS AND SPECIFICATIONS, AND OTHER SPECIAL ORDERS AND IMPORTANT DECISIONS.
NA

WEATHER CONDITIONS:
Overcast 80°F

IMPORTANT TELEPHONE CALLS:
Karen Sims FedEx cables for digital camera connection to lap top.

IT PERSONNEL ON SITE:

SIGNATURE: Adrian M Gonzalez

DATE: 7/27/98

327A-7-86

INTERNATIONAL TECHNOLOGY CORPORATION

FIELD ACTIVITY DAILY LOG CONTINUATION SHEET

DAILY LOG			
DATE	7	27	98
NO.	0	0	2
SHEET	2	OF	3

PROJECT NAME FTMC PROJECT NO.

FIELD ACTIVITY SUBJECT Field Reconn 2

DESCRIPTION ON DAILY ACTIVITIES AND EVENTS

1450 Walked over cart bridge onto SW side of ~~over~~ Ag Cane Creek. Noted dramatic effect of stream vegetation growth stopped at pipe outfall line.

Walk ~200 yds further east along SW side of Cane Creek to proposed ~~Gf~~ Ag Golf course stream smpl location 2 of 5. Stream is predominantly bedrock. Noted minnows, shiners, & freshwater snails throughout this Cane Creek reach.

Ag ~~1618~~ 1518 Golf course site smpl location 3 of 5 Great impoundment area of Remount creek with still water & depositional areas.

1525 Upstream Remount Creek adjacent to bridge on Galloway Gate Rd. and monitoring well LF1-G03. Site for possible upstream reference. Heavily vegetated corridor.

1545 Golf Course Remount Creek sampling location 4 of 5 adjacent to green & cart bridge 4320. Stream quiet flow; noted minnows, large frogs, large tadpoles

Note: Unable to access fifth Golf course sample site in Cane Creek.

Ag ~~1715~~ 1615 Print Plant Bldg 2051 Site 173(7). Bldg now Small Arms Training Team. Bldg & pavement surrounded by sparse tree stands & lawn.

1635 Stopped at Fmr Motor Pool Area North of Fmr DPDO [site 241(7)] This site was visited & photographed ~~at a previously visit.~~ Ag

1645 Site 162(7) Printing Plant Bldg 3183 across street from bldg 3170. Highly developed bordered by tree stands and maint. lawn~~ed~~. Ag Previously visited

632-3-86

INTERNATIONAL TECHNOLOGY CORPORATION

FIELD ACTIVITY DAILY LOG CONTINUATION SHEET

DAILY LOG			
DATE	7	27	98
NO.	0	0	3
SHEET	3	OF	3

PROJECT NAME: FTMC

PROJECT NO.:

FIELD ACTIVITY SUBJECT: Field Reconn #2

DESCRIPTION ON DAILY ACTIVITIES AND EVENTS

1700 Found the approx location of Trenches West of Remount [site 228(7)]. Not sure of exact location. Large grassy hill may be site; surrounded by deciduous tree with thick understory.

END for 7/27/98

INTERNATIONAL TECHNOLOGY CORPORATION

DAILY LOG			
DATE	7	28	98
NO.	0	0	4
SHEET 1		OF 5	

FIELD ACTIVITY DAILY LOG

PROJECT NAME: FTMC

PROJECT NO.:

FIELD ACTIVITY SUBJECT: Field Reconn #2 Ecological Habitat

DESCRIPTION OF DAILY ACTIVITIES AND EVENTS:

0810 Start to Choccolocco Corridor

0835 Entered Choccolocco Area from the south on Choccolocco Rd (?). Mountainous road surrounded on all sides by pine forest with sparse understory. Turned left, Uncertain about road name - most likely Bain's Gap Road.

0840 Stopped at Range 21 & Range 22 firing range. Range 22 is a maint'd lawn with bleachers & targets area just north of firing berm. Between berm & lawn is a moderately sized creek with short riparian vegetation along creek banks.

0900 Walked back to the moderately sized creek - most likely Cane Creek. It's swollen from intense rains early this morning. Several runoff ditches empty into creek. Culvert to west of property channels creek under road.

Found an access, dirt road running south btwn Ranges 22 and 21. Tank bridge crosses Cane Creek (photo A17) and leads to rear of Range 21 and upper origin of Cane Creek. Endangered species signs posted. Tributary and Cane Creek converge at end of dirt road. Seep from ground identified (photo A22). Egressed access road to Range 21 ~~meaAg~~ adjacent to Bain's Gap Road

VISITORS ON SITE:

CHANGES FROM PLANS AND SPECIFICATIONS, AND OTHER SPECIAL ORDERS AND IMPORTANT DECISIONS.

WEATHER CONDITIONS: Intense rain btwn 5-6 a.m.; heavy overcast skies at 9 a.m. No rain rest of day.

IMPORTANT TELEPHONE CALLS: Agnes - FAX; Karen - Ted Simon Email

IT PERSONNEL ON SITE: Michael Nazerias & Adrian Gonzalez

SIGNATURE: Adrian M Gonzalez

DATE: 7/28/98

327A-7-86

INTERNATIONAL TECHNOLOGY CORPORATION

FIELD ACTIVITY DAILY LOG CONTINUATION SHEET

DAILY LOG			
DATE	7	28	98
NO.	0	0	5
SHEET 2	OF 5		

PROJECT NAME FTMC PROJECT NO.

FIELD ACTIVITY SUBJECT Field Recon #2 Ecological Habitat

DESCRIPTION ON DAILY ACTIVITIES AND EVENTS

Seep located behind Range 21 may be Marcheta Hill Orchid seep.

0950 Stopped at Range 27 (a few hundred yrds further west along Bain's Gap Road). Cane Creek reach located along back of Range). Maint'd lawn surrounded by deciduous trees & shrubs.

0955 ~~Stopped~~ Turned left from Bain's Gap Road onto ? Rd. to bridge over Cane Creek (photo A24). Thick decid. forest with moderate understory.

1000 Drove further along "Range 20 / Site 239(7)" Road to Range 20 [Site 239(7)]. Typical Range with open, cleared land surrounded by unaltered forest of deciduous trees. Hill to left may be Marcheta Hill.

Drove further along "Range 20" Road to Range 28. In use for training, no photo. Could not find Site 240(7), but similar to 239(7) habitat likely.

1020 Drove back to Bain's Gap Rd to bridge over Cane Creek (photo A27). Decid. forest & riparian vegetation.

1030 Turned off Stump Dump Road to Intersection of dirt roads w/ "16E" sign on tree. Typical habitat of mixed pine deciduous forest with moderate to heavy decid. understory.

1040 Visit general area of site 106(6). Located culvert under dirt road, but no clear indication of an existing site, or of a stream along road. Noted sign a few hundred yrd later "Smoke Training Area R" and "...S" Did not attempt access down road adjoining this sign.

1055 Lunch break and photo transfer to lap top.

INTERNATIONAL TECHNOLOGY CORPORATION

FIELD ACTIVITY DAILY LOG CONTINUATION SHEET

DAILY LOG			
DATE	7	28	98
NO.	0	0	6
SHEET	3	OF	5

PROJECT NAME: FTMC PROJECT NO.

FIELD ACTIVITY SUBJECT: Field Recon #2 Ecological Habitat

DESCRIPTION ON DAILY ACTIVITIES AND EVENTS

1500 Arrived back onto Bain's Gap Road from Main Post direction.

Turned off road onto north-directed dirt road east of stump dump. Located old, wooden observation tower. Followed NE-directed dirt road toward 5-way intersection.

Maps show no aquatic but seeps and small creek observed along dirt road. Primarily mixed pine-decid. forest with Longleaf Pine. Misread map, possibly.

1525 Further along dirt road (APEC MPS) road splits but not reflected on maps. Took right fork; several hundred yrds further found a sizable seep-fed creek flowing north to south. Currently driving SE direction

1545 Further along dirt road came to strong creek crossing road (photos 86 & 87). Steep hill before creek traversed by truck. No aquatic species noted. Flow very fast; could be an intermittent creek during storm event

Weather: Partly cloudy; 81°F

Further along same road (SW direction) passed obstacle course foot path (on RR) and bldg PR6505-24, old helicopter; road widens w/gravel)

1555 Back out on Bain Gap Rd. Range 24 sign. Turned right off of Bain Gap Rd into open area with AST (Parcel Map Coord 36,32). Several concret foundations & wooden beam-tops.

INTERNATIONAL TECHNOLOGY CORPORATION

FIELD ACTIVITY DAILY LOG CONTINUATION SHEET

DAILY LOG			
DATE	7	28	98
NO.	0	0	7
SHEET	4	OF	5

PROJECT NAME: FTMC PROJECT NO.:

FIELD ACTIVITY SUBJECT: Field Reconn #2 Ecolog. Habitat

DESCRIPTION ON DAILY ACTIVITIES AND EVENTS

1606 Dirt road turnoff to north of Bain Gap Rd. has 2 signs: 16G to the left and 14B to the right.

Followed this road in a northerly direction to T (N and S). Noted a clear wetland area to left of road (photo B). Could be Fredrick Hill Aster Site? Road represents ~~boundary~~ border between Range 16G/14B, between APECs MP8/9, and is located in Coord 42,36. Better estimate is that wetland is part of Bains Gap Seep.

Michael walked to wetland. Reports strong vocalizations from numerous species associated with the wetland. Noted hawk flying in area.

1630 Further on border road located a "14C" sign, and a Radio Relay Antenna Tower (photo B11). Near Moorman Hill summit. Probably apex of APECS 3, 9, and 6

1640 Reached NE corner of Main Post on border of APECs MP3 and MP9. Turning Westerly direction along North boundary of Main Post.

1650 Reached a ground scar/clearing within APEC MP3. (photo B13). Noted standing water at base of gravel hill. Water appears to be semi-permanent: noted a full grown frog in the small pond, aquatic grass, and decaying deciduous leaves.

1700 Noted a hawk in trees just over Installation fence.

Turned south off of fenceline road, located open grass area surrounded by mixed pine-hardwood forest. MP03 (Coord. 38,50)

632-3-88

INTERNATIONAL TECHNOLOGY CORPORATION

FIELD ACTIVITY DAILY LOG CONTINUATION SHEET

DAILY LOG			
DATE	7	28	98
NO.	0	0	8
SHEET	5	OF	5

PROJECT NAME: FTMC PROJECT NO.:

FIELD ACTIVITY SUBJECT: Field Reconn #2 Ecolog. Habitat

DESCRIPTION ON DAILY ACTIVITIES AND EVENTS

1715 Noted small creek flowing off site to north.

Took next left (south, off of fenceline road). Found training assembly area to West of road. Noted several severely damaged pine trees (photos B18) to B18)

1730 Stopped a little further SE on MP2/3 boundary road. Cleared (recovering) area with young pines surrounded by older growth forest.

Turned around to return to fenceline road; which turned SW. Located the Fuelwood Area on right; and further down road located an abandoned detention camp.

1745 Took road to east of detention camp. Found large open area within APEC MP2 covered by small shrubs & surrounded by old growth forest.

Further on same road came upon large, excaved area. Road appears to end. May be back side of site 231(7).

1820 Passed German Mock Village. Took (Rt turn; toward South) dirt road to point where Cave Creek passes under road. Coord 28/29, 44

1830 Semi-lost somewhere within APEC MP6. Located 2 open grass fields surrounded by mixed pine-decid. forest.

1855 Cave Creek seep contributing to Cave Creek. Not heavy flow; standing water ~~only~~ also.

1900 End Field visits

632-3-88

INTERNATIONAL TECHNOLOGY CORPORATION

FIELD ACTIVITY DAILY LOG

DAILY LOG			
DATE	7	29	98
NO.	0	0	9
SHEET	1	OF	5

PROJECT NAME: FTMC

PROJECT NO.:

FIELD ACTIVITY SUBJECT: Field Reconn #2 - Ecological Habitat

DESCRIPTION OF DAILY ACTIVITIES AND EVENTS:

0830 Entered Choccolocco Corridor Area from the south on Rt. 9. Turned on first rt. turn, Rt 522 at Chocc. Corr sign showing Chocc. Corr Forest Office, Bain's Gap Camp ground, bike trail, etc. Followed this road all the way to eastern boundary of Chocc Corr. and beyond. Turned back to near boundary (photo C1).

0850 Continued back (west) along road trying to find 2 dirt roads providing access to the north. First is just a short access way ending ~100 yds off main dirt road. Second road was found but access denied by road conditions (photo C2)

0905 Back onto Rt 9 north, turned Rt onto Rainbow Dr. Found private lake (photo C3). Good reference location Harper's Lake?

0915 Back onto Rt 9 south, turned Rt onto Joseph Springs Mtwy Turned Rt onto first dirt road toward site 159(7). Difficult access, but cleared area in woods near road (photo C4).

0920 Further west on Joseph Springs Mtwy crossed Choccolocco Creek (ph. C5/C6) Noted turtles & carp in creek. Approx 30-40 yds width at bridge.

0935 Returned on Joseph Springs Mtwy, crossed Rt 9 to Rt 522. Found Willis Branch. (photo C7) Fairly strong flow.

VISITORS ON SITE:

CHANGES FROM PLANS AND SPECIFICATIONS, AND OTHER SPECIAL ORDERS AND IMPORTANT DECISIONS.

WEATHER CONDITIONS: Sunny 76°F

IMPORTANT TELEPHONE CALLS:

IT PERSONNEL ON SITE: Michael Nazerias Adrian Gonzalez

SIGNATURE: Adrian M Gonzalez DATE: 7/29/98

327A-7-86

INTERNATIONAL TECHNOLOGY CORPORATION

FIELD ACTIVITY DAILY LOG CONTINUATION SHEET

DAILY LOG			
DATE	7	29	98
NO.	0	1	0
SHEET	2	OF	5

PROJECT NAME: FTMC PROJECT NO.

FIELD ACTIVITY SUBJECT: Field Reconn #2 - Ecological Habitat

DESCRIPTION ON DAILY ACTIVITIES AND EVENTS

0940 Out onto Rt. 9 (Lft turn, heading south). Found where Willis Branch crosses under Rt. 9 at Mile 225 Marker. Fair flow; approx 10-15 feet across at bridge. Noted aquatic grasses, riparian veg. (deciduous), and minnows.

0950 Unnamed trib/creek crossing under Joseph Springs Mtwy is several hundred yrds west of Chocc. Creek (photo C10). Approx 10-15 feet wide at culvert.

Continued ~~east~~ west on Joseph Springs Mtwy. At "T" intersection Chocolocco Road turned rt (North), to Bains Gap Rd turned left & stopped at site 38(7) (photo C11). open field surrounded by mixed pine-decid. forest.

Back out onto Chocolocco ~~cross~~ road (turned left; north) to unnamed trib. forms boundary of Chocc. Corr Area. & Dairy farm located adjacent to trib creek.

Back south on Chocco. Road to Bain's Gap Rd. Turned Rt. to second dirt road on rt. Road is gated but walked toward unnamed trib. Noted mountain bike trail staging area, deer tracks, coyote tracks, and orchids. Found unnamed trib (photo C15). This trib is same as Dairy Farm trib, only upstream of Farm location.

1030 Further west on Bains Gap Rd, found a dirt road to right with construction debris, an open (red clay) clearing, a former small car dirt race track. Continued around to back of track and came upon a lake with a partially submerged boat (photo C16).

1050 South on Chocco Rd to southern boundary of Chocco Corr. to where creek trib crosses under Chocco Rd. (photo C17).

1105 Off map to south of Chocco Corr. Took Cobb Rd west to

INTERNATIONAL TECHNOLOGY CORPORATION

FIELD ACTIVITY DAILY LOG CONTINUATION SHEET

DAILY LOG			
DATE	7	29	98
NO.	0	1	1
SHEET	3	OF	5

PROJECT NAME: FTMC — PROJECT NO.:

FIELD ACTIVITY SUBJECT: Field Recon #2 Ecological Habitat

DESCRIPTION ON DAILY ACTIVITIES AND EVENTS

1145 Finished with Choccolocco Corridor. Back on Barns Gap Rd over mountains to Rocky Hollow Rd / 22nd st intersection. Stopped at bridge 4350 over Cane Creek. (photo C20)

Further on 22nd st to bridge over Ingram Creek (photo C21)

Turned Rt onto 21st street to bridge 4363 over Cane Creek (photo C22).

1200 Lunch

1250 Site 168(7) revisit for Agnes. Took site dimensions.

1320 Site 29(7) revisit for drainage ditches to Remount ~~ch~~ Ag creek. Saw one deer, & frogs in drainage ditch.

1400 Located Lake Yahoo (photo C23), Feed-ditch dry. Took road NE of campground; road serves as drainage ditch near boundary of APECs MP10 and MP11. Led to no where in particular; took photo C24 of typical area habitat.

1430 Took rt turnoff near Reynold's Hill turkey oak area within APEC MP12 (Range 18A) (photo C25). Back on main road; a few hundred yrds further turn ~~into~~ at rt off road located a small creek crossing dirt road (C26). Further west on same road located a

1445 trib to the first creek (C27). main creek flows parallel to road in E to W direction

1450 Reached south-western Main Post boundary; turned south along fenceline to adjoining road. Turned left (APEC MP 12; photo C28)

INTERNATIONAL TECHNOLOGY CORPORATION

FIELD ACTIVITY DAILY LOG CONTINUATION SHEET

DAILY LOG			
DATE	7	29	98
NO.	Ø	1	2
SHEET	4	OF	5

PROJECT NAME: FTMC — PROJECT NO.

FIELD ACTIVITY SUBJECT: Field Recon #2 Ecol. Habitat

DESCRIPTION ON DAILY ACTIVITIES AND EVENTS

1515 Changed a flat tire photo 29

1540 Traveled along ~~on~~ the west base ~~foot~~ of Davis Hill (APEC MP13) (photo C30) access to honeysuckle not found. Habit mixed pine-deciduous forest; no water found in Parcel Coord (21,1); noted frog crossing road, however.

1600 Turned into Range 15F/APEC MP11 (Parcel Coord 28,8) Deciduous forest with very little understory. Noted a small runoff creek flowing across road & down steep hill to our left.

1610 Further on same road (APEC MP11 Range 15F), found the feed trib to South Branch Cane Creek (photo C32). Large concret culvert on east side of road. Less than 100 yrds further the same feed trib to SoBr Cane Creek was crossed again. Flow was in opposite direction - east to west. Predominantly deciduous trees.

1630 Arrived at ~~Came out~~ other side of APEC MP11 road. Came out onto R24A in Range 15G. Not a cleared-access area! Noted that this is site 108(7). Open field with grass surrounded by forest (photo C33). Also noted a training area for chemical/burning activities (photo C34).

A few yards down road (north) is site 88(5) a fog oil storage area for smoke Range 24A. Combination of open grass fields and concret berms (C35). Road to east crosses large training field. Road crosses South Branch Cane Creek at bridge 6505 (photo C36), and ~50 yds further east is site 187(7), the former chemical munitions disposal training area. [C37] ~~Cre~~ Ag Creek bottom in this general area is rather rocky.

INTERNATIONAL TECHNOLOGY CORPORATION

FIELD ACTIVITY DAILY LOG CONTINUATION SHEET

DAILY LOG			
DATE	7	29	98
NO.	0	1	3
SHEET	5	OF	5

PROJECT NAME: FTMC PROJECT NO.

FIELD ACTIVITY SUBJECT: Field Reconn #2 Ecol. Habitat

DESCRIPTION ON DAILY ACTIVITIES AND EVENTS

1710 Found another road that crosses So Br Cane Creek (Coord. 26,19; Range 15C). Photo C38; substrate is silt-covered gravel.

1720 Back on Rocky Hollow Rd heading north, crossed So Br. Cane Creek at bridge 4365 (Photo C39); substrate large cobble/boulder.

4365

1730 Upper reach of Ingram Creek at crossing with Bains Gap Rd ~~cross Ag~~ across from Range 25 - K-D Range. Photo C40. Rocky creek bottom.

END 7/29/98 Visits

INTERNATIONAL TECHNOLOGY CORPORATION

FIELD ACTIVITY DAILY LOG CONTINUATION SHEET

DAILY LOG			
DATE	7	30	98
NO.	0	~~0~~ 1	4
SHEET	1	OF	3

PROJECT NAME FTMC PROJECT NO.

FIELD ACTIVITY SUBJECT Field Reconn. #2 - Ecological Habitat

DESCRIPTION ON DAILY ACTIVITIES AND EVENTS

0845 Visit to Range Control for access permission to MP and Pelham Range.

0920 Revisit site 200 (7) - Ground Scar w/Trenches at Driving course. Look closer at Ingram Creek to NW of site. Noted 2 drainage channels along NW boundary of site discharing in a SE to NW direction. Take depositional soil samples at end of ditches (photo D1). Noted a ponded hole around several trees; could be water table level.

Could not find Ingram Crk on the NW side. Checked on the ~~west side~~ SW corner of the site, where we found a small, covered foot bridge crossing over a tributary to Ingram Creek (photos D2 & D3). Take deposit. soil sample several yards in front of foot bridge, and one sediment/SW sample in Creek downstream of bridge.

0945 Drove to corner of Rocky Hollow Rd & Bain's Gap Rd, where Ingram Crk flows under the road (photo D4).

1010 Stopped at site 9(7) (coords 19,38) adjacent to a sizable trib to Cave Creek. Silty-sand substrate at bridge. Maintained lawn & buildings surn'd by mixed pine decid. forest (photos D5 & D6). Minnows/shiners in crk.

1020 Stopped at site 87(7) [135(7) & 10(7)]. Confirmed depositional soil sample locations at south fenceline corner. Could not access Cave Creek from this direction. ~~When~~ Ag Went to 3rd Street to access from behind. Found Cave Creek & hiked ~50 yds upstream into brush (photo D7).

532-3-88

INTERNATIONAL TECHNOLOGY CORPORATION

FIELD ACTIVITY DAILY LOG CONTINUATION SHEET

DAILY LOG			
DATE	7	30	98
NO.	0	1	5
SHEET	2	OF	3

PROJECT NAME | PROJECT NO.

FIELD ACTIVITY SUBJECT

DESCRIPTION ON DAILY ACTIVITIES AND EVENTS

1050 Located Sites 104(7), 59(7), and 62(7). Open grass area surrd'd by pine. Water inaccessable on NW corner of site. (D8)

1115 stopped at Cane Creek (Coord 24,32) photo D9

1150 Lunch

1330 Site 124(7); open field surrounded by forest

To Pelham Range —

1355 Arrived at Pelham R., went to Range 2D/B61 in NE corner of P.R. Found first creek ditch dry.

Continued to NE boundary (N/S fenceline) & turned rt (south). Continued to trib to Cane Creek (D11). Stuck in mud. Returned North & turned left. Turned left again into Range Area 1D (photo D12) through muddy back road. Found main road.

1430 Continued out through P.R. parallel to Cane Creek, Crossed a tributary to Cane Crk (photo D13)

Continued a few hundred yards on main road and turned left onto dirt road to Cane Creek. (photo D14)

1440 Bridge out.

1455 Arrived at Willett Springs wetland. Photo taken previous reconn (#1). Turtle on Road (D15). Snapping turtle trying to cross road.

1505 Cane Creek (photo D16) in Range Area 4A.

INTERNATIONAL TECHNOLOGY CORPORATION

FIELD ACTIVITY DAILY LOG CONTINUATION SHEET

DAILY LOG			
DATE	7	30	98
NO.	0	1	6
SHEET	3	OF	3

PROJECT NAME | PROJECT NO.

FIELD ACTIVITY SUBJECT

DESCRIPTION ON DAILY ACTIVITIES AND EVENTS

1540 Stopped at small pond in Range Area 4B (photo D17) Few yards (~100 yds) to trib. to Cane Creek crossing northerly road.

1555 ~~Another~~ Noted kingfisher & duck. bridge crossing Cane Creek in Range Area 24B (D18). Took Rt to another Cane Creek crossing (D19) On Range Area 6A / 7A boundary. Bridge out ~~(Area A9~~

1615 Trib to Cane Creek (D20) and D21. Deer tracks. Area 7A.

1620 Small Creek to Off-Installation in Area 9C (D22). Deer sighting. Further on same road crossed ~~a dry~~ the same creek ditch. Flow is generally north (D23), Area 9C.

1640 Habitat within Area 10A, Northwest corner of P.A. (D24) mixed pine-deciduous forest with moderate understory.

1655 Found wetland in Range Area 10A, Heron flew away; rabbit crossed road. Cattails (D25), Went around to opposite side. Wetland is more of a pond in the middle (D26). Noted deer tracks & raccoon tracks.

1705 Further on same road crossed Cane Creek (D27).

1715 Drove around a large clearing dominated by shrubs. Crossed bridge 8701 over trib to Cane Creek (D28 in Range Area 24A). Habitat photo of clearing (D29)

1745 Habitat photos (D30) D31 of Range Area 1C & Graham Drop Zone from south side of Graham D.Z. Wide open grassy valley.