

**APPENDIX A**

**FISCAL YEAR FUNDING REQUIREMENTS AND COSTS**

**Table A-1**

**Total Environmental Program Summary  
Fort McClellan, Calhoun County, Alabama**

<b>Fund Requirements (\$000)</b>			
<b>Program</b>	<b>FY 2002</b>	<b>FY 2003</b>	<b>FY 2004</b>
BRAC	34,236	28,565	28,617
Real Estate Support	256	256	256
Program Support	40	40	40
<b>Total</b>	<b>\$34,532</b>	<b>\$28,821</b>	<b>\$28,813</b>

**Table A-2**

**Historical Environmental Program Expenditures Summary  
Fort McClellan, Calhoun County, Alabama**

<b>Fund Requirements (\$000)</b>				
<b>Program</b>	<b>FY 1998</b>	<b>FY 1999</b>	<b>FY 2000</b>	<b>FY 2001</b>
BRAC	12,132	36,711	18,526	14,989
Real Estate Support	256	256	256	256
Program Support	40	40	40	40
<b>Total</b>	<b>\$12,428</b>	<b>\$37,007</b>	<b>\$18,822</b>	<b>\$15,285</b>

BRAC = Base Realignment and Closure

**APPENDIX B**

**INSTALLATION ENVIRONMENTAL RESTORATION  
DOCUMENTS SUMMARY TABLE**

**Table B-1  
Installation Environmental Restoration  
Documents Summary Table  
Fort McClellan, Calhoun County, Alabama**

(Page 1 of 9)

Parcel	Prelim. Assessment Report	EBS	SI	Dec. Doc.	RI	RI Work Plan	EECA	LTM Report	UST Closure Report	FOST/ FOSL	Baseline Envir. Investigation Report	Lead Based Paint Risk Assessments	Asbestos Survey Report	Archive Search Report	Removal Action Report	Commodity Site Survey Report	Radiological Status/Survey Report	NRC Inspection Report	Radiological Remediation Report
1(4)	X	X	X	X						X									
2(4)		X	X	X															
3(4)	X	X	X	X															
4(4)	X	X	X	X															
5(3)	X	X	X	X															
6(4)	X	X	X	X															
7(3)		X	X	X						X									
8(7)	X	X																	
9(3)	X	X		X					X	X									
10(3)	X	X	X																
11(4)	X	X	X	X						X									
12(4)	X	X	X	X						X									
13(3)	X	X	X	X						X									
14(3)	X	X	X	X															
15(3)	X	X								X									
16(3)	X	X	X																
17(4)	X	X	X	X							X								
18(3)	X	X	X	X							X								
19(3)	X	X	X	X							X								
20(3)	X	X	X	X															
21(7)	X	X				X													
22(7)	X	X				X													
23(3)	X	X	X	X															
24(7)	X	X																	
25(7)	X	X																	
26(3)	X	X	X	X															
27(3)	X	X	X	X						X									
28(3)	X	X	X	X						X									
29(3)	X	X	X	X						X									
30(4)	X	X	X	X						X									
31(4)	X	X	X	X					X	X									
32(4)	X	X	X	X															
33(3)	X	X		X					X	X									
34(4)	X	X		X					X	X									
35(3)	X	X		X					X	X									
36(3)	X	X		X					X	X									
37(3)	X	X	X	X						X									
38(3)	X	X		X					X										
39(3)	X	X		X					X	X									
40(4)	X	X		X					X	X									
41(4)	X	X	X	X						X									
42(4)	X	X	X	X															
43(4)	X	X		X					X										
44(4)	X	X		X					X										
45(4)	X	X		X					X										
46(7)	X	X																	
47(3)	X	X	X	X															
48(3)	X	X	X	X						X									
49(3)	X	X		X					X	X									
50(3)	X	X		X					X	X									
51(3)	X	X		X					X	X									
52(3)	X	X	X	X						X									
53(7)		X																	

**Table B-1  
Installation Environmental Restoration  
Documents Summary Table  
Fort McClellan, Calhoun County, Alabama**

(Page 2 of 9)

Parcel	Prelim. Assessment Report	EBS	SI	Dec. Doc.	RI	RI Work Plan	EECA	LTM Report	UST Closure Report	FOST/ FOSL	Baseline Envir. Investigation Report	Lead Based Paint Risk Assessments	Asbestos Survey Report	Archive Search Report	Removal Action Report	Commodity Site Survey Report	Radiological Status/Survey Report	NRC Inspection Report	Radiological Remediation Report
54(3)	X	X		X					X	X									
55(3)	X	X		X					X	X									
56(3)	X	X		X					X	X									
57(3)	X	X		X					X	X									
58(3)	X	X		X					X	X									
59(3)	X	X								X	X								
60(3)	X	X	X	X						X	X								
61(6)	X	X																	
62(1)	X	X								X	X								
63(3)		X		X					X	X	X								
64(3)	X	X	X	X						X									
65(7)	X	X																	
66(7)	X	X				X													
67(3)	X	X	X	X															
68(3)	X	X	X	X						X									
69(3)	X	X	X	X															
70(7)	X	X																	
71(3)	X	X	X	X															
72(3)	X	X	X	X						X									
73(7)	X	X																	
74(3)	X	X	X	X						X									
75(3)	X	X	X	X						X									
76(1)		X								X									
77(3)	X	X	X	X						X									
78(6)	X	X					X	X											
79(6)	X	X	X				X	X											
80(5)		X	X		X		X	X											
81(5)	X	X					X												
82(7)		X					X												
83(3)	X	X	X	X						X									
84(7)	X	X																	
85(3)	X	X	X	X						X									
86(3)	X	X	X	X															
87(4)	X	X	X																
88(6)	X	X																	
89(3)	X	X	X	X															
90(3)	X	X	X	X															
91(3)	X	X	X	X															
92(1)	X	X								X									
93(7)		X																	
94(7)		X																	
95(3)		X	X	X						X									
96(3)		X	X	X															
97(3)		X	X	X															
98(1)		X																	
99(3)		X	X	X															
100(3)	X	X	X	X															
101(3)	X	X	X	X															
102(7)	X	X																	
103(3)		X																	
104(3)		X					X			X	X								
105(3)		X	X	X			X												
106(3)		X	X	X			X												

**Table B-1  
Installation Environmental Restoration  
Documents Summary Table  
Fort McClellan, Calhoun County, Alabama**

(Page 3 of 9)

Parcel	Prelim. Assessment Report	EBS	SI	Dec. Doc.	RI	RI Work Plan	EECA	LTM Report	UST Closure Report	FOST/ FOSL	Baseline Envir. Investigation Report	Lead Based Paint Risk Assessments	Asbestos Survey Report	Archive Search Report	Removal Action Report	Commodity Site Survey Report	Radiological Status/Survey Report	NRC Inspection Report	Radiological Remediation Report
107(3)		X	X	X															
108(7)		X												X					
109(7)		X																	
110(7)		X																	
111(3)	X	X	X	X															
115(1)		X																	
116(1)		X																	
117(7)		X																	
118(7)		X																	
119(7)		X																	
122(3)		X	X	X			X												
123(7)	X	X																	
124(3)		X	X	X			X												
125(3)		X	X	X						X									
126(7)		X					X												
127(7)		X																	
128(3)		X	X	X															
129(3)		X	X	X															
130(3)		X	X	X						X									
131(3)		X	X	X						X									
132(7)		X																	
133(7)		X																	
134(7)		X																	
135(3)		X	X																
136(3)		X	X	X						X									
137(3)	X	X	X	X						X									
138(3)		X	X	X						X									
139(3)		X	X	X						X									
140(7)		X																	
141(3)		X	X	X						X									
142(7)		X																	
143(3)		X	X	X															
144(3)		X	X	X						X									
145(3)		X	X	X						X									
146(7)		X																	
147(3)		X	X	X						X									
148(3)		X	X																
149(3)		X	X	X															
150(3)		X	X	X						X									
151(3)		X	X	X						X									
152(3)		X	X	X															
153(3)		X	X	X															
154(3)		X	X	X															
155(7)		X																	
156(3)		X	X	X															
157(3)		X	X	X															
158(3)		X	X	X															
159(3)		X	X	X															
160(7)		X																	
161(1)		X																	
162(3)	X	X	X	X						X									
163(3)		X	X	X															
164(3)		X	X	X						X									

**Table B-1  
Installation Environmental Restoration  
Documents Summary Table  
Fort McClellan, Calhoun County, Alabama**

(Page 4 of 9)

Parcel	Prelim. Assessment Report	EBS	SI	Dec. Doc.	RI	RI Work Plan	EECA	LTM Report	UST Closure Report	FOST/ FOSL	Baseline Envir. Investigation Report	Lead Based Paint Risk Assessments	Asbestos Survey Report	Archive Search Report	Removal Action Report	Commodity Site Survey Report	Radiological Status/Survey Report	NRC Inspection Report	Radiological Remediation Report
165(7)		X																	
166(3)	X	X	X	X															
167(3)	X	X		X					X	X									
168(3)	X	X	X																
169(7)		X																	
170(3)		X	X	X						X									
171(3)		X	X	X						X									
172(3)		X	X	X															
173(3)		X	X	X						X									
174(3)		X	X	X															
175(5)	X	X					X												
176(7)		X					X												
177(3)		X	X	X															
178(3)		X	X	X						X									
179(3)		X	X	X															
180(7)	X	X			X		X												
181(7)	X	X			X		X												
182(7)	X	X	X		X		X												
183(6)	X	X	X				X												
184(7)	X	X					X							X					
185(7)	X	X					X							X					
186(6)		X	X		X		X							X					
187(7)	X	X	X		X		X							X					
188(7)		X			X		X							X					
189(7)		X					X												
190(7)		X					X												
191(7)	X	X					X												
192(7)	X	X					X												
193(7)	X	X					X												
194(7)		X																	
195(3)		X	X	X															
196(3)		X	X	X						X									
197(3)		X	X	X															
198(3)		X	X	X						X									
199(3)		X	X	X			X												
200(3)		X	X	X						X									
201(7)		X																	
202(7)	X	X	X		X														
203(7)	X	X			X														
204(7)	X	X	X																
205(7)	X	X	X																
206(7)		X																	
207(7)		X																	
208(7)	X	X																	
209(7)		X																	
210(7)	X	X																	
211(7)		X																	
212(7)	X	X																	
213(7)		X																	
216(1)		X																	
217(1)		X																	
220(1)		X																	
221(1)		X																	

**Table B-1  
Installation Environmental Restoration  
Documents Summary Table  
Fort McClellan, Calhoun County, Alabama**

(Page 5 of 9)

Parcel	Prelim. Assessment Report	EBS	SI	Dec. Doc.	RI	RI Work Plan	EECA	LTM Report	UST Closure Report	FOST/ FOSL	Baseline Envir. Investigation Report	Lead Based Paint Risk Assessments	Asbestos Survey Report	Archive Search Report	Removal Action Report	Commodity Site Survey Report	Radiological Status/Survey Report	NRC Inspection Report	Radiological Remediation Report
222(1)		X																	
223(1)		X																	
224(1)		X																	
225(3)		X	X	X															
226(3)		X	X	X															
227(7)		X					X												
228(3)		X	X	X						X									
229(7)		X					X												
230(7)		X					X			X									
231(7)		X					X												
232(7)		X																	
233(7)		X					X												
234(7)		X																	
235(3)		X	X	X															
236(3)		X	X	X															
237(3)		X	X	X															
238(3)		X	X	X															
239(3)		X	X	X															
240(3)		X	X	X															
241(3)		X	X	X															
242(7)		X																	
500(3)			X	X															
501(3)			X	X						X									
502(3)				X					X										
503(3)			X	X			X												
504(3)			X	X															
505(3)				X					X										
506(3)				X					X	X									
507(7)																			
508(7)																			
509(7)							X							X					
510(7)							X							X					
511(7)							X							X					
512(7)							X							X					
513(7)							X							X					
514(7)							X							X					
515(7)							X							X					
516(7)							X							X					
517(7)							X							X					
518(7)																			
519(4)		X		X									X		X				
520(4)		X		X									X	X	X				
M2 Area			X	X			X			X					X				
1Q		X										X	X						
2Q	X	X								X		X	X						
3Q		X								X		X	X						
4Q		X								X		X	X						
5Q	X	X								X		X	X						
6Q	X	X								X		X	X						
7Q		X								X		X							
8Q		X								X		X	X						
9Q	X	X								X		X							
10Q	X	X								X		X	X						

**Table B-1  
Installation Environmental Restoration  
Documents Summary Table  
Fort McClellan, Calhoun County, Alabama**

(Page 6 of 9)

Parcel	Prelim. Assessment Report	EBS	SI	Dec. Doc.	RI	RI Work Plan	EECA	LTM Report	UST Closure Report	FOST/ FOSL	Baseline Envir. Investigation Report	Lead Based Paint Risk Assessments	Asbestos Survey Report	Archive Search Report	Removal Action Report	Commodity Site Survey Report	Radiological Status/Survey Report	NRC Inspection Report	Radiological Remediation Report
11Q		X								X									
12Q										X									
13Q		X																	
14Q		X								X			X			X		X	
15Q	X	X								X		X							
16Q		X											X		X				
17Q		X								X			X						
18Q		X																	
19Q		X								X			X						
20Q		X								X			X						
21Q		X								X									
22Q		X																	
23Q		X								X									
24Q		X																	
25Q		X											X						
27Q		X											X						
28Q	X	X								X		X	X						
29Q		X										X							
30Q		X								X			X						
31Q		X								X									
32Q		X											X						
33Q		X								X			X						
34Q		X											X						
35Q		X								X			X					X	
36Q		X																	
37Q		X											X						
38Q		X											X						
39Q		X								X			X						
40Q		X								X			X						
41Q	X	X								X		X	X						
42Q		X								X									
43Q		X								X			X						
57Q		X	X	X															
60Q		X																	
62Q		X											X			X		X	
63Q		X														X		X	
64Q		X								X						X		X	
65Q		X																X	
66Q		X														X	X		X
67Q		X														X			
68Q		X																X	
69Q		X																X	
70Q		X												X					
71Q		X												X					
72Q	X	X												X					
73Q	X	X												X					
74Q	X	X												X					
75Q		X												X					
76Q		X												X					
77Q		X												X					
78Q		X												X					
79Q		X												X					
80Q		X												X					

**Table B-1  
Installation Environmental Restoration  
Documents Summary Table  
Fort McClellan, Calhoun County, Alabama**

(Page 7 of 9)

Parcel	Prelim. Assessment Report	EBS	SI	Dec. Doc.	RI	RI Work Plan	EECA	LTM Report	UST Closure Report	FOST/ FOSL	Baseline Envir. Investigation Report	Lead Based Paint Risk Assessments	Asbestos Survey Report	Archive Search Report	Removal Action Report	Commodity Site Survey Report	Radiological Status/Survey Report	NRC Inspection Report	Radiological Remediation Report
81Q		X												X					
82Q		X												X					
83Q		X					X							X			X	X	
84Q		X					X							X					
85Q		X												X					
86Q		X					X							X					
87Q	X	X					X							X					
88Q	X	X					X							X					
89Q		X					X							X					
90Q		X	X	X			X							X					
91Q	X	X					X							X					
92Q		X												X					
93Q		X					X							X					
94Q		X												X					
95Q		X												X					
96Q		X												X					
97Q		X												X					
98Q		X												X					
99Q		X												X					
100Q		X					X							X					
101Q		X					X							X					
102Q		X					X							X					
103Q		X					X							X					
104Q		X												X					
105Q		X												X					
106Q		X					X							X					
107Q		X					X							X					
108Q		X					X							X					
109Q		X												X					
110Q		X					X							X					
111Q		X					X							X					
112Q		X					X							X					
113Q		X												X					
114Q		X					X							X					
115Q		X					X							X					
116Q		X					X							X					
117Q		X					X							X					
118Q		X					X							X					
119Q		X												X					
120Q		X												X					
121Q		X					X							X					
122Q		X					X							X					
123Q		X					X							X					
124Q		X												X					
125Q		X					X							X					
126Q	X	X	X							X	X			X					
127Q		X					X							X					
129Q		X					X							X					
130Q		X					X							X					
131Q		X												X					
132Q		X					X							X					
133Q		X					X							X					
134Q		X												X					

**Table B-1  
Installation Environmental Restoration  
Documents Summary Table  
Fort McClellan, Calhoun County, Alabama**

(Page 8 of 9)

Parcel	Prelim. Assessment Report	EBS	SI	Dec. Doc.	RI	RI Work Plan	EECA	LTM Report	UST Closure Report	FOST/ FOSL	Baseline Envir. Investigation Report	Lead Based Paint Risk Assessments	Asbestos Survey Report	Archive Search Report	Removal Action Report	Commodity Site Survey Report	Radiological Status/Survey Report	NRC Inspection Report	Radiological Remediation Report
135Q		X	X	X			X							X					
136Q		X												X					
137Q		X												X					
138Q		X												X					
139Q		X												X					
140Q		X												X					
141Q		X												X					
142Q		X												X					
143Q		X												X					
144Q		X												X					
145Q		X												X					
146Q		X												X					
147Q		X												X					
148Q		X												X					
149Q		X					X							X					
150Q		X					X							X					
151Q		X					X							X					
152Q		X												X					
153Q		X												X					
154Q		X												X					
155Q		X												X					
156Q		X												X					
157Q		X												X					
158Q		X												X					
159Q		X												X					
160Q		X												X					
161Q		X												X					
162Q		X												X					
163Q	X	X												X					
164		X												X					
165Q		X												X					
166Q		X												X					
167Q		X												X					
168Q		X												X					
169Q		X												X					
170Q		X												X					
171Q		X												X					
172Q		X												X					
173Q		X												X					
174Q		X												X					
175Q		X												X					
176Q		X												X					
177Q		X												X					
184Q		X												X					
185Q		X												X					
186Q		X												X					
187Q		X												X					
188Q		X												X					
189Q		X												X					
190Q		X												X					
191Q		X												X					
192Q		X												X					
193Q		X												X					

**Table B-1  
Installation Environmental Restoration  
Documents Summary Table  
Fort McClellan, Calhoun County, Alabama**

(Page 9 of 9)

Parcel	Prelim. Assessment Report	EBS	SI	Dec. Doc.	RI	RI Work Plan	EECA	LTM Report	UST Closure Report	FOST/ FOSL	Baseline Envir. Investigation Report	Lead Based Paint Risk Assessments	Asbestos Survey Report	Archive Search Report	Removal Action Report	Commodity Site Survey Report	Radiological Status/Survey Report	NRC Inspection Report	Radiological Remediation Report	
194Q		X												X						
195Q		X												X						
200Q		X					X							X						
201Q		X					X							X						
202Q		X																		
203Q		X															X			
204Q		X																		
205Q		X																		
206Q		X																		
207Q		X																		
208Q		X																		
209Q		X																		
210Q		X																		
211Q		X					X													
212Q		X																		
213Q		X												X						
214Q		X												X						
215Q		X					X							X						
216Q		X												X						
217Q		X		X									X	X	X					
218Q		X					X							X						
219Q		X					X							X						
220Q		X					X							X						
221Q		X					X							X						
222Q		X					X							X						
223Q		X					X							X						
224Q		X					X							X						
225Q		X												X						
226Q		X												X						
227Q		X												X						
228Q		X					X							X						
229Q		X					X							X						
230Q		X					X							X						
231Q		X					X							X						
232Q		X					X							X						
234Q		X								X		X								
235Q	X	X								X		X								
236Q		X	X	X																
237Q		X												X						
238Q		X												X						
239Q		X					X							X						
244Q		X								X										
245Q		X								X		X								
246Q		X								X										
247Q		X					X							X						

**APPENDIX C**  
**NO FURTHER ACTION SUMMARIES**

## **Appendix C**

### **No Further Action Summaries**

As of this writing, No Further Action Decision Documents have been signed for 128 Parcels. Twenty parcels are awaiting ADEM concurrence letters. The BCT determined that no further action was necessary for 6 parcels that are awaiting both ADEM and EPA concurrence letters. These Parcels are identified in Table C-1 below. Site Investigation Results indicated that no chemicals associated with the sites present an unacceptable risk to either human health or the environment as provided in Table 3-1 of this plan.

**Table C-1**

**No Further Action Parcels at  
Fort McClellan, Alabama**

(Page 1 of 7)

<b>CERFA Parcel Label</b>	<b>CERFA Parcel Description</b>	<b>No Further Action Decision Document Signed (Date)</b>
30(4)PS/PR	Bldg. 3298 Motor Pool. Waste oil UST	11/16/01
74(3)PS	Bldg. 3262/3263 Wash rack	11/16/01
29(3)PS/PR	Bldg. 3294/3299; Area 3200 Motor Pool.	11/16/01
20(3)PS/PR	Autocraft shop. Bldg. 1800. One waste oil UST.	11/13/01
47(3)PS	Autocraft Shop. Bldg. 1800. One 2,000-gal UST for No. 2 heating oil	11/13/01
152(3)HS/HR(P)	Former DPDO, also called the Former Salvage yard. A former Washrack is located in the extreme SE corner of the parcel.	11/13/01
153(3)HR(P)	Ground Scar south of Bldg. 3134.	11/13/01
156(3)HR(P)	Ground scar south of the ASP.	11/13/01
226(3)PS/PR(P)	Boiler Plant No. 2, Bldg. 2278.	11/13/01
241(3)PS(P)/PR(P)	Former Area 2100 Motor Pool. Located N of the Former DPDO.	11/13/01
100(3)HS/PS	Former Smoke Area R, Central Main Post	11/13/01
23(3)PS	Boiler Plant #2. Bldg. 2278. Two 25,000-gal heating oil USTs	11/1/01
97(3)PR	Former Sandel Flame Thrower Range, Main Post, north side of Howitzer Hill	10/12/01
101(3)PS	Boiler Plant # 4, Bldg. 1876. Two 50,000-gal USTs for No. 4 heating oil, One 500-gal gasoline UST for a back-up generator	10/12/01
158(3)HR(P)	Ground scar, located at the south end of the confidence course.	10/12/01
236(3)PS/PR(P)	Boiler Plant No. 4, Bldg. 1876	10/12/01
83(3)HS	Golf Course Storage and Mixing Facility, Bldg. S-2252. 50 gal of pesticides stored here	9/18/01
90(3)HR(P)	Chemical School Laboratory Sump, Bldg. 2281. Lab wastes were drained down sink.	9/18/01
141(3)HS/HR(P)	Former Pesticide Storage and mixing at Bldg. T-2249.	9/18/01
141(3)HS/HR(P)	Former Pesticide Storage and mixing at Bldg. T-2249.	9/18/01
178(3)HR(P)	Golf Course	9/18/01
225(3)HS/HR(P)	Solvent Storage Bldg. 2282. Located west of Bldg. 2281.	9/18/01
14(3)PS	Boiler Plant #3. Bldg. 1076. Two 15,000-gal USTs were removed in 2000.	8/16/01
26(3)PS/PR	Boiler Plant #1, Bldg. 3176. Two 18,000-gal USTs of heating oil, one 500-gal gasoline UST for a back-up generator	8/16/01
89(3)PS/PR(P)	Boiler Plant No. 1, Bldg. 3176,	8/16/01

**Table C-1****No Further Action Parcels at  
Fort McClellan, Alabama**

(Page 2 of 7)

<b>CERFA Parcel Label</b>	<b>CERFA Parcel Description</b>	<b>No Further Action Decision Document Signed (Date)</b>
96(3)HS(P)	Former incinerators. Bldgs. 4428 & 4430, former washrack located at site.	8/16/01
235(3)PS/PR(P)	Boiler Plant No. 3, Bldg. 1076	8/16/01
11(4)PS/PR	Bldg. 888 Motor Pool. Waste oil UST	7/16/01
12(4)PS/PR	Bldg. 894 Motor Pool, Two USTs, one Mogas, and one diesel tanks were removed in 1991.	7/16/01
13(3)PS	Gym & Pool, Bldg. 1012. 5000-gal heating oil tank removed	7/16/01
17(4)PS/PR	Bldg. 1696 Motor Pool, 2,000-gal waste oil UST	7/16/01
18(3)PS/PR	Bldg. 1697 Motor Pool, One 2,000-gal waste oil UST.	7/16/01
19(3)PS	Bldg. 1694 Former Gas Station, two 10,000-gal USTs, one Mogas, one diesel, were removed in 1991.	7/16/01
68(3)PS	Bldg. 866 Wash rack	7/16/01
71(3)PS	Bldg. 1643 wash rack	7/16/01
106(3)PR	Former Smoke Area S, Central Main Post	7/16/01
122(3)PS/PR(P)	Former Fog Oil Storage Area Main Post, west of skeet range.	7/16/01
124(3)PR	Smoke Range BVZ, Main Post	7/16/01
139(3)PS	Former gas station at Bldg. 1094, located at the former Area 1000 motor pool. Building removed.	7/16/01
150(3)PS/PR(P)	Former Motor Pool at Area 1000, at current Bldg. 1012.	7/16/01
163(3)PS/PR(P)	Area 1600 Motor Pool	7/16/01
164(3)PS/PR(P)	Former Motor Pool Area 800	7/16/01
174(3)HS	National Guard, Small Weapons Storage and Cleaning Compound, Bldg. 1378.	7/16/01
179(3)HR	Former Personnel Decontamination Station (PDS) at Bldg. 3185	7/16/01
195(3)HR(P)	Gas Mask Test Chambers (Bldgs. T-401 & T-402)	7/16/01
196(3)HR(P)	Former Gas Mask Test Chamber (Bldg. 439) .	7/16/01
198(3)HR(P)	Former CS Training Area	7/16/01
200(3)HS/HR(P)	Ground Scar with probable trenches at the former Driving Course, SE Main Post	7/16/01
237(3)HR(P)	Cleared Area with mound, Choccolocco Corridor	7/16/01
503(3)	UST within 1600 Motor Pool Area	7/16/01

**Table C-1****No Further Action Parcels at  
Fort McClellan, Alabama**

(Page 3 of 7)

<b>CERFA Parcel Label</b>	<b>CERFA Parcel Description</b>	<b>No Further Action Decision Document Signed (Date)</b>
504(3)	UST at Building 1693 within 1600 Motor Pool Area	7/16/01
16(3)PS	Bldg. 1394 Motor Pool, Former gas station. Two 5,000-gal USTs, one Mogas and one diesel, were removed in 1991.	6/13/01
143(3)PS/PR(P)	Motor Pool at Area 1300.	6/13/01
148(3)PS/PR(P)	Former Motor Pool at Area 1300.	6/13/01
168(3)PS	National Guard, Bldg. 1224, wash rack.	6/13/01
9(3)PS	Recreation Bldg. 503. One heating oil UST	5/17/01
15(3)PS/PR	WAC Museum, Bldg. 1077. Leaking 1,000-gal heating oil UST	5/17/01
27(3)PS	Bldg. 3196/3148 Motor Pool. Two, 10,000-gal diesel USTs at the Former Motor Pool Area 3100, 23 rd Street	5/17/01
28(3)PS/PR	Bldg. 3196/3148 Motor Pool. One 2,000-gallon waste oil UST at the Former Motor Pool Area 3100, 23 rd Street	5/17/01
31(4)PS	Ammunition supply point at Bldg. 4407. One 1,000-gal UST for heating oil was closed in 1991.	5/17/01
33(3)PS	Bldg. S-55. Building Demolished. One 4,000-gal UST used for heating oil was closed in 1991.	5/17/01
34(4)PS	Fitness Center, Bldg. 128. One 4,000-gal UST for No. 2 heating oil.	5/17/01
35(3)PS	Field House, Bldg.130. One 2,500-gal UST for No. 2 heating oil.	5/17/01
36(3)PS	Administration Bldg. 141. One 2,500-gal UST for No. 2 heating oil.	5/17/01
38(3)PS	Bivouac Area B-44. One 1,000-gal UST for No. 2 heating oil. Position approximate. Choccolocco Corridor.	5/17/01
39(3)PS	Clothing, Bldg. 273. One 1,000-gal UST for No. 2 heating oil	5/17/01
43(4)PS	Building Demolished. Bldg. 796. One 1,000-gal UST for No. 2 heating oil	5/17/01
44(4)PS	Building Demolished. Bldg. 1201. One 1,000-gal UST for No. 2 heating oil.	5/17/01
45(4)PS	Building Demolished. Bldg. 1202. One 1,000-gal UST for No. 2 heating oil.	5/17/01
49(3)PS	Dental Clinic. Bldg. 1929. One 1,500-gal UST for No. 2 heating oil	5/17/01

**Table C-1**

**No Further Action Parcels at  
Fort McClellan, Alabama**

(Page 4 of 7)

<b>CERFA Parcel Label</b>	<b>CERFA Parcel Description</b>	<b>No Further Action Decision Document Signed (Date)</b>
50(3)PS	PX. Bldg. 1965. One 3,000-gal UST for No. 2 heating oil	5/17/01
51(3)PS	Post Office. Bldg. 1966. One 1,000-gal UST for No. 2 heating oil	5/17/01
54(3)PS	Barracks. Bldg 3131. One 20,000-gal UST for No. 2 heating oil	5/17/01
55(3)PS	Headquarters. Bldg. 3161. One 1,000-gal UST for No. 2 heating oil	5/17/01
56(3)PS	Community Club. Bldg. 3212. One 2,500-gal UST for No. 2 heating oil	5/17/01
57(3)PS	Recreation Center. Bldg. 3213. One 4,000-gal UST for No. 2 heating oil	5/17/01
58(3)PS	Chapel. Bldg. 3293. One 4,000-gal UST for No. 2 heating oil	5/17/01
60(3)PS/PR(P)	Bulk Storage Area. Bldg. 296. Six 25,000-gal and one 10,000-gal ASTs were used to store No. 4 heating oil	5/17/01
63(3)PS	Bldg. 162, One 2,500 gal UST for #2 heating oil	5/17/01
72(3)PS	Bldg 3146/7 Wash rack	5/17/01
85(3)HS/HR	DRMO, Bldg. T-341-346. Former RCRA Interim Status Storage Facility	5/17/01
130(3)PS	Quartermasters Gasoline Storage Area, near ASP, Main Post	5/17/01
131(3)PS	Former Fuel Yard (location approximate, extent unknown)	5/17/01
136(3)PS	Former gas station at Bldg. 694, located at the Area 6 motor pool. Building removed.	5/17/01
137(3)PS	Former gas station at Bldg. 2094, located at the former Area 2000 motor pool, now the go-cart track. Building removed.	5/17/01
144(3)PS/PR(P)	Former motor pool at Area 2000 at current go-cart track	5/17/01
147(3)PS/PR(P)	Motor Pool at Area 3100, just south of 23rd road.	5/17/01
149(3)PS/PR(P)	Former Motor Pool at Area 600, current Wildlife Management Office	5/17/01
167(3)PS	WAC Museum, Bldg. 1077. One 1,000-gal UST for No. 2 heating oil.	5/17/01
172(3)HS/HR(P)	Former Printing Plant, Bldg. 1060.	5/17/01
228(3)HR(P)	Trenches west of Remount Creek.	5/17/01
239(3)HR(P)	Trench near Range 20 firing line.	5/17/01
240(3)HR(P)	Trench near Range 20 firing line.	5/17/01
502(3)	UST at Building 1338	5/17/01

**Table C-1**

**No Further Action Parcels at  
Fort McClellan, Alabama**

(Page 5 of 7)

<b>CERFA Parcel Label</b>	<b>CERFA Parcel Description</b>	<b>No Further Action Decision Document Signed (Date)</b>
505(3)	UST at Building 3179	5/17/01
506(4)	UST at Building 3691	5/17/01
1(3)PS/PR	Bldg. 202/215 (DEH), Waste oil UST	3/21/01
48(3)PS	Bowling Alley. Bldg. 1928. One 1,000-gal UST for No. 2 heating oil	3/21/01
52(3)PS	Motor Pool. Bldg. 1997. One 2,500-gal UST for No. 2 heating oil	3/21/01
105(3)PR	Former Smoke Area R, Central Main Post	3/21/01
107(3)PR	Former Choccolocco Corridor Smoke Area	3/21/01
125(3)HR(P)	Old Incinerator, Bldg. 5710, northern main post. Near landfill #2.	3/21/01
145(3)PS/PR(P)	Motor pool at Areas 1900 and 1800, east of current post office	3/21/01
159(3)PR	Smoke Area at south slope of Morgan Mt.; Choccolocco Corridor	3/21/01
162(3)HS/HR(P)	Printing Plant Bldg. 3138. At one time, stored and used solvents in process.	3/21/01
173(3)HS/HR(P)	Former Printing Plant, Bldg. 2051.	3/21/01
197(3)HS	Ammunition Supply Point	3/21/01
199(3)HR(P)	Bldg. 4416 (Igloo No. 14) at the Ammunition Supply Point	3/21/01
59(3)PS	CDTF. Bldg. 4482. One 5,000-gal UST for No. 2 heating oil	2/21/01
62(1)HS	CDTF, Bldg. 4482. Two 8,000-gal ASTs. One for sulfuric acid (inactive), one for caustic soda solution. One 20,000-gal wastewater AST. One 40,000 gal Diesel AST	2/21/01
64(3)HS/PS/HR(P)/PR(P)	Directorate of Engineering and Housing compound.	2/21/01
104(3)HR(P)	CDTF Incinerator	2/21/01
95(3)HS/HR(P)	Former Hospital	12/13/00
177(3)PS/PR	AST Located at Range 16	12/4/00
177(3)PS/PR	AST Located at Range 16	12/4/00
37(3)PS	Administration, Bldg.143. One 4,000-gal UST for No. 2 heating oil	12/4/00
138(3)HS/HR(P)	Former Printing Plant Bldg. 143 (basement)	12/4/00
171(3)HS/HR(P)	Former Printing Plant, Bldg. 144 (1st Floor).	12/4/00
501(3)	Buildings south of Reilly Airfield	11/30/00
7(3)PS	Consolidated Maintenance, Bldg. 350. One diesel tank, one waste oil UST	11/29/00

**Table C-1**

**No Further Action Parcels at  
Fort McClellan, Alabama**

(Page 6 of 7)

<b>CERFA Parcel Label</b>	<b>CERFA Parcel Description</b>	<b>No Further Action Decision Document Signed (Date)</b>
40(4)PS	Noble Army Hospital, Bldg. 292. One 8,000-gal UST for No. 2 heating oil	11/29/00
77(3)PR/HR(P)	Former Fire Training Pit, located where Bldg. 350 is now.	11/29/00
170(3)PS	Consolidated Maintenance Facility, Bldg. 351, Wash Rack.	11/29/00
519(4)	Building 141, Former Pistol Ranges in attic of building	11/2/00
520(4)	Building 143, Former Pistol Ranges in attic of building	11/2/00
76(1)HS/PS	Consolidated Maintenance Facility, Bldg. 350 & 351. Includes paint booth, weapons maintenance, vehicle repair, radiator repair, battery maintenance	12/9/96
92(1)HS	U. S. Army Noble Hospital, Bldg. 292 and 293 Ag recovery units, incinerator	12/9/96
98(1)HS	Current Hazardous Storage Facility, Bldg. 348	12/9/96
<b>Need ADEM Concurrence Letter</b>		
10(3)PS(P)	Waste Chemical Storage Area (former Motor Pool area), Bldg. 598	Need ADEM Concurrence Letter
32(4)PS	Former Tar Plant/Temporary Transformer Storage Bldg. 4437. One 2,500-gal UST for heating oil was closed in 1991.	Need ADEM Concurrence Letter
99(3)PS/PR	Former Tar Plant/ Temporary transformer storage facility, Bldg. S-4437	Need ADEM Concurrence Letter
135(3)PS	Former gas station at Bldg. 594, located at the Area 5 Motor Pool. Building was removed.	Need ADEM Concurrence Letter
500(3)	UST at Building 3691	Need ADEM Concurrence Letter
2(4)PS/PR	GSA Motor Pool. Bldg. 238. Waste oil UST	Need ADEM Concurrence Letter
3(4)	Telephone Exchange. Bldg. 251. Diesel UST	Need ADEM Concurrence Letter
4(4)PS/PR	POL point. Bldg. 265. Three of eight USTs were leaking.	Need ADEM Concurrence Letter
67(3)HS/HR(P)	Former Battery Maintenance and Storage Area, Bldg. 234. Batteries were drained here until 1981 to a floor drain.	Need ADEM Concurrence Letter
69(3)PS	Bldg. 253 Wash rack	Need ADEM Concurrence Letter
86(3)HS/HR(P)/PR(P)	Golf Course Storage and Mixing Facility, Bldg. S-2252	Need ADEM Concurrence Letter

**Table C-1**

**No Further Action Parcels at  
Fort McClellan, Alabama**

(Page 7 of 7)

<b>CERFA Parcel Label</b>	<b>CERFA Parcel Description</b>	<b>No Further Action Decision Document Signed (Date)</b>
87(4)HS/PS/HR/PR(P)	Waste Chemical Storage Area Building 598	Need ADEM Concurrence Letter
91(3)HS/HR(P)	Former Dry Cleaning Area, Bldg. T-233, Bldg removed.	Need ADEM Concurrence Letter
111(3)HR(P)	Former Multi Craft Shop, Bldg. 245. Building demolished. Photographic wastes.	Need ADEM Concurrence Letter
128(3)HR(P)/PR(P)	Washrack, no longer used. Cane Creek @ Nielsen St.	Need ADEM Concurrence Letter
129(3)HR(P)/PR(P)	Washrack, near Bldg. T-222., no longer used.	Need ADEM Concurrence Letter
151(3)HS(P)/PS(P)/HR(P)/PR(P)	GSA Area and surrounding warehouses	Need ADEM Concurrence Letter
154(3)HR(P)	Ground scar/ trenches are present, off of Littlebrandt Rd.	Need ADEM Concurrence Letter
157(3)HR(P)	Ground scar, south of autocraft shop.	Need ADEM Concurrence Letter
238(3)PS	Former Gas Station Bldg. 3794, Bldg. Removed. Located near current Bldg. 234.	Need ADEM Concurrence Letter
<b>Parcels Determined to Need No Further Action Need EPA/ADEM Concurrence Letters</b>		
5(3)PS	Bldg. 326 (former ORMA) One Mogas UST and one diesel UST were removed in 1991.	Need EPA/ADEM Concurrence Letters
6(3)PS/PR	Recycling Center, Bldg. 338. (Former OMRA) one waste oil UST	Need EPA/ADEM Concurrence Letters
41(4)PS	General Purpose, Building 303. One 3,000-gal UST for No. 2 heating oil	Need EPA/ADEM Concurrence Letters
42(4)PS	Recycling Center, Building 338. OMRA. One 2,500-gal UST for No. 2 heating oil	Need EPA/ADEM Concurrence Letters
75(3)HS/HR(P)/PS/PR(P)	Former Ordnance Motor Repair Area (OMRA) and adjacent warehouses and photo lab. Includes Washrack, battery storage and maintenance, ordnance motor repair, oil and paint storage buildings	Need EPA/ADEM Concurrence Letters
166(3)HS/HR(P)	Training Aids Building Building 267	Need EPA/ADEM Concurrence Letters