SECTION 7

PHOTOGRAPHS

Photographs of AREEs taken during WESTON's visit are provided on the following pages.



263-1696

1. LOOKING WEST FROM CHOCCOLOCCO MOUNTAINS TOWARD THE MAIN POST



263-1696a

2. LOOKING EAST FROM CHOCCOLOCCO MOUNTAINS TOWARD THE CHOCCOLOCCO CORRIDOR



3. WASTE OIL STORAGE TANK LOCKED FILL PIPE BEHIND BUILDING 202

263-1696C

4. SERVICEABLE BULK PETROLEUM STORAGE AREA BEHIND BUILDING 202



5. 55-GALLON DRUM OF ANTI-FREEZE IN CAGED AREA BEHIND BUILDING 202

6. BLACK EMPTY 55-GALLON DRUMS NORTHWEST OF BUILDING 211

7. OTHER EMPTY 55-GALLON DRUMS NORTHWEST OF BUILDING 211

263-1696E

8. FULL 55-GALLON DRUMS NORTHWEST OF BUILDING 211



9. PAINT SPRAY BOOTH AT BUILDING 1800

263-1696F

10. OIL STAINS AROUND WASTE OIL TANK FILL PIPE AT BUILDING 1800

11. OIL STAINS IN PARTS LAYDOWN AREA BEHIND BUILDING 1800

263-1696G

12. OIL STAINS IN SEDIMENT OF INTERMITTENT STREAM BEHIND PARTS LAYDOWN AREA



13. WASTE OIL DRUMS NEAR PARTS LAYDOWN AREA



14. TWO 55-GALLON DRUMS ON RACK NEAR BUILDING 339

15. OIL STAINED AREA AROUND OLD WASTE OIL TANK AND 55-GALLON WASTE OIL DRUMS



16. MOTOR POOL AREA AROUND BUILDING 1693



17. MOTOR POOL AREA AROUND BUILDINGS 894 AND 895

18. FUEL PUMPS AT BUILDING 265



19. LOADING PLATFORM AT BUILDING 264

20. VEHICLE WASH RACK AT UTES #1

21. OIL/WATER SEPARATOR AT UTES #1

22. OLD SKEET RANGE

23. RANGE 19 - QUALIFICATION PISTOL RANGE

24. SPENT ROUNDS FOUND AT RANGE 19

25. RANGE 57 - PELHAM, TARGETS FOR M16s

26. RANGE 22 - MAIN POST, FIRING RANGE

27. BOUNDARY OF IMPACT AREA - PELHAM RANGE

28. MAIN POST - SHOWING RESTRICTED ACCESS TO AREA T-24A

29. PELHAM RANGE - SHOWING RESTRICTED ACCESS TO RANGE I

30. PELHAM RANGE - SHOWING RESTRICTED ACCESS TO RANGE J
(NOTE RUSTED DRUMS IN TALL GRASS)



31. RANGE J - RUSTED DRUM

32. PELHAM RANGE - SHOWING VEGETATION AT RANGE K

33. RANGE K - PONDED AREA

34. PELHAM RANGE - SHOWING LIMA POND AT RANGE L

35. POL POINT - BUILDING 263



36. UNDERGROUND STORAGE TANK LINES
(NOTE THAT BUILDING 598 NO LONGER EXISTS)

37. STATE-OF-THE-ART NEWLY INSTALLED UST



38. ABOVE GROUND PROPANE STORAGE AT BUILDING 3217

39. PELHAM RANGE - UTES #1 SITE FUEL STORAGE

40. ABOVE GROUND FUEL STORAGE AT BUILDING 296



267-1696V

41. OLD LANDFILL NO. 1



42. DRAINAGE DIVERSION CHANNEL - OLD LANDFILL NO. 1



43. OLD LANDFILL NO. 2 - WOODED AREA LOOKING NORTHWEST SHOWING TOE OF LANDFILL

44. OLD LANDFILL NO. 3 - WOODED AREA WITH TRENCHES IDENTIFIED

45. OLD LANDFILL NO. 3 - MONITORING WELL (W-2)



267-1696Y1

46. ACTIVE SANITARY LANDFILL NO. 4



267-1696Y

47. BORROW PIT NORTHEAST OF MAIN POST (STUMP DUMP)

263-1696Z

48. BORROW PIT NEAR ACTIVE SANITARY LANDFILL NO. 4

49. BUILDING 292 WITH HOSPITAL INCINERATOR



263-1697A

50. OLD INCINERATOR (NOTE INFECTIOUS WASTE CONTAINERS IN FOREGROUND)

51. BAGS OF INCINERATOR ASH

52. PESTICIDE MIXING AND STORAGE FACILITY-BUILDING 211



53. MIXING TANK AT PESTICIDE MIXING AND STORAGE FACILITY

54. FORESTRY COMPOUND (BUILDING T08519 - PELHAM RANGE)



55. PCB STORAGE FACILITY



263-1697D

56. INSIDE PCB STORAGE FACILITY - TRANSFORMERS AND OTHER DRUMS

57. TRANSFORMERS IN TEMPORARY TRANSFORMER STORAGE/STAGING AREA

58. EMPTY DRUM STORAGE AREA AT DRMO STORAGE FACILITY



59. BRASS RECYCLING BINS AT DRMO STORAGE FACILITY



60. LOCATION OF CLOSED RCRA INTERIM STATUS STORAGE AREA

61. STEP VAN IN CONTRACTOR LAYDOWN AREA

62. EMPTY FOG OIL DRUMS IN CONTRACTOR LAYDOWN AREA

63. OLD UNDERGROUND STORAGE TANKS IN CONTRACTOR LAYDOWN AREA

64. TELEPHONE POLE STORAGE AREA IN CONTRACTOR LAYDOWN AREA



65. FORMER WASTE CHEMICAL STORAGE AREA - BUILDING 598



66. WETLANDS AREA SOUTHWEST OF FORMER BUILDING 598



67. GREASE PIT IN FORMER BUILDING 598

263-1697J

68. UNDERGROUND STORAGE TANKS EAST OF FORMER BUILDING 598

69. RANGE 24A FOG OIL DRUM STORAGE AREA



263-1697K

70. STAINS AT RANGE 24A FOG OIL DRUM STORAGE AREA

71. RANGE 4A FOG OIL DRUM STORAGE AREA

72. HOT CELL FACILITY - BUILDING 3192



73. SEPTIC TANK ON NORTH SIDE OF BUILDING 267

267-1697M

74. USED HYPO CONTAINERS IN BACK OF BUILDING 267

75. SILVER RECOVERY UNIT IN U.S. ARMY HOSPITAL - BUILDING 292



76. HAZARDOUS MATERIAL STORAGE AREA IN U.S. ARMY HOSPITAL - BUILDING 292



77. BUILDING 273 (NOTE SUSPECTED UST, ASBESTOS AND LEAD PAINT)



78. INSIDE BUILDING 273 (NOTE SUSPECTED ASBESTOS)



79. OUTSIDE BUILDING 273 (NOTE SUSPECTED ASBESTOS AND LEAD PAINT)

80. TYPICAL TRANSFORMERS IN SERVICE