

APPENDIX C

**Photo Documentation Log
Original Photographs of the Site
And Pertinent Site Features**



Figure #1
Fenced area at Range "I".



Figure #2
Concrete marker inside fence at Range "I".
"REF Base I, August 1973"



Figure #3
One of five posts located south of Range “I” fenced area.



Figure #4
Photo of another post located in same area.



Figure #5
Metal Post found in Radiological Area on Main Post.
(For Comparison)



Figure #6
Corner post for the old fence at the Pelham Range Burial Area.



Figure #7
Knocked down corner post for the old fence at the Pelham Range Burial Area.